

REPAIR ESTIMATE*

VEHICLE NO : SHD 4427K

DATE 11/6/2018 11:12

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille			\$ 282.10
	Radiator Grille U Moulding			\$ 108.90
	Front Bumper Cover			\$ 538.80
	Front Bumper Lip			\$ 59.90
	Front Bumper Bracket Top (LH/RH) ?		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) ?		\$ 20.10	\$ 40.20
	Headlamp (LH)			\$ 797.90
	Front Fender (LH)			\$ 593.00
	Front Fender Shield (LH/RH) LH ✓ RH?		\$ 86.00	\$ 172.00
	Front Wheel Hub Cap, LH			\$ 145.00
	SUB TOTAL			\$ 2,782.60
	LESS 20%			\$ 556.52
	DISCOUNTED TOTAL			\$ 2,226.08
	Front Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00
				\$ 200.00
	Labour Charge			
	Panel Beating			\$ 600.00 400
	Spray Painting Charge			\$ 500.00 400
	Wiring Charge			\$ 50.00 30
	Tuff Kote			\$ 50.00 20
	FRT Wheel Alignment			\$ 120.00 60
	TOWING			\$ 60.00 -
	TOTAL LABOUR			\$ 1,320.00
	ESTIMATE TOTAL			\$ 3,746.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.