

WENG KEE MOTOR

DATE: 11-06-2018

REPAIR ESTIMATE

VEHICLE: SLW 5818 L

MODEL: Subaru Impreza

S/n	Description of part	Qty	Estimate
1	Tailgate R	1	876.00
2	Tailgate emblem "impreza" ✓ NEC	1	32.90
3	Tailgate emblem "eyesight" ✓ NEC	1	85.80
4	Tailgate emblem "subaru" ✓ NEC	1	34.40
5	Tailgate emblem "symmetrical awd" ✓ NEC	1	74.30
6	Tailgate weatherstrip ✓ Deform	1	116.00
7	Tailgate outer garnish assembly X	1	258.00
8	Tailgate outer garnish assembly clip - set X	1	40.00
9	Tailgate logo X	1	68.40
10	Tailgate lock mechanism ? ✓ CUT	1	187.80
11	Rear windscreen moulding LH/RH ✓ NEC	2	85.00
12	Rear windscreen moulding top ✓ NEC	1	35.00
13	Rear windscreen moulding bottom ✓ NEC	1	32.00
14	Tail lamp LH/RH ? ✓ CRK	2	797.60
15	Tail lamp lower bracket LH/RH ? ✓ CRK	2	71.60
16	Tail gate lamp LH/RH ? ✓ CRK	2	577.40
17	Rear license plate lamp LH/RH X NN	2	56.80
18	Rear bumper ✓ CRK	1	493.60
19	Rear bumper support bracket LH/RH ? ✓ OT	2	56.40
20	Rear bumper clip - set ✓ NEC	1	30.00
21	Rear bumper side retainer RH/LH ? ✓ CRK	2	22.80
22	Rear bumper tow cover ✓ CUT	1	28.00
23	Blindspot sensor LH/RH ? ✓ SCR	2	2,160.00 X SVC / NN
24	Blindspot sensor bracket LH/RH ? ✓ CUT	2	34.80 X NN
25	Rear bumper lower garnish ✓ OT	1	260.00
26	Rear bumper reflector LH/RH ? ✓ SCR	2	24.20
27	Rear bumper reinforcement ? ✓ OT	1	278.70
28	Rear end panel top garnish ✓ CUT	1	88.00
29	Rear end panel ? R	1	297.30
Sub-total 1			7,202.80
Less 20%			5,762.24
30	Rear bumper extension grommet screw LH/RH ✓ NEC	2	8.00
31	Rear bumper extension fastener ✓ NEC	2	7.00
32	Rear bumper fastener ✓ NEC	2	8.00
33	Rear reverse sensor ? ✓ OMG	1	350.00 175
34	Windscreen sealant ✓ NEC	1	40.00 X NN
35	Windscreen primer ✓ NEC	1	20.00 X NN
36	Windscreen support sponge ✓ NEC	1	20.00 X NN

WENG KEE MOTOR

37	number plate with holder X NN	1	45.00
38	Tail lamp pad LH/RH $\frac{2}{3}$ ✓ NEC	2	30.00
39	Tail gate lamp pad LH/RH $\frac{2}{3}$ ✓ NEC	2	30.00
40	end panel sealant $\frac{2}{3}$ X NN	1	30.00
Sub-total 2			588.00
Parts total			6,350.24

Labour

41	To cut and remove rear end panel. To remove and refit above parts.	800.00	600
42	To putty, re-spray painting and polish affected areas.	800.00	600
43	To remove and refit tailgate upholstery to facilitate repair.	80.00	50
44	To remove and refit rear windscreen	120.00	60 X NN
45	To remove and repair rear exhaust silencer	150.00	X NN
46	To check and rectify wiring system.	80.00	40
47	To remove and install reverse sensors	60.00	30
48	To rust proof affected areas.	60.00	30 X NN
Labour total		2,150.00	
Parts & Labour total		8,500.24	

4 days

Sathya Sai

12/6/2012

sebastianyang@lkkauto.com

98072012

3 days + 2 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary terms must be ascertained and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature
Date:

- Lump Sum Repair
- Question mark item photo
- Photo after paint.

5606.3
- 20 %
4485.04
+ 513.00
+ 1410.00
6408.04

L/S: \$ 6400 @ 5 days
confirmed