



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SGG5161R
Date of Accident : 04 June 2018

Mr Lim Hai Seng

Date : 07 June 2018

Estimate To Repair SH2388B - Toyota Prius Hybrid 1.8L CVT
Chassis No : ZVW301991487

LUK - Marcus
08/06/18 @ 1420h

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	front bumper <i>Deep cut 105-9-10</i>	\$ 1,569.00
02	1 pc	left front bumper side retainer <i>11</i>	\$ 76.90
03	6 ps	front bumper clips @ \$4.30 <i>uc</i>	\$ 25.80
		Less <i>25%</i>	\$ 1,671.70
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 50.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 350.00
03		Putty and spray painting of the affected portion.	\$ 650.00
			\$ 1,050.00
		Total	\$
<i>Not Delivered</i>			
<i>1/5 #1100/2</i>			
<i>2 dy.</i>			
<i>Take place after repair</i>			
<i>8/6/18</i>			

20
200
380
600

21084.8
25%
513.67
600
1413.67
1130.84

Auto Consultants hence notify
1 - Repairer of the following:
• Resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date: