

## Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Attn: Catherine / Adrian

62564315

### Telefax

|            |   |                    |
|------------|---|--------------------|
| Estimate   | : | Accident Repairs   |
| Workshop   | : | Ubi Road 1         |
| Contact No | : | 6366 2323          |
| Fax No     | : | 6841 1183          |
| Reference  | : | PA/TP/0684/2018/PH |
| Date       | : | 12-Jun-18          |

Vehicle not IN workshop. Kindly arrange for survey.

### AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

|                   |   |                                        |
|-------------------|---|----------------------------------------|
| Owner's Name      | : | Mr Zhou Xiao Ming                      |
| Address           | : | 248 Miltonia Close<br>Singapore 768309 |
| Telephone         | : | HP +65 96991553                        |
| Type of Claim     | : | Third Party Claims                     |
| Policy No.        | : |                                        |
| Vehicle No        | : | <b>SKD 499 T</b>                       |
| Model Code        | : | A6 2.0 TFSI Qu                         |
| Model / Year      | : | Oct-11                                 |
| Engine No         | : | CDN 216379                             |
| Chassis No        | : | WAUZZZZ4G3CN035600                     |
| Mileage           | : |                                        |
| Date In           | : |                                        |
| Liability         | : | -                                      |
| Excess Cost       | : | -                                      |
| Estimated By      | : | Johnny Boo / Allan Wu                  |
| Accident Date     | : | 8-Jun-18                               |
| Place of Accident | : | CTE towards the City                   |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKD 499 T.

| S/n                         | Nature of Jobs                                                                                                                        | Estimated Charges           | Surveyor's Recommendation |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|---------------------------|
| 1                           | To remove and transfer rear parking aid. Check function and renew according to damage.                                                | S/N \$ 280.00               | ✓                         |
| 2                           | To remove and transfer rearlid's convenience lock system and wire harness for tail lights.                                            | S/N \$ 280.00               | ✓                         |
| 3                           | To dismantle and renew rear bumper and rear lid. Align to position. Re-organise rear crash management components. Reinstall all parts | \$ <del>2,100.00</del> 1200 |                           |
| 4                           | To respray rear bumper and rear lid                                                                                                   | \$ <del>1,700.00</del> 1200 |                           |
| 5                           | To carry out diagnostic check                                                                                                         | S/N \$ 192.00               | ✓                         |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                       | <b>: \$ 4,552.00</b>        |                           |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No SKD 499 T.

| S/N                            | Parts Description                      | Damaged Parts & Prices |        |
|--------------------------------|----------------------------------------|------------------------|--------|
|                                |                                        | S/Nett                 | Remark |
| 1                              | REAR BUMPER <i>del d</i>               | \$ 2,205.00            | ✓      |
| 2                              | FIXING PARTS FOR BUMPER <i>new</i>     | \$ 236.00              | ✗      |
| 3                              | SPOILER <i>ut</i>                      | \$ 301.00              | ✓      |
| 4                              | SECURING STRIP                         | \$ 148.00              | ✗      |
| 5                              | GUIDE SECTION - LH/RH LOWER            | 2 \$ 92.00             | ✗      |
| 6                              | GUIDE SECTION - LH                     | \$ 28.00               | ✗      |
| 7                              | GUIDE SECTION - CENTRE                 | \$ 91.00               | ✗      |
| 8                              | GUIDE SECTION - RH                     | \$ 28.00               | ✗      |
| 9                              | BUMPER CARRIER                         | \$ 851.00              | ✗      |
| 10                             | SEAL - LH/RH <i>new</i>                | 2 \$ 22.00             | ✗      |
| 11                             | SENSOR                                 | 2 \$ 421.00            | ✗      |
| 12                             | REAR LID <i>del d</i>                  | \$ 2,485.00            | ✓      |
| 13                             | ATTACHMENT PARTS FOR REAR LID <i>m</i> | \$ 70.00               | ✓      |
| 14                             | AUDI EMBLEM <i>new</i>                 | \$ 108.00              | ✓      |
| 15                             | A6' EMBLEM                             | \$ 83.00               | ✓      |
| 16                             | 2.0 T' EMBLEM                          | \$ 83.00               | ✓      |
| 17                             | PACKING ADHESIVE <i>new</i>            | \$ 15.00               | ✓      |
| 18                             | LED TAIL LIGHT - LH                    | \$ 1,094.00            | ✗      |
| 19                             | LED TAIL LIGHT - RH                    | \$ 1,094.00            | ✗      |
| 20                             | LED TAIL LIGHT- LH INNER               | \$ 1,094.00            | ✗      |
| <b>SUB SPARE PARTS CHARGES</b> |                                        | <b>\$ 10,549.00</b>    |        |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No SKD 499 T.

| S/N                              | Parts Description                         | <u>Damaged Parts &amp; Prices</u> |        |
|----------------------------------|-------------------------------------------|-----------------------------------|--------|
|                                  |                                           | S/Nett                            | Remark |
| 21                               | LED TAIL LIGHT - RH INNER <i>3 pc</i>     | \$ 1,094.00                       | X      |
| 22                               | LED LICENCE PLATE LIGHT                   | 2 \$ 100.00                       | X      |
| 23                               | PUSH BUTTON FOR LOCK ACTUATOR <i>1 pc</i> | \$ 159.00                         | X      |
| 24                               | SUNDRIES                                  | \$ 200.00                         | ?      |
| <b>TOTAL SPARE PARTS CHARGES</b> |                                           | <b>: \$ 12,102.00</b>             |        |
| <b>TOTAL LABOUR</b>              |                                           | <b>: \$ 4,552.00</b>              |        |
| <b>GRAND TOTAL</b>               |                                           | <b>: \$ 16,654.00</b>             |        |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

## Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

### Telefax

Name : Adrian King  
Surveyed Date : 13/06/18  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised , 04 Days .

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant