

ASS. REC. BY:

REF: CS/FCI18010590/R19d3 n2

Special Instruction:

Survivor:

CWS

ASSIGNMENT (Office)

From (Person):

Serene Lee

of

FCI

Date/Time:

11/6/18 @ 2.25pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFU 2346 H

Insured:

SHC 3769K

at Workshop m/s:

Performance Motor

Tel:

63190174

of

303 Alexandra Road

Policy No:

D-18089936MESH

Claim No:

D18004588 MPSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/06/2018

CA / REV / REP. / REV 24 HRS

(up)

02072018

H.O.D. Endorsement:

Date/Time:

3:10pm @ 11/6/18

Person Contacted:

Caroline

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate	Qty
	SFU 2346 H - X		
	SHC 3769K - CS/FCI16023823 / K/H3M2		
03/7/18 @ 1.38pm	revised to Serene Lee by email.		
07/08/18 @ 1.36pm	confirmed with Caroline final fig \$3,90.40, 3 days.		
	(Red \$2809.75, 47%)		



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004588MFSH

Date: 03 July 2018

Our Ref: CS/FCI18010590/R1qd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SFU 2346H .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 02/07/2018 at the premises of M/s PERFORMANCE MOTORS LIMITED . and have the following to report:-

Workshop Estimate Amount	: S\$ <u>5,864.50</u> .
Revised Estimate Amount	: S\$ <u>3,032.15</u> .
“Check” Items Amount	: S\$ <u>1,851.35</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	08-06-2018	Our Ref No. D18004588MFSH
Accident Date	07-06-2018	Claim Type. Third Party
Insured Vehicle	SHC3769K	Third Party Vehicle. SFU2346H
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/ 0	Fax No. 64794601
Survey Type	DIRECT SETTLEMENT: EST COR - \$6,275.02	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241262)



PRI Documents



Close



PRI Header Details

Claim No	D18004588MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PERFORM [RAGAM RADH
Workshop Name	PERFORMANCE MOTORS LIMITED (Contact Person : CAROLINE)	Survey Location & Contact Details	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CEP Mobile: 0 , Phone: 63190174 , Fax: 64794601 EmailId: PML-PBSP@SIMEDARBY.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT: EST COR - \$6,275.02		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC3769K	TP Vehicle No	SFU2346H
PRI Recieved Date	08-06-2018 04:15:44 PM	Surveyor Appointed Date	11-06-2018 02:24:47 PM	Surveyor Accept Date	11-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	11-06-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 7 August 2018 1:36 PM
To: 'PBSP'; Rasul (LKKAuto); SUR
Subject: RE: FINAL REPORT / SFU2346H

Dear Caroline,

WITHOUT PREJUDICE

Confirm final fig \$3,190.40 before GST and 3 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Thursday, 26 July 2018 5:43 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT / SFU2346H

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,014.00

Total Parts : 1,176.40

Total Labour & Parts : 3,190.40

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 3 July 2018 1:38 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004588MFSH/1
Attachments: CSFCI18010590R1qd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SFU 2346H.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 11 June 2018 3:13 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004588MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 11 June 2018 2:24 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004588MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/510 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

08 JUN 2018

Estimate No. : b1 47219 Page No. : 1 of 5
Date Estimated : 07/06/2018
Prepared By : Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR - Ragam Radha Madhav 13 Westridge Walk Singapore 117844	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFU2346H	NP47346	21/12/2012	320iA/4	0

DESCRIPTION	VALUE
To replace rear bumper and attachment include knocking	850 / 1,700.00
Painting rear bumper	934 / 1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 / 171.00
Sundries.	REC 80.00
Total Labour 1:	2,995.00

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER BOTTOM REINFORCEMENT	1	66.10	66.10
REAR BUMPER CENTRE GUIDE	1	32.10	32.10
REAR BUMPER CARRIER (ECE)	1	432.90	432.90
DECORATIVE STRIP (LUXURY LINE)	1	145.05	145.05
RR BUMPER TRIM PANEL PRIMED (LINES/	1	1,018.15	1,018.15
REAR PDC HOLDER SET	1	23.10	23.10
REAR BUMPER LH SIDE GUIDE	1	57.05	57.05
REAR BUMPER RH SIDE GUIDE	1	57.05	57.05
RR BUMPER RH REFLECTOR	1	35.20	35.20
RR BUMPER LH REFLECTOR	1	35.20	35.20
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
ULTRASONIC SENSOR BLACK	4	236.85	947.40
Total Parts :			2,869.50

Handwritten notes:
 X { 66.10
 32.10
 432.90
 145.05
 1,018.15
 23.10
 57.05
 57.05
 35.20
 35.20
 20.20
 947.40
 1100.25

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No: 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.	: b1 47219	Page No. : 2 of 5
Date Estimated	: 07/06/2018	
Prepared By	: Gary Poh Chai Hoon	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFU2346H	NP47346	21/12/2012	320iA/4	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey ~~before~~ after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regd No. _____ Claim No. _____

Date: 02/07/18 @ 1400

Surveyor's Name: RASUL

Phone No: 90010068

3 days

[Handwritten Signature]
3/7/18

Labour 1	:	2,995.00
Parts	:	2,869.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	410.52
Grand Total	:	6,275.02

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

5999.65

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 47219
Date Estimated : 07/06/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Ragam Radha Madhav
13 Westridge Walk

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 117844

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE	ORIGINAL PRICE	DISC. %	NETT
SFU2346H	NP47346	21/12/2012	320iA/4	0			
DESCRIPTION							
To replace rear bumper and attachments include knocking out dents caused by the accident					850.00		850.00
To spray paint rear bumper					934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function.					150.00		150.00
Sundries.					80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PANEL PRIMED (LINES)	1,100.25	1.00		1,100.25
REAR PDC HOLDER SET	23.10	1.00		23.10
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,176.40
Total Labour & Parts :	3,190.40
Deduction for Excess :	
Total Repair Costs less Excess:	3,190.40
GST @7%:	223.33
Grand Total :	3,413.73

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 47219
Date Estimated : 07/06/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Ragam Radha Madhav
13 Westridge Walk

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 117844

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SFU2346H	NP47346	21/12/2012	320iA/4	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05

Total Labour :	
Total Parts :	53.05
Total Labour & Parts :	53.05



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18010590/R1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 13-08-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 3769K	Veh. Inspected	SFU 2346H
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18004588MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	11/06/2018
2. Vehicle Particulars & Condition			
Make & Model	BMW 320I	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WBA3B16040NP47346	Colour	BLACK
Odometer	127028	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm
L/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/06/2018	Inspection Date	02/07/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFU 2346H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RR BUMPER BOTTOM REINFORCEMENT (SN)	SERVICEABLE	66.10	-
1	REAR BUMPER CENTRE GUIDE (SN)	SERVICEABLE	32.10	-
1	REAR BUMPER CARRIER (ECE)(SN)	SERVICEABLE	432.90	-
1	DECORATIVE STRIP (LUXURY LINE)(SN)	SERVICEABLE	145.05	-
1	RR BUMPER TRIM PANEL PRIMED (LINES)(SN)	DEFORMED	1,100.25	1,100.25
1	REAR PDC HOLDER SET (SN)	NECESSARY	23.10	23.10
1	REAR BUMPER LH SIDE GUIDE (SN)	SERVICEABLE	57.05	-
1	REAR BUMPER RH SIDE GUIDE (SN)	SERVICEABLE	57.05	-
1	RR BUMPER RH REFLECTOR (SN)	SERVICEABLE	35.20	-
1	RR BUMPER LH REFLECTOR (SN)	SERVICEABLE	35.20	-
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	SERVICEABLE	20.20	-
4	ULTRASONIC SENSOR BLACK (SN)	SERVICEABLE	947.40	-
1	(DG/SL) ADHESIVE SET K6 (ADDITIONAL)(SN)	NECESSARY	53.05	53.05
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
			3,084.65	1,256.40
LABOUR				
	TO REPLACE REAR BUMPER AND ATTACHMENT INCLUDE KNOCKING.		1,700.00	850.00
	PAINTING REAR BUMPER.		1,038.00	934.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
			2,915.00	1,934.00
GRAND TOTAL			5,999.65	3,190.40
RECOMMENDED COST OF REPAIRS				3,190.40

Report Ref No. CS/FCI18010590/R1qd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.