

22/03/2003

ASS. REC. BY:

REF: CS/EGT/16010696/K1qdz/n2

Special Instruction:

Surveyor: Calvin

ASSIGNMENT (Office)

From (Person): Yee Pei Li of EGT Date/Time: 11/06/18 @ 4:09pm

Estimated Cost: _____ Bill to: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SHC6662P Insured: GBF8114Xat Workshop m/s: Premier Automotive Tel: 6544 6671of 23 Changi South Ave 2Policy No: _____ Claim No: GBF8114Y/SL/pl CPMC G18000114

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 08/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS lup H.O.D. Endorsement: _____Date/Time: 4:17pm @ 11/6/18 Person Contacted: Gary Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC6662P-CS/III16018354/S/6XX DOA: 8/9/2016
	GBF8114Y-X
20/6/18 @ 3:16pm	revised to spare tire by email.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI18010596/K1qd3	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 11-06-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 8114Y	Veh. Inspected	SHC 6662P	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBF8114Y/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	11/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/06/2018	Inspection Date		
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GBF8114Y/SL/pl

Date: 20th June 2018

Our Ref: CS/EG118010596/K1qd3

Without Prejudice

The Motor Claims Department
ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SHC 6662P


We thank you for the instruction on 11/06/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/06/2018 at the premises of M/s PREMIER AUTOMOTIVE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>4,111.00</u>
Revised Estimate Amount	: S\$ <u>2,101.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
Salvage Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the n/s body.



Comments/ Present Status:

Damages consistent.

Days of repair: 3 days.

We have NOT authorise repair.

Yours faithfully

Kalvin Ang
Automotive Assessor

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 11 June 2018 4:09 PM
To: 'admin-d@lkkauto.com'
Cc: 'ASSIGNMENTS@LKKAUTO.COM'
Subject: OI : GBF8114Y / TP : SHC6662P/LKK / DOA : 08/06/2018
Attachments: GBF8114Y - SAS.pdf; SHC6662P - SAS.pdf; SHC6662P - PRS FORM.pdf; Pre-inspection / Accident involving SHC6662P & GBF8114Y on 08.06.18 (815 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

ADDRESS : 23 CHANGI SOUTH AVE 2
#01-02
SINGAPORE 486443

PERSON TO CONTACT : GARY SHI @ 6544 6671 / 6214 8880 EXT 69

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle. Inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 11.06.2018
Our Reference: GBF 8114Y/SL/pl
Your Reference: SHC 6662P

Sent via Fax

or

Email

weedek.goh@premiertaxi.com /
gary.shi@premiertaxi.com /
vincent.chua@premiertaxi.com

To:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SHC 6662P
Insured's Vehicle: GBF 8114Y
Date Of Accident: 08.06.2018


We acknowledge receipt of your request for PRS on: 11.06.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* **LKK**

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input checked="" type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us todate.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				<u>FAX : 6829 9247</u>

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 20 June 2018 3:16 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'; assignments; 'Steve Lim'
Cc: SUR
Subject: RE: GBF8114Y / TP : SHC6662P/LKK / DOA : 08/06/2018
Attachments: CSEGI18010596K1qd3.pdf

Dear Steve,

Enclosed herewith preliminary advice of SHC 6662P.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Saturday, 16 June 2018 12:40 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBF8114Y / TP : SHC6662P/LKK / DOA : 08/06/2018

Claim no. is CDMCG18000114

From: Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Monday, 11 June, 2018 4:19 PM
To: Survey Report (ERGO Insurance Pte. Ltd.); 'assignments'
Cc: "SUR"; Yee Pei Li
Subject: RE: GBF8114Y / TP : SHC6662P/LKK / DOA : 08/06/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Monday, 11 June 2018 4:09 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>
Subject: OI : GBF8114Y / TP : SHC6662P/LKK / DOA : 08/06/2018

Dear Catherine,

Enquire Transaction History

Transaction History Details

Log Date/Time:	11 Nov 2013 / 10:51:29	Receipt No.:	AACCK001-AX239-131111-000020
Asset Type:	Vehicle	Transaction Amount:	\$75,658.00
Asset ID:	SHC6662P	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20131111105129413417		

Vehicle No.:	SHC6662P
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	11 Nov 2013
Original Registration Date:	11 Nov 2013
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5451086
Engine No.:	D4FDDH308301
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$19,721.00
Minimum PARF Benefit:	\$7,332.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	11 Nov 2013 10:51:29
COE No.:	20131111101000775D
COE Expiry Date:	10 Nov 2021
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$63,297.00
Lifespan Expiry Date:	10 Nov 2021
Owner ID Type:	Company

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

11-Jun-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6662 P

1 pc	n/s wing mirror assy	590	\$	590.00
1 pc	Front n/s fender	384	\$	384.00
1 pc	Front n/s fender inner shield	120	\$	120.00
1 pc	Front bumper emblem	44	\$	44.00
1 pc	Front n/s wheel cover	116	\$	116.00
1 pc	Rear n/s wheel cover	116	\$	116.00
			\$	1,370.00
			Less 10%	\$ 137.00
			\$	1,233.00

S/NETT

1 set	Front n/s fender inner shield clips	28	\$	28.00
1 pc	Front n/s fender sticker	30	\$	30.00
1 set	n/s door stickers	100	\$	100.00
1 pc	Rear n/s fender stickers	60	\$	60.00

Sundry	200	\$	50.00 20
To check wheel alignment		\$	80.00 X 1, 1
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 50
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front bumper, front n/s door, rear n/s door & rear n/s fender		\$	850.00 400
To putty and spray painting on front bumper, front n/s fender, n/s side mirror, front n/s door, rear n/s door, rear n/s fender	X X	\$	1,350.00 590
To apply rustproofing on the repaired and replaced panels.		\$	150.00 X 1, 1
		\$	4,111.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalva 12/6/18

19/6/18 1545hrs

3 hrs

4/5 After Repair photo

Auto Consultants hence notify
er of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18010596/K1qd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 28-06-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 8114Y	Veh. Inspected	SHC 6662P	
Policy No.		Coverage (\$)	0.00	
Claim No.	CDMCG18000114	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	11/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	KNAGM414ME5451086	Colour	SILVER	
Odometer	486991	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	ACHILLES	7 mm	
L/H Front Tyre	205/60 R16	ACHILLES	7 mm	
R/H Rear Tyre	205/60 R16	ACHILLES	7 mm	
L/H Rear Tyre	205/60 R16	ACHILLES	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/06/2018	Inspection Date	19/06/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6662P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	N/S WING MIRROR ASSY	CRACKED	590.00	590.00
1	FRONT N/S FENDER	DENTED	384.00	384.00
1	FRONT N/S FENDER INNER SHIELD	SERVICEABLE	120.00	-
1	FRONT BUMPER EMBLEM	NOT NECESSARY	44.00	-
1	FRONT N/S WHEEL COVER	GRAZED	116.00	116.00
1	REAR N/S WHEEL COVER	SERVICEABLE	116.00	-
	LESS 10% DISCOUNT		-137.00	-109.00
			1,233.00	981.00
SPECIAL NETT ITEMS				
1	SET FRONT N/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	28.00	-
1	FRONT N/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	SET N/S DOOR STICKERS (SN)	NOT NECESSARY	100.00	-
1	REAR N/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			268.00	80.00
LABOUR				
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE FRONT BUMPER, FRONT N/S DOOR, REAR N/S DOOR & REAR N/S FENDER.		850.00	400.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER, FRONT N/S FENDER, N/S SIDE MIRROR, FRONT N/S DOOR, REAR N/S DOOR, REAR N/S FENDER.		1,350.00	590.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	150.00	-
			2,610.00	1,040.00
GRAND TOTAL			4,111.00	2,101.00

Report Ref No. CS/EGI18010596/K1qd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,650.00
---	--	--	----------

Report Ref No. CS/EGI18010596/K1qd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.