

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 29673

Vehicle Insured : GBF 1787 B
Accident Date : 16-Mar-2018

Date : 03-Apr-2018

Our Ref : 180235 (EQ) / SHUMAN

PAGE : 1

TAM KIN KEUNG (MR)
Singapore

Not Authorized
6/1 by 8?
Resurvey After Pain *3 days*

ESTIMATED COST OF REPAIR FOR VOLVO S60 D2 1560cc (2013) SKJ5717A

1 pc o/s front fender	1,000.00	c	✓
1 pc front bumper	1,350.00	c	?
1 pc front bumper side retainer	100.00	c	?
	2,450.00		
Add 20% :	490.00		
	2,940.00		

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

380.00 *300*

To apply undersealing

30.00 ✓

To putty and respray on affected
portions.

600.00 *440*

Total : S\$ 3,950.00

Singapore Dollars Three Thousand Nine Hundred
and Fifty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: