

REPAIR ESTIMATE*

VEHICLE NO : SHD 4255P

DATE 6/7/2018 16:13

MAKE :

MODEL : HYUNDAI SONATA

QBE / LKK
RIGHT FRONT

F2

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>X 1/2</i>			\$ 538.80
	Front Bumper Bracket (RH) <i>X</i>			\$ 20.10
	Front Wheel Hub Cap (RH) <i>X</i>			\$ 145.00
	<i>Front RH Fender X 1/2</i>			
	SUB TOTAL			\$ 703.90
	LESS 20% <i>252</i>			\$ 140.78
	DISCOUNTED TOTAL			\$ 563.12
	Front Fender Advertisement Logo (RH) <i>✓</i>			\$ 100.00
				\$ 100.00
	Labour Charge			200
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 500.00
	FRT Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 980.00
	ESTIMATE TOTAL			\$ 1,643.12

1 call 1 call
8/6/18 0945h
2 Pys
43
After Ryz p 4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.