

f

QUAN DE MOTOR TRADING

1 KAKI BUKIT AVENUE 6, #01-67
 AUTOBAY, SINGAPORE 417883
 HP: 96709191 FAX: 66840767

EQ Insurance Co. Ltd
 5 Maxwell Road,
 #17-00 Tower Block
 MND Complex
 Singapore 069110.
 Attn: Motor Claims Department

Attn: Mr. Marcus (Bureaucrat)
 Not Allowed
 L/S \$ 58.00
 8/11

Date: 11 June 2018

**Accident on 08/06/2018 involving vehicles SLX5361G & SLR1673P
 along PIE towards Tuas**

Estimate cost of repair to vehicle SLX5361G Honda Civic

1 pc.	rear bumper	DD	\$	638.00	—
2 pcs.	rear bumper side retainers @\$20.50	set	\$	41.00	—
1 set	rear bumper clips	set	\$	45.00	—
1 pc.	bootlid	DD/SUC	\$	610.00	—
1 pc.	bootlid rear logo	set	\$	28.80	—
1 pc.	bootlid "CIVIC" emblem	set	\$	32.20	—
1 pc.	bootlid "IVTEC" emblem	set	\$	36.50	—
2 pcs.	bootlid reflectors @\$248.20	17	\$	496.40	X
1 pc.	bootlid inner lock	twi	\$	198.60	—
1 pc.	bootlid weatherstrip	twi	\$	101.00	—
1 pc.	bootlid inner trim	17	\$	282.30	X
2 pcs.	bootlid hinges @\$148.60	2	\$	297.20	X
2 pcs.	taillamps @\$282.50	one	\$	565.00	—
2 pcs.	taillamp housing panel @\$167.70	MSD	\$	335.40	IPC
1 pc.	rear end panel	Bo lid	\$	296.60	—
1 pc.	rear end panel top garnish	tyl	\$	160.80	—
1 pc.	rear floor panel	crumpled	\$	911.40	—
1 pc.	rear floor panel top board	weld	\$	316.00	—
2 pcs.	rear fenders @\$741.50	MS De	\$	1,483.00	X
2 pcs.	rear fender inner trims @\$242.80	2	\$	485.60	IPC
1 pc.	rear exhaust	17	\$	494.00	X
2 pcs.	rear exhaust mountings @\$36.00	17	\$	72.00	X
1 pc.	rear splash shield	17	\$	42.50	X
1 pc.	rear windscreen moulding	17	\$	68.20	X
			\$	8,037.50	
		Less 20%	\$	1,607.50	
			\$	6,430.00	

4391.40
 3513.12

S. Nett Items:

1 set rear bumper reverse sensor
 1 pc. rear end panel sealant
 1 pc. rear license plate w/holder
 1 set rear floor panel insulator
 1 pc. rear windscreen sealant

Bal c/f \$ 6,430.00

sluhl \$ 300.00 200
 rec \$ 100.00 50
 11 \$ 50.00 X
 rec \$ 300.00 200
 11 \$ 60.00 X

Labour Charges:

To check wiring
 To remove & refix reverse sensor
 To remove & refix seat & cushion upholstery
 To remove & refix rear exhaust
 To remove & reinstall rear windscreen
 To remove & refix petrol tank
 To transfer bootlid components
 To spray rust proofing
 Labour for panel beating, welding & renew parts
 To putty & spray painting

\$ 80.00 30
 \$ 100.00 50
 \$ 150.00 100
 \$ 120.00 60
 11 \$ 150.00 X
 , \$ 120.00 80
 \$ 100.00 60
 \$ 200.00 120
 \$ 2,000.00 1600
 \$ 1,600.00 1200

Total: \$ 11,860.00

7263.12
 5810.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: