

15/02/2011

INS. CASE OWNER:

Ming Yau

CC 6 / AIG1801

0612, 4p67 1/2

LKK:
IDAC:

Surveyor:

marcus

DOI:

ASSIGNMENT

11/6/18

Date / Time:

11/6/18

Registered in Merimen:

11/6/18

Pre-assign / CCU / FTE:

SJH 66615



Insured Vehicle No.:

Name of Insured:

Teng Yim Yau

Insured Tel No.:

HP:

9524444

Excess Sec II :\$5

D.O.A.:

26/6/18

Is driver the owner?

(YES) / NO

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L) YES / NO

Claim No.:

085016166756

Policy No.:

Make / Model:

Mazda

Place of Accident:

PTE TO PPE

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

GBC 7569R

INSRS:
WSP:
Tel:
Liability:
RMKS:

Lin's

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

12/6/18

LHT

11/7/18 5:30pm

12/7/18

21/8/18

24/8/18

GBC 7569R - Y

SJH 66615 - Y

Called OI, Mr. Teng. Confirm rear end
TP. Inform TP claim. Agreed to settle
& aware NCD issue.

Sent letter to OI

OI video.

PV sent

Freepass to show per to close

RECEIVED 21 AUG 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No. 27

If NO or B 28, Ass. Lia:

Repair Cost:

\$5

6400.00

Loss of Rental (LOR):

\$5

(

days)

Loss of Use (LOU):

\$5

360.00

(\$

60 x 6

days)

Loss of Income (LOI):

\$5

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow / Independent)

Legal Cost

\$5

Total:

\$5

6760.00

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with

Email

Call

Payee 1:

\$5

6760.00

Name 1:

Lin's Brother Auto Engineering Workshop

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320 + \$20

COPY SENT

ASS. REC. BY: Marcus

A14/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBC 7569Rat Workshop m/s 1125

of _____

Insured: 5116661

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 835k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBC 7569R Yr Regn: 10/13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CM/Make: FIAT Doblo c.c. 1248Colour: white A/C: Insured / Std / NI / NASp. Reading: 79off T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2FA 263000 0 6101433

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mmR/Bal: 6 mm L/Bal: 6 mmL/Bal: 6 mm D.O.A. 26/5/18 D.O.I. 11/6/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 10600 5 yrs. rule by 7800US\$ 6400 (Reel \$ 3495.20 / 3591)

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ \$ - RS. ____ \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$ _____)

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liusbros@gmail.com

Invoice/Ref No: GBC7569R180526

Estimate**Customer**

Name: AIG Asia Pacific Insurance Pte Ltd

Date: 08-06-18

Address: Motor Claims Department

Vehicle No: GBC7569R

78 Shenton Way #07-16

Model/Make: Fiat Doblo Cargo

AIG Building

Singapore 079120

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Lh Tailgate <i>306500</i>	\$ 2,156.30	
2	Tailgate Outer Garnish <i>CU7</i>	\$ 369.80	
3	Tailgate "70 KM/H" Sticker <i>neu</i>	\$ 12.00	SN 105.~
4	Tailgate Inner Lower Lock <i>neu</i>	\$ 192.90	
5	Tailgate Sealant <i>111</i>	\$ 50.00	SN 405.~
6	Rear Rh Tailgate <i>306500</i>	\$ 1,895.90	
7	Tailgate Outer Garnish <i>111</i>	\$ 321.80	
8	Tailgate "6 PAX" Sticker <i>neu</i>	\$ 12.00	SN 105.~
9	Tailgate Sealant <i>neu</i>	\$ 50.00	SN 405.~
10	Rear Bumper <i>2019</i>	\$ 627.00	
11	Bumper Clips 1 set <i>neu</i>	\$ 65.00	SN 505.~
12	Bumper Top Protector <i>neu</i>	\$ 185.00	
13	Bumper Beam <i>3061</i>	\$ 475.30	
14	Bumper Side Holder 02 pcs (@ \$865.00) <i>neu</i>	\$ 130.00	
15	Bumper Side Holder Clips 1 set <i>Repl</i>	\$ 45.00	SN X
16	Bumper Reverse Sensor <i>shrub</i>	\$ 220.00	SN 2005.~
17	End Panel <i>2019 part</i>	\$ 430.00	
18	End Panel Garnish <i>111</i>	\$ 347.70	
	To check all wiring & electrical component for proper function	\$ 50.00	30
	Remove and refix rear Rh/Lh tailgate components	\$ 150.00	120
	Remove and refix rear bumper reverse sensor	\$ 80.00	50
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	600
	To putty & spray painting & including touch up paint on accident affected	\$ 880.00	800
	Remove & reinstall Rh / Lh Tailgate Glass to facilitate repairs	\$ 180.00	100
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 120.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 9,845.70

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplement(ary item/s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-6462.2

5-814 98

S.N - 350

146 - 1880

8045 8

not allowed

n/s 26400

11/6/18
5 day.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-087920

Date of Request 08/06/2018

Your Ref No:

Online Purchase

LIU'S BROTHER AUTO WORKSHOP

1 Kaki Bukit Ave 6 #01-01

Auto Bay@Kaki Bukit

Singapore 417883

Dear Sir/Madam,

Enquiry Date 08/06/2018
Enquiry By Susan Low Siew Yian
TP Vehicle No. SJH6661S
Accident Date 27/05/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJH6661S	AIG Asia Pacific Insurance Pte. Ltd.	08/12/2017-07/12/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18010612/Upb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 11-06-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJH 6661S	Veh. Inspected	GBC 7569R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	11/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	26/05/2018	Inspection Date	11/06/2018
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Our Ref: GBC7569R180526

Date: 04/07/2018

Your Ref:

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Chartis Building
Singapore 079120

Attn: Motor Claims Department

Dear Sir / Madam

**TRAFFIC ACCIDENT ALONG KPE NEAR SIMS WAY EXIT
INVOLVING GBC7569R AND SJH6661S ON 26/05/2018**

We/I, **Messers Goldbell Leasing Pte Ltd** (Nric / ROC No: **199001196N**), the registered owners of m/vehicle – **GBC7569R** at all material times of the above accident. Our/my vehicle was surveyed by "AIG Asia" authorized appraiser and we/I based our/my on his recommendation for **S\$6,400-00** being the repair for **05** Days (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle **SJH6661S** when the same was involved in the aforesaid accident with our/my m/vehicle – **GBC7569R**.

We/I whereby you are the insurers of m/vehicle **SJH6661S** and the driver / owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle – **GBC7569R** has suffered loss and damage as follows:

(a) Cost of repairs	S\$	6,400-00
(b) LOU for pre-repair notice 02 days @\$80-00		120-00
(c) LOU Fee for 05 days @\$60-00		300-00
(d) GIA / LTA search fee		2-00

Total Amount

S\$ 6,822-00

We/I enclose herewith copies of the supporting documents for vehicle no. **GBC7569R** as follows:-

- (i) Motor Accident Report;
- (ii) Repair Invoices;

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of **M/s Liu's Brother Auto Engineering Workshop**. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,



The owner of m/vehicle **GBC7569R**
Messers Goldbell Leasing Pte Ltd
cc. Liu's Bro Auto Engrg Ws

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	1196N

Vehicle Details

Vehicle No.:	GBC7569R
Vehicle to be Exported:	No
Intended De-registration Date:	08 Jun 2018
Vehicle Make:	FIAT
Vehicle Model:	DOBLO CARGO SX 1.3 MJ
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	263A20005067589
Chassis No.:	ZFA26300006101433
Maximum Power Output:	-
Open Market Value:	\$17,945.00
Original Registration Date:	16 Oct 2013
First Registration Date:	16 Oct 2013
Transfer Count:	1
Actual ARF Paid:	\$898.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	15 Oct 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$19,836.00
COE Rebate Amount:	\$10,616.00
Total Rebate Amount:	\$10,616.00

The information contained herein is correct as at 08 Jun 2018

OK

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 28 July 2018 10:02 AM
To: Lee, Ming Yao (MingYao.Lee@aig.com)
Subject: <Request for OI Video>Your Ref: 0850161667SG *Our Ref: CC6/AIG18010612/Upb3
[ACCIDENT INVOLVING SJH 6661S(OI) & GBC 7569R(TP) ON 26/05/2018]

Your Ref: **0850161667SG**
Our Ref: CC6/AIG18010612/Upb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SJH 6661S(OI) & GBC 7569R(TP) ON 26/05/2018

We refer to the above matter.

Kindly assist to upload OI's video in Merimen for our viewing.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Lee, Ming-Yao <MingYao.Lee@aig.com>
Sent: Tuesday, 31 July 2018 11:06 AM
To: Hsiao Tong (LKKAUTO)
Subject: RE: <Request for OI Video>Your Ref: 0850161667SG *Our Ref: CC6/AIG18010612/Upb3 [ACCIDENT INVOLVING SJH 6661S(OI) & GBC 7569R(TP) ON 26/05/2018]

Hi Hsiao Tong,

Video shared in Merimen.

Regards,
George Lee
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1769 | Fax +(65) 6835 7416

Ming-Yao.Lee@aig.com | www.aig.com.sg

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: 28 July 2018 10:02
To: Lee, Ming-Yao
Subject: <Request for OI Video>Your Ref: 0850161667SG *Our Ref: CC6/AIG18010612/Upb3 [ACCIDENT INVOLVING SJH 6661S(OI) & GBC 7569R(TP) ON 26/05/2018]

Your Ref: **0850161667SG**
Our Ref: CC6/AIG18010612/Upb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SJH 6661S(OI) & GBC 7569R(TP) ON 26/05/2018

We refer to the above matter.

Kindly assist to upload OI's video in Merimen for our viewing.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 1 August 2018 10:09 AM
To: liusbrojasmine@yahoo.com; 'Susan Low'
Cc: Admin A
Subject: <OFFER> - GBC7569R Claims against SJH6661S ***LKK
REF:CC6/AIG18010612/Upb3

Without Prejudice

Hi Susan,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair	\$ 6,400.00
2. Loss of Use (6days x \$60.00)	\$ 360.00
3. LTA/GIA search fee	DOA not tally
TOTAL	<u>\$ 6,760.00</u>

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)
Sent: Monday, 11 June 2018 5:50 PM
To: liusbrojasmine@yahoo.com
Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: RE: Request for 3rd party claims survey - GBC7569R Claims against SJH6661S ***LKK
REF:CC6/AIG18010612/Upb3

Dear Jasmine,

We refer to the below email.

Please be informed that we are currently pending for our insured's report.

Kindly note that for liability, claim negotiation and settlement, please contact Hsiao Tong at 6742 3197.

Our respective case handler will look into the matter and revert to you in due course.

Thank you

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jasmine Low [<mailto:liusbrojasmine@yahoo.com>]

Sent: Friday, 8 June, 2018 4:38 PM

To: assignments@lkkauto.com; sur@lkkauto.com

Subject: Request for 3rd party claims survey - GBC7569R Claims against SJH6661S

Accident on 26/05/2018 Along KPE Near Sims Way Exit

Involving GBC7569R and SJH6661S

We refer to the above accident and 3rd party claims.

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop at No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883 as soon as possible.

Kindly arrange.

Thank you.

Best Regard!

Jasmine Low

M/s Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01

AutoBay @ Kaki Bukit

Singapore 417883 ☎: 6741 1730 📠: 6744 5746

Date of Survey:- _____

Name of Authorise Surveyor:- _____

Surveyor Email: _____

Remark :- _____

Hsiao Tong (LKKAUTO)

From: Susan Low <liusbro@ymail.com>
Sent: Wednesday, 1 August 2018 1:00 PM
To: Hsiao Tong (LKKAUTO)
Subject: Our Ref: GBC7569R180526 Your Ref: LKK REF:CC6/AIG18010612/Upb3

We hereby confirm acceptance of your offer. Kindly let us have your discharge for our client's execution and your cheque made in our favour as soon as possible.

Thank.

Best Regards,

Susan Low
M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 67411730 Fax: 67445746

On Wednesday, 1 August 2018, 12:48:08 PM SGT, Jasmine Low <liusbrojasmine@yahoo.com> wrote:

----- Forwarded message -----

From: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
To: liusbrojasmine@yahoo.com <liusbrojasmine@yahoo.com>; Susan Low <liusbro@ymail.com>
Cc: Admin A <admin-a@lkkauto.com>
Sent: Wednesday, 1 August 2018 10:09:07 AM
Subject: - GBC7569R Claims against SJH6661S ***LKK REF:CC6/AIG18010612/Upb3

Without Prejudice

Hi Susan,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair	\$ 6,400.00
2. Loss of Use (6days x \$60.00)	\$ 360.00
3. LTA/GIA search fee	DOA not tally
TOTAL	\$ 6,760.00

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Monday, 11 June 2018 5:50 PM

To: liusbrojasmine@yahoo.com

Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Request for 3rd party claims survey - GBC7569R Claims against SJH6661S ***LKK
REF:CC6/AIG18010612/Upb3

Dear Jasmine,

We refer to the below email.

Please be informed that we are currently pending for our insured's report.

Kindly note that for liability, claim negotiation and settlement, please contact Hsiao Tong at 6742 3197.

Our respective case handler will look into the matter and revert to you in due course.

Thank you

To check availability of the case handler , you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jasmine Low [<mailto:liusbrojasmine@yahoo.com>]

Sent: Friday, 8 June, 2018 4:38 PM

To: assignments@lkkauto.com; sur@lkkauto.com

Subject: Request for 3rd party claims survey - GBC7569R Claims against SJH6661S

Accident on 26/05/2018 Along KPE Near Sims Way Exit

Involving GBC7569R and SJH6661S

We refer to the above accident and 3rd party claims.

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop at No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883 as soon as possible.

Kindly arrange.

Thank you.

Best Regard!

Jasmine Low

M/s Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01

AutoBay @ Kaki Bukit

Singapore 417883 ☎: 6741 1730 📠: 6744 5746

Date of Survey:- _____

Name of Authorise Surveyor:- _____

Surveyor Email: _____

Remark :- _____



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18010612/Upb3

13 JULY 2018

TENG JUIN YAN
BLK 686C CHOA CHU KANG CRESCENT
#17-212
SINGAPORE 683686

Dear Sir/Madam,

ACCIDENT INVOLVING SJH 6661S & GBC 7569R ON 26/05/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from GBC 7569R against your motor insurance policy.

Based on the accident report and accident scenario, liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG
Case Handler
DID: 6742 3197
FAX: 6741 4108
Email: chewht@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT

(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

We / I, Messers Goldbell Leasing Pte Ltd ("the third party claimant") of No. 18 Tuas Avenue 10 Singapore 639142 (address), owner of GBC7569R (vehicle No.) hereby authorize M/s Liu's Brother Auto Engineering Workshop ("the workshop") to act for me / us with respect to my / our claim for repair costs and/or rental and/or loss of use ("claim") for my / our vehicle no. GBC7569R that was damaged pursuant to the accident which occurred on 26/05/2018 (date) along KPE Near Sims Way Exit (location) involving vehicle no / s SJH6661S ("the accident").

We / I further authorize the workshop to settle my / our above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my / our claim with payment cheque / s being made in favour of the workshop.

We / I further acknowledge that any settlement the workshop may reach on my / our behalf is on a without prejudice and without admission of liability basis insofar as the driver / owner / insurers of the other vehicle / is concerned.

Dated this 11th (day) of August (month) 20 18 (years)



Signed by "the third party claimant"
Messers Goldbell Leasing Pte Ltd
199001196N
GBC7569R



Signed by "the workshop"

Liu's Brother Auto Engineering Workshop
Co. Reg. No.: 53291793J
No.1 Kaki Bukit Avenue 6 #01-01
(Block A Heavy Vehicle Entrance)
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 6741 1730 / 1 Fax: 6744 5746

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, LIU'S BROTHER AUTO ENGINEERING WORKSHOP ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$6,400.00 (Repair Cost), S\$360.00 (Loss of Use/Rental), SS - (Disbursement) for vehicle no. GBC 7569R that was damaged pursuant to the accident which occurred on 26/05/2018 (date) along KPE NEAR SIMS WAY EXIT (location) involving vehicle no/s SJH 6661S. This is pursuant to the inspection conducted on 11/06/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner GOLDBELL LEASING PTE LTD (the third party claimant") of vehicle no. GBC 7569R make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to GBC 7569R (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 11th (day) of August (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

Liu's Brother Auto Engineering Workshop
ROB No. 53291793J
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 391005

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liusbros@gmail.com

Invoice/Ref No: GBC7569R180526

Final Bill

Customer

Name: AIG Asia Pacific Insurance Pte Ltd

Date: 04-07-18

Address: Motor Claims Department

Vehicle No: GBC7569R

78 Shenton Way #07-16

Model/Make: Fiat Doblo Cargo

AIG Building Singapore 079120

SX 1.3 MJ

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Lh Tailgate	\$ 2,156.30	\$ -
2	Tailgate Outer Garnish	\$ 369.80	\$ -
3	Tailgate "70 KM/H" Sticker	\$ 12.00	SN \$ -
4	Tailgate Inner Lower Lock	\$ 192.90	\$ -
5	Tailgate Sealant	\$ 50.00	SN \$ -
6	Rear Rh Tailgate	\$ 1,895.90	\$ -
7	Tailgate Outer Garnish	\$ 321.80	\$ -
8	Tailgate "6 PAX" Sticker	\$ 12.00	SN \$ -
9	Tailgate Sealant	\$ 50.00	SN \$ -
10	Rear Bumper	\$ 627.00	\$ -
11	Bumper Clips 1 set	\$ 65.00	SN \$ -
12	Bumper Top Protector	\$ 185.00	\$ -
13	Bumper Beam	\$ 475.30	\$ -
14	Bumper Side Holder 02 pcs (@ \$865.00)	\$ 130.00	\$ -
15	Bumper Side Holder Clips 1 set	\$ 45.00	SN \$ -
16	Bumper Reverse Sensor	\$ 220.00	SN \$ -
17	End Panel	\$ 430.00	\$ -
18	End Panel Garnish	\$ 347.70	\$ -
	To check all wiring & electrical component for proper function	\$ 50.00	\$ -
	Remove and refix rear Rh/Lh tailgate components & wiper mechanism	\$ 150.00	\$ -
	Remove and refix rear bumper reverse sensor	\$ 80.00	\$ -
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	\$ -
	To putty & spray painting & including touch up paint on accident affected	\$ 880.00	\$ -
	Remove & reinstall Rh / Lh Tailgate Glass to facilitate repairs	\$ 180.00	\$ -
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 120.00	\$ -

Total Parts & Labour of estimate for damaged vehicle

\$ 9,845.70

Total amount in Lump Sum Basis for repaired vehicle

\$ 6,400.00

SDLS: Six Thousand Four Hundred Only



M/s Liu's Brother Auto Engrg Wks

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Jun 2018 Edit Reg		11 Jun 2018 00:00 Edit Adj Rpt	S\$6,400.00 Edit Estimates	S\$6,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TENG JUIN YAN , ID: S8113423E								
Main Claimant:	GOLDBELL LEASING PTE LTD , Co. Reg. No.: 199001196N								
Vehicle Reg. No.:	GBC7569R	Date of Loss:	26/05/2018 19:00 - :59 [55 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0850161667SG	Policy/Cover Note No.:	1700092495 (Comprehensive) Coverage: 08/12/2017 - 07/12/2019						
Vehicle Reg. No. (Insured):	SJH6661S	Policy No. (Claimant):	D-17087422MFCV						
		Excess:							
Repairer:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 21/06/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBC7569R (0850161667SG)
[SJH6661S]**

TP














































GOLDBELL LEASING PTE LTD

May 26 2018 7:00PM

[TENG JUIN YAN]

Liu's Brother Auto Engineering Workshop

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	31/07/18 11:06	Video - Accident <small>From: OD - Reg. No: SJH6661S, Claimant: TENG JUIN YAN</small>	Load AVI	
Letters/Correspondences				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	
Photos/Images				
			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/06/18 17:47	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	11/06/18 17:47	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
3	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
4	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
5	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
6	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
7	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
8	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
9	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
10	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
11	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
12	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
13	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
14	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
15	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
16	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
17	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
18	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
19	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
20	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
21	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
22	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
23	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
24	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
25	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
26	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
27	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
28	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
29	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>
30	11/06/18 17:47	General View	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
31	11/06/18 17:47	General View	 Load JPG	<input checked="" type="checkbox"/>
32	11/06/18 17:47	General View	 Load JPG	<input checked="" type="checkbox"/>
33	11/06/18 17:47	General View	 Load JPG	<input checked="" type="checkbox"/>
34	11/06/18 17:47	General View	 Load JPG	<input checked="" type="checkbox"/>
35	11/06/18 17:47	General View	 Load JPG	<input checked="" type="checkbox"/>
36	11/06/18 17:47	General View	 Load JPG	<input checked="" type="checkbox"/>
37	11/06/18 17:47	General View	 Load JPG	<input checked="" type="checkbox"/>
38	11/06/18 17:47	General View	 Load JPG	<input checked="" type="checkbox"/>
39	11/06/18 17:47	General View	 Load JPG	<input checked="" type="checkbox"/>
40	11/06/18 17:47	General View	 Load JPG	<input checked="" type="checkbox"/>
41	11/06/18 17:47	General View	 Load JPG	<input checked="" type="checkbox"/>
42	11/06/18 17:47	General View	 Load JPG	<input checked="" type="checkbox"/>
43	11/06/18 17:47	General View	 Load JPG	<input checked="" type="checkbox"/>
44	11/06/18 17:47	General View	 Load JPG	<input checked="" type="checkbox"/>
45	11/06/18 17:47	General View	 Load JPG	<input checked="" type="checkbox"/>
46	11/06/18 17:47	General View	 Load JPG	<input checked="" type="checkbox"/>
47	11/06/18 17:47	General View	 Load JPG	<input checked="" type="checkbox"/>
48	11/06/18 17:47	General View	 Load JPG	<input checked="" type="checkbox"/>
49	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	12/06/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	26/06/18 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	26/06/18 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	26/06/18 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	26/06/18 16:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/06/18 17:28	TP GIA REPORT	 Load PDF	
2	28/07/18 10:04	TP ESTIMATE_MARKED	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/06/18 09:57	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJH6661S (Insd veh)	Model:	FIAT DOBLO 1.3 D SX
	GBC7569R (TP veh)		CARGO (M)
Date of Accident:	26/05/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	: \$	9,845.70		
Final Repair Cost	: \$	6,400.00		
Loss of Use	: \$	360.00		6.00 days at \$60.00 per day
Rental (if any)	: \$	0.00		days
LTA / GIA Search Fee	: \$	0.00		
Others:	: \$	0.00		
	: \$			
Final Settlement Sum	: \$	6,760.00		

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Liu's Brother Auto Engineering Workshop	: \$	6,760.00
2)		: \$	

JOANNE LEE KHANG MIN

27 Aug
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18010612/UPB3Q2

Date: 27/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1700092495

Claimant Vehicle
No : GBC7569R

Insured Vehicle No : SJH6661S

Date of Loss: 26/05/2018

Nature of Claim:

TP

Claim No: 0850161667SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

GBC7569R

Make & Model:

FIAT DOBLO, 1.3 D SX Cargo (M)

Engine No:

263A20005067589

Reg. Date:

16/10/2013 (Man. Year: 2013)

Chassis No:

ZFA26300006101433

Colour:

White

Odometer:

79088 km

Engine Capacity:

1248 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

185/65 R15

Rear Tyre Size:

185/65 R15

Front Left Side:

Trangle 6 mm

Rear Left Side:

Trangle 6 mm

Front Right Side:

Trangle 6 mm

Rear Right Side:

Trangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,585.70	6,160.98	1,424.72	18.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,880.00	380.00	16.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,845.70	8,040.98	1,804.72	18.33
Approved Total (Overridden) (S\$)		6,400.00		
Nett Amount (S\$)	9,845.70	6,400.00	3,445.70	35.00
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
Nett Liability (S\$)		6,760.00		

INSPECTION

Date of Assignment:

11/06/2018

Date Inspected:

11/06/2018 Inspected At:

Liu's Brother Auto Engineering Workshop
(HQ)
BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO
BAY @ KAKI BUKIT
Singapore 417883

Estimated Period of Repair:

5.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH TAILGATE	Badly Dented	2,156.30 F	*2,156.30 FL
2	1		*REAR LH TAILGATE OUTER GARNISH	Cut	369.80 F	*369.80 FL
3	1		*REAR LH TAILGATE 70KM/H STICKER	Necessary	12.00 FS	*10.00 FS
4	1		*REAR LH TAILGATE INNER LOWER LOCK	Twisted	192.90 F	*192.90 FL
5	1		*REAR LH TAILGATE SEALANT	Necessary	50.00 FS	*40.00 FS
6	1		*REAR RH TAILGATE	Badly Dented	1,895.90 F	*1,895.90 FL
7	1		*REAR RH TAILGATE OUTER GARNISH	Not Necessary	321.80 F	*- FL
8	1		*REAR RH TAILGATE 6PAX STICKER	Necessary	12.00 FS	*10.00 FS
9	1		*REAR RH TAILGATE SEALANT	Necessary	50.00 FS	*40.00 FS
10	1		*REAR BUMPER	Dented / Deformed	627.00 F	*627.00 FL
11	1		*SET REAR BUMPER CLIPS	Necessary	65.00 F	*50.00 FL
12	1		*REAR BUMPER TOP PROTECTOR	Necessary	185.00 F	*185.00 FL
13	1		*REAR BUMPER BEAM	Bent	475.30 F	*475.30 FL
14	2		*REAR BUMPER SIDE HOLDER	Necessary	130.00 F	*130.00 FL
15	1		*SET REAR BUMPER SIDE HOLDER CLIPS	Repeated	45.00 FS	*- FS
16	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
17	1		*REAR END PANEL	Dented/Bent	430.00 F	*430.00 FL
18	1		*REAR END PANEL GARNISH	Not Necessary	347.70 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,585.70	6,812.20
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	651.22
Total Parts (\$\$)	7,585.70	6,160.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING &ELECTIRCAL COMPONENT FOR PROPER FUNCTION	New	50.00	30.00
2	REMOVE AND REFIX REAR RH/LH TAILGATE COMPONENTS	New	150.00	120.00
3	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	80.00	50.00
4	LABOR FOR PANEL BEATING,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	800.00	600.00
5	TO PUTTY &SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	880.00	800.00
6	REMOVE &REINSTALL RH/LH TAILGATE GLASS TO FACILITATE REPAIRS	New	180.00	180.00
7	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	120.00	100.00
Gross Labour Cost (S\$)			2,260.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >