

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@ymail.com

Invoice/Ref No: GBC7569R180526

Estimate

Customer

Name: AIG Asia Pacific Insurance Pte Ltd

Date: 08-06-18

Address: Motor Claims Department

Vehicle No: GBC7569R

78 Shenton Way #07-16

Model/Make: Fiat Doblo Cargo

AIG Building

Singapore 079120

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Lh Tailgate <i>3015.00</i>	\$ 2,156.30	
2	Tailgate Outer Garnish <i>647</i>	\$ 369.80	
3	Tailgate "70 KM/H" Sticker <i>neu</i>	\$ 12.00	SN 105.~
4	Tailgate Inner Lower Lock <i>neu</i>	\$ 192.90	
5	Tailgate Sealant <i>neu</i>	\$ 50.00	SN 405.~
6	Rear Rh Tailgate <i>3015.00</i>	\$ 1,895.90	
7	Tailgate Outer Garnish <i>neu</i>	\$ 321.80	
8	Tailgate "6 PAX" Sticker <i>neu</i>	\$ 12.00	SN 105.~
9	Tailgate Sealant <i>neu</i>	\$ 50.00	SN 405.~
10	Rear Bumper <i>neu</i>	\$ 627.00	
11	Bumper Clips 1 set <i>neu</i>	\$ 65.00	SN 505.~
12	Bumper Top Protector <i>neu</i>	\$ 185.00	
13	Bumper Beam <i>neu</i>	\$ 475.30	
14	Bumper Side Holder 02 pcs (@ S\$65.00) <i>neu</i>	\$ 130.00	
15	Bumper Side Holder Clips 1 set <i>Repld</i>	\$ 45.00	SN α
16	Bumper Reverse Sensor <i>shut</i>	\$ 220.00	SN 2005.~
17	End Panel <i>neu</i>	\$ 430.00	
18	End Panel Garnish <i>neu</i>	\$ 347.70	
	To check all wiring & electrical component for proper function	\$ 50.00	30
	Remove and refix rear Rh/Lh tailgate components	\$ 150.00	120
	Remove and refix rear bumper reverse sensor	\$ 80.00	50
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	600
	To putty & spray painting & including touch up paint on accident affected	\$ 880.00	800
	Remove & reinstall Rh / Lh Tailgate Glass to facilitate repairs	\$ 180.00	100
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 120.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 9,845.70

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engng Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-64622

S-81498

S.N-350

146-1880

804588

Not Allowed

1/5 26400

11/6/18
5 day.