

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 28 Jun 2018

Preliminary Advice

Vehicle No	: SGS665Z	Accident Date	: 03/06/2018
Make	: AUDI A3	Policy No.	: 1700078903
Assignment Date	: 11/06/2018	Excess	: S\$600.00
Date of Inspection	: 11/06/2018	Est. Duration of Repair	: 21 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion & undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	109,883.00
Revised Amount	:S\$	79,979.00 include supplementary
Check Items (Estimated)	:S\$	10,749.00
Total	:S\$	90,728.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	119,999.00
Pre-Accident Value	:S\$	110,000.00
COE / PARF Rebate	:S\$	49,278.00
Salvage Value	:S\$	
Margin for Repair	:S\$	70,721.00 (NEW CAR VALUE MINUS RESIDU 60,722.00 (MARKET VALUE MINUS RESIDU/

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER ASKING REPAIR COST \$ 63,000.00