

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 199802965G
CHARIOT TRAVELS PTE LTD
NO

SINGAPORE
TEL : FAX :
PH : 90266857
ATTN :

ESTIMATE BILL

Number : EB00004854
Date : 08/06/2018
Case No : AD00009774
Vehicle No : PC121D
Chassis : JTFST22P800009400
Year of Mfr : 2010
Policy No
Model : TOYOTA HIACE

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT BUMPER <i>D.S</i>	1.0	727.80	25	545.85
2	FRONT BUMPER RETAINER LH <i>one</i>	1.0	127.91	25	95.93
3	HEADLAMP LH <i>Scr</i>	1.0	757.14	25	567.86
4	FRONT BUMPER FOGLAMP COVER LH	1.0	87.60	25	65.70
5	FRONT STEP PANEL GARNISH LH <i>ground</i>	1.0	189.52	25	142.14
6	FRONT GRILLE <i>11</i>	1.0	598.14	25	448.61
List Price - Parts Sub Total					1,866.09
7	FRONT DOOR LH - REPAIR	1.0	<i>2 X</i>		
Special Nett Price - Parts Sub Total					0.00
Parts Total					1,866.09
8	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	700.00	0 <i>300</i>	700.00
9	SPRAY PAINT ON THE AFFECTED AREAS	1.0	700.00	0 <i>300</i>	700.00
10	ANTI-RUST COATING	1.0	120.00	0 <i>11 X</i>	120.00
11	WIRING	1.0	40.00	0 <i>20</i>	40.00
Labour 1 Sub Total					1,560.00
SINGAPORE DOLLARS : THREE THOUSAND SIX HUNDRED SIXTY-FIVE AND CENTS NINETY-TWO ONLY					
Less Excess					0.00
SUBTOTAL					3,426.09
GST 7.00%					239.83
TOTAL					3,665.92

Date of accident : 04/05/2018 12:50 PM Place of accident : JUNCTION OF MARINA COASTAL DR/CENTRAL BOULEVARD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

LKK Auto Consultants hence notify
the Rep of the following:
• To resurvey before/after spray painting
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Stolen item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

CUSTOMER SIGNATURE

Date: _____

AUTHORISED SIGNATURE