

ESTEEM PERFORMANCE PTE LTD


**ESTEEM
PERFORMANCE**

 Blk 5039 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569596.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLX 3246 U

Parts (a) Cost / List Price Items	\$	4,265.38
Plus/Less 25%	\$	1,066.35
Total of Cost / List	\$	3,199.04
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items		
Total Parts Cost	\$	3,199.04
Labour	\$	3,010.00
Total	\$	6,209.04

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

 Acknowledged by Repairer
 Signature:
 Date:

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

 (a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

 (c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor :

Date: 10/7/18


**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE. LTD.

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

 Vehicle No. : **SLX 3246 U**
 Make & Model : **TOYOTA PRIUS**
 Chassis No : **ZVW508036422**

 Submit By : **Carmen Lim**
 Year Manufacture : **2016**
 Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front door <i>RL</i>	1	\$1,226.70		X
2	LH front door hinge top <i>RL</i>	1	\$78.34		X
3	LH front door hinge bottom <i>RL</i>	1	\$78.34		X
4	LH front door weatherstrip <i>SL</i>	1	\$198.49		X
5	LHF door glass outer moulding <i>SL</i>	1	\$122.95		X
6	LH rear door <i>RL</i>	1	\$1,181.75		X
7	LH rear door hinge top <i>RL</i>	1	\$78.34		X
8	LH rear door hinge bottom <i>RL</i>	1	\$78.34		X
9	LH rear door weatherstrip <i>SL</i>	1	\$178.40		X
10	LHR door glass outer moulding <i>SL</i>	1	\$111.61		X
11	LH side skirt <i>SL</i>	1	\$691.47		X
12	LH side skirt clip <i>RL</i>	10	\$45.00		X
13	LH rear hub cap <i>RL</i>	1	\$195.65		✓
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Tel: +65-6484 1221 Fax: +65-6484 7828 Website: www.eesteemperf.com.sg

Vehicle No. : SLX 3246 U Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2016

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.