



RICO 60 AUTO SERVICES PTE. LTD.

Co. Reg. No.: 201807623M

8 Kaki Bukit Avenue 4

Premier @ Kaki Bukit

#02-24, Singapore 415875

Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

Vehicle No.:	GBE 3690 M
Make & Model:	NISSAN NV350
Chassis No.:	JN1MC2E26Z0005390

TRAXA

Vivian

NO.	DESCRIPTION - PARTS	QTY.	PRICE
1	TAILGATE <i>Dented</i>	1	\$ 2,101.40
2	TAILGATE WINDSCREEN MOULDING <i>2</i>	1	\$ 126.30
3	TAILGATE LOGO- NISSAN	1	\$ 77.40
4	TAILGATE EMBLEM- NV 350 <i>NEC</i>	1	\$ 77.40
5	TAILGATE EMBLEM- URVAN	1	\$ 45.60
6	TAILGATE CHROME MOULDING <i>NEC</i>	1	\$ 256.00
7	TAILGATE OUTER HANDLE <i>Not NEC</i>	1	\$ 180.00
8	TAILGATE CHROME MOULDING CYLINDER LOCK <i>Not NEC</i>	1	\$ 152.00
9	TAILGATE LOCK <i>Damaged</i>	1	\$ 228.10
10	TAILGATE INNER LOCK ASSY <i>Not NEC</i>	1	\$ 489.00
11	TAILGATE WEATHER STRIP <i>at</i>	1	\$ 95.00
12	REAR BUMPER <i>Dented</i>	1	\$ 632.70
13	REAR BUMPER SIDE RETAINER L+R <i>NEC</i>	2	\$ 78.00
14	REAR BUMPER BRACKET L+R <i>Not NEC</i>	2	\$ 89.00
15	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 182.60
16	REAR END PANEL <i>Dented</i>	1	\$ 461.10
17	REAR END PANEL TOP SCUFF <i>Dented</i>	1	\$ 198.00
18	REAR FLOOR PANEL <i>Not NEC</i>	1	REPAIR
19	Tail lamp <i>Not NEC</i>	1	\$ 210.00
	4513.60	SUBTOTAL	\$ 5,469.60
	3159.52	LESS 20% <i>30%</i>	\$ 1,093.92

		PARTS TOTAL	\$ 4,375.68	
NO.	SPECIAL NETT	QTY.	PRICE	
1	REVERSE SENSOR <i>Changed</i>	2	\$ 320.00	200
2	REAR BUMPER CLIPS <i>new</i>	10	\$ 100.00	30
3	READ END PANEL SEALANT <i>new</i>	1	\$ 120.00	60
4	REAR FLOOR PANEL BOARD <i>crushed</i>	1	\$ 800.00	300
5	REAR TAILGATE STICKER 70KM/H <i>2 new</i>	1	\$ 50.00	10
6	REAR TAILGATE STICKER 6 PAX <i>610</i>	1	\$ 50.00	10
		SPECIAL NETT TOTAL	\$ 1,440.00	
NO.	LABOUR	QTY.	PRICE	
1	TO R&R ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK AND ALIGN		\$ 1,800.00	700
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA		\$ 1,200.00	80
3	TO RUST PROOF ACCIDENT AFFECTED AREA		\$ 120.00	40
4	TO R&R REAR WINDSCREEN		\$ 300.00	120
5	TO R&R REAR BOOT MECHANISM		\$ 120.00	80
6	TO R&R REAR LUAGGAGE COMPARTMENT		\$ 400.00	40
8	TO R&R REVERSE SENSOR AND CHECK FUNCTION		\$ 120.00	40
16	TO DO WATER LEAK TEST <i>1780</i>		\$ 80.00	40
		LABOUR TOTAL	\$ 4,140.00	
		GRAND TOTAL COST	\$ 9,955.68	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5549.52.

2/5: 4.4K.
06Days