

ASS. REC. BY:

REF:

TM1/

CC3/TM11 8010658/Kgdn 2

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

09 days

Res.: Yes or No

Lum Sum:

1-B-1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S110 5082P

Yr Regn:

12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perant Latitude

c.c

1995

Colour:

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

46756

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL 15 Apr 283240

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N/A / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

8/6/18

D.O.I.

11/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

10/6 File PCR to Catherine.

SHD 5082P - CC3 / A/H 1003387 / K02H4

D/A: 16/11/2010

GBE 7304C - X

12/6/18 @ 1.50pm Email GIA report, police report &amp; estimate to TM1.

\* DAMAGES CONSISTENT TO ACCIDENT REPORT

Final fig 874242.86, 9 days (Red 625673.61, 51%)

RECEIVED 29 NOV 2018

Date/Time, File Pass to?



: Prel. Report

11/29/11 11:11



: Final Report

Date/Time, File Return to?

Days Of Repair:

9

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

250

S + RS. \$1

10

Paints

Others

TOTAL

260

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

NER-TP

Lump Sum / I.B.I. (\$

24242.86

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Tuesday, 12 June 2018 1:50 PM  
**To:** motorclaims@tokiomarine.com.sg  
**Cc:** SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 08/06/2018, SHD 5082P (TP VEHICLE), GBE 7304C (OI VEHICLE)  
**Attachments:** SHD5082 PR.pdf; SHD5082 GIA.pdf; SHD5082 EST.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 5082P M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63, SINGAPORE 569111.

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3878K

**Vehicle Details**

Vehicle No.: SHD5082P

Vehicle to be Exported: Yes

Intended De-registration Date: 08 Jun 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2015

Engine No.: M9R8839C003167

Chassis No.: VF1ABL15AUC283240

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 08 Dec 2017

First Registration Date: 08 Dec 2017

Transfer Count: 0

Actual ARF Paid: \$19,998.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 07 Dec 2025

PARF Rebate Amount: \$14,998.00

**Intended COE Rebate Details**

COE Expiry Date: 07 Dec 2025

COE Category: A - Car up to 1600cc &amp; 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$34,159.00

COE Rebate Amount: \$27,327.00

**Total Rebate Amount: \$42,325.00****Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 08 Jun 2018.

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/06/2018 13:27
Date Of Accident	08/06/2018 10:15
Exact Location Of Accident	SIMS AVENUE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD5082P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	WANG FANG KOK
NRIC No	S1617452A
Date Of Birth	17/08/1963
Occupation	OUTDOOR
Date Of Driving Pass	25/11/2009
Driving Experience	8 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96806797
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 607 CLEMENTI WEST STREET 1
	#12-60
Postcode	120607
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BISHAN NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5529999 - FAX NO: 65561905
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE SEE ATTACHED POLICE REPORT T/20180608/2050

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE7304C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	THIA SENG CHONG
NRIC/Passport Number	S0569732H
Contact Number	98369998
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name WANG FONG KOK

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHD5082P

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

**SKETCH PLAN**


**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please See attached Police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





**SINGAPORE  
POLICE FORCE**



T/20180608/2050

3 of 3

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999

Report No. T/20180608/2050

## CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 2 REEMA KAUR SANDHU

Signature Of Informant:

8/6/18

NAN/G

Signature Of Interpreter:

Not applicable

Date/Time:

08/06/2018 12:54

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 YEO KIA HUAT

Contact No.: 65476325

Classification Of Case:

SINGAPORE  
POLICE FORCE

SN 051

Authentication Stamp

NP168

SIGNATURE

## POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180608/2050

2 of 3

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999

Report No. T/20180608/2050

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	WANG FANG KOK	ID No.	S1617452A
Related Vehicle	SHD5082P (Car)	Contact No.	96806797
Hospital/Clinic	HORIZON MEDICAL CENTRE	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	08/06/2018	Date Discharge	08/06/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight
<b>Driver</b>			
Name	THIA SENG CHONG	ID No.	S0569732H
Related Vehicle	NIL	Contact No.	98369998
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 08/06/2018 at about 10.15am, I was driving my taxi (SHD5082P) and was at the T-Junction of Sims Avenue when the traffic light turned red as such I came to a stop. Suddenly, I felt a strong impact because a lorry (GBE7304C) had hit my taxi from the rear. The impact caused my taxi to be pushed forward and the entire rear portion is damaged.

I wish to state that there were no passenger in my taxi at that time. I later felt pain as such I visited the clinic and received 5 days of MC.

I wish to state that I have an in-car camera installed. The lorry is from Teong Theng Company 369 Joo Chiat Road.

That's all.

## POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180608/2050

1 of 3

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999

Report No. T/20180608/2050

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/06/2018 12:54		Vide Report No.:		Station Diary No.: 103	
<b>Informant's Particulars</b>					
Name of Informant: WANG FANG KOK			Address: APT BLK 607 CLEMENTI WEST STREET 1 #12-60 SINGAPORE 120607		
ID Type / ID No.: NRIC NO / S1617452A			Contact No.: Home/Office: Mobile: 96806797		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 54	Date of Birth: 17/08/1963	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: TAXI DRIVER			Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:

<b>General Information of the Accident</b>				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 08/06/2018 10:15	Type of Location: T-Junction
Location: Along Road 1 KALLANG ROAD  T JUNCTION OF SIMS AVENUE Lamp Post Number: 21				
Weather: Clear		Road Surface: Wet	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBE7304C	Lorry					0
SHD5082P	Car	RENAULT		Red	Slightly Damaged	0

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5082P**

AAD1806-077

*Not Authorised**Reserve B4 paint**824242.86*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHD 5082P**

VF1ABL15AUC283240

RENAULT

LATITUDE

8.6.2018

**TOKIO MARINE****PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>R</i> 1,108.46	—
2	1 BUMPER LOWER REAR	\$	<i>CM</i> 768.84	—
3	1 BUMPER BRACKET CTR REAR	\$	<i>CM</i> 113.47	—
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Di</i> 135.97	—
5	1 BUMEP R RETAINER RH REAR	\$	<i>Di</i> 44.99	—
6	1 BUMPER REFLECTOR RH	\$	<i>CM</i> 43.61	—
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	<i>Sn</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>B</i> 777.52	—
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>Di</i> 225.95	—
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>B</i> 225.95	—
13	1 BOOT REAR	\$	<i>B</i> 2,872.68	—
14	1 BOOT FINISHER	\$	<i>CM</i> 470.06	—
15	1 BOOT WHEATERSTRIP	\$	<i>Di</i> 323.05	—
16	1 BOOT REFLECTOR LAMP LH	\$	<i>CNA</i> 493.35	—
17	1 BOOT REFLECTOR LAMP RH	\$	<i>CNA</i> 493.35	—
18	1 BOOT BADGE 'RENAULT'	\$	<i>R</i> 225.36	—
19	1 BOOT BADGE	\$	<i>R</i> 225.36	—
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08	X
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08	X
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	X
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	X
24	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45	X
25	1 BOOT SWITCH	\$	<i>Sn</i> 168.13	X
26	1 BOOT LOCK	\$	<i>Di</i> 202.67	—
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	X
28	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	X
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	X

# Trans-cab Auto Services Pte Ltd

AAD1806-077

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

## SHD 5082P

- 30 1 DOOR PANEL REAR LH
- 31 1 FENDER PANEL INNER TRIM REAR LH
- 32 1 FENDER PANEL REAR LH
- 33 1 WHEELARCH REAR LH
- 34 1 FENDER PANEL INNER TRIM REAR RH
- 35 1 FENDER PANEL REAR RH
- 36 1 WHEELARCH REAR RH
- 37 1 TAILLAMP RH
- 38 1 TAILLAMP PANEL RH
- 39 1 TAILLAMP LH
- 40 1 TAILLAMP PANEL LH
- 41 1 OUTER PANEL REAR (End Panel)
- 42 1 OUTER PANEL REAR (End Panel)TRIM
- 43 1 SPARE WHEEL PANEL (Luggage Floor Panel)
- 44 1 SPARE WHEEL PANEL TRIM
- 45 1 EXHAUST REAR
- 46 1 EXHAUST CAP REAR
- 47 1 FUEL FLAP L70Y

\$	R	2,844.66	X
\$	Jun	671.45	X
\$	R	3,299.13	X
\$	Jun	543.47	X
\$	Net for	671.45	✓
\$	But	3,299.13	✓
\$	Jun	543.47	X
\$	CM	552.55	—
\$	R	986.70	—
\$	mg CM	552.55	✓
\$	R	986.70	X
\$	R	1,471.77	—
\$	CM	404.56	—
\$	R	2,189.88	X
\$	Jun	612.21	X
\$	R	7,489.05	— 5200 SN
\$	R	230.49	—
\$	Jun	343.57	X
<b>TOTAL</b>	<b>\$</b>	<b>39,057.17</b>	
<b>10%</b>	<b>\$</b>	<b>3,905.72</b>	
	<b>\$</b>	<b>35,151.45</b>	

## Special Nett

- 1 1SET PARKING AID
- 2 1SET REAR BUMPER CLIP
- 3 1SET BUMPER BRACKET CTR CLIP
- 4 1SET BUMPER BRACKET SIDE CLIP RH RR
- 5 1SET BUMERPR RETAINER RH CLIP RR
- 6 1SET BUMERPR BRACKET SIDE CLIP LH RR
- 7 1SET BUMERPR RETAINER CLIP LH RR
- 8 1SET BUMPER LOWER REAR RIVET
- 9 1SET BUMPER LOWER REAR CLIP
- 10 1 EXHAUST MOUNTING REAR
- 11 1SET BOOT FINISHER CLIP
- 12 1 BOOT STICKER "Trans-cab"
- 13 1 BOOT STICKER "6555-3333"
- 14 1 BOOT INNER TRIM CLIP
- 15 1SET FENDER WHEELARCH REAR RH CLIP

\$	Shan	700.00	Good
\$	nn	66.00	—
\$	nn	33.00	—
\$	nn	10.00	—
\$	nn	20.00	—
\$	nn	10.00	—
\$	nn	20.00	—
\$	nn	22.00	—
\$	nn	66.00	—
\$	nn	17.82	X
\$	nn	24.20	X
\$	nn	30.00	—
\$	nn	30.00	—
\$	nn	45.00	X
\$	nn	35.00	X

## Trans-cab Auto Services Pte Ltd

AAD1806-0 17

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5082P

16 1SET FENDER WHEELARCH REAR LH CLIP	\$	nn 35.00 X
17 1 FENDER INNER TRIM CLIP LH	\$	nn 28.00 X
18 1 FENDER INNER TRIM CLIP LH	\$	nn 28.00 X
19 1 TAILLAMP CLIP RH	\$	nn 5.00 —
20 1 TAILLAMP CLIP LH	\$	nn 5.00 —
21 2 REAR WINDSCREEN SELANT	\$	nn 80.00 40sn
22 1 WINDSCREEN MOULDING	\$	nn 100.00 —
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn 100.00 30sn
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn 385.00 X
25 1 SPARE TYRE	\$	sn 330.00 X

**TOTAL \$ 2,225.02****TOTAL PARTS \$ 37,376.47**

### LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 1700l
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 1200l
To Rust-Proofing Of The Affected Areas.	\$	170.00 90l
To reinstall rear bumper parking sensor.	\$	170.00 60l
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 60l
To repair and realign rear exhaust pipe.	\$	170.00
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 } 80l
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00 X

**Trans-cab Auto Services Pte Ltd****AAD1806-077**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5082P**

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	100/
To supply and re-do rear luggage floor panel insulation padding.	\$	~ 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	120/
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	~ 380.00	X

**TOTAL \$ 12,540.00****Over All Total \$ 49,916.47**

50296.46

**(PART-BY-PART)****Repair Days****20 DAYS**

9 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18010658/KQBN2

Date: 05/12/2018

## REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MU000157
Claimant Vehicle No :	SHD5082P	Insured Vehicle No :	GBE7304C
Date of Loss:	08/06/2018	Nature of Claim:	TP
		Claim No:	M1802928

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHD5082P	Engine No:	M9R8839C003167
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC283240
Reg. Date:	08/12/2017 (Man. Year: 2015)	Odometer:	46756 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,376.46	21,432.86	15,943.60	42.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,920.00	2,810.00	10,110.00	78.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>50,296.46</b>	<b>24,242.86</b>	<b>26,053.60</b>	<b>51.80</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>3,520.75</b>	<b>1,697.00</b>	<b>1,823.75</b>	<b>51.80</b>
<b>Nett Amount (S\$)</b>	<b>53,817.21</b>	<b>25,939.86</b>	<b>27,877.35</b>	<b>51.80</b>

## INSPECTION

Date of Assignment:	13/06/2018	
Date Inspected:	11/06/2018 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
		2, Ang Mo Kio Street 63
		Singapore 569111

Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 Dec 2018)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD5082P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Bent	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Cracked	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Cracked	113.47 FL	*113.47 FL
4	1		*BUMPER BRACKET SIDE RH REAR	Distorted	135.97 FL	*135.97 FL
5	1		*BUMPER RETAINER RH REAR	Distorted	44.99 FL	*44.99 FL
6	1		*BUMPER REFLECTOR RH	Cracked	43.61 FL	*43.61 FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Distorted	225.95 FL	*225.95 FL
12	1		*BUMPER BEAM BRACKET RH REAR	Bent	225.95 FL	*225.95 FL
13	1		*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
14	1		*BOOT FINISHER	Cracked	470.06 FL	*470.06 FL
15	1		*BOOT WEATHERSTRIP	Distorted/Dented	323.05 FL	*323.05 FL
16	1		*BOOT REFLECTOR LAMP LH	Cracked	493.35 FL	*493.35 FL
17	1		*BOOT REFLECTOR LAMP RH	Cracked	493.35 FL	*493.35 FL
18	1		*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1		*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
20	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1		*BOOT HINEG LH	Repair	367.84 FL	*- FL
23	1		*BOOT HINEG RH	Repair	367.84 FL	*- FL
24	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1		*BOOT LOCK	Dented	202.67 FL	*202.67 FL
27	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1		*DOOR PANEL REAR LH	Repair	2,844.66 FL	*- FL
31	1		*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
32	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
33	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
34	1		*FENDER PANEL INNER TRIM REAR RH	Deformed	671.45 FL	*671.45 FL
35	1		*FENDER PANEL REAR RH	Buckled	3,299.13 FL	*3,299.13 FL
36	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
37	1		*TAILLAMP RH	Cracked	552.55 FL	*552.55 FL
38	1		*TAILLAMP PANEL RH	Bent	986.70 FL	*986.70 FL
39	1		*TAILLAMP LH	Mtg Cracked	552.55 FL	*552.55 FL
40	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
41	1		*OUTER PANEL REAR (END PANEL)	Bent	1,471.77 FL	*1,471.77 FL
42	1		*OUTER PANEL REAR (END PANEL) TRIM	Cracked	404.56 FL	*404.56 FL
43	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR	Repair	2,189.88 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			PANEL)			
44	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
45	1		*EXHAUST CAP REAR	Bent	230.49 FL	*230.49 FL
46	1		*FUEL FLAP L70Y	Serviceable	343.57 FL	*- FL
47	1		*EXHAUST REAR	Bent	6,740.15 FS	*5,200.00 FS
48	1		*SET PARKING AID	Shorted	700.00 FS	*600.00 FS
49	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
50	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
51	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
52	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
53	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
54	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
55	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
56	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
57	1		*EXHAUST MOUNTING REAR	Not Necessary	17.82 FS	*- FS
58	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
59	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
60	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
61	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
62	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
63	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
64	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
65	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
66	1		*TAILLAMP CLIP RH	Necessary	5.00 FS	*5.00 FS
67	1		*TAILLAMP CLIP LH	Necessary	5.00 FS	*5.00 FS
68	2		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
69	1		*WINDSCREEN MOULDING	Necessary	100.00 FS	*100.00 FS
70	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	100.00 FS	*30.00 FS
71	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
72	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>40,533.27</b>	<b>23,124.84</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>3,156.81</b>	<b>1,691.98</b>
<b>Total Parts (\$\$)</b>	<b>37,376.46</b>	<b>21,432.86</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	1,100.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,200.00	1,200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	90.00
4	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
5	TO REPAIR AND REALIGN REAR EXHAUST PIPE }	New	170.00	80.00
6	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE }	New	170.00	-
7	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
8	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	100.00
9	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	-
10	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
11	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	120.00
12	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
13	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
14	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
Gross Labour Cost (S\$)			12,920.00	2,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >