

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 12 Jun 2018

## **Preliminary Advice**

Vehicle No	: SJG8855S	Accident Date	: 04/06/2018
Make	: NISSAN X-TRAIL	Policy No.	: PNPV2018-00002858
Assignment Date	: 12/06/2018	Excess	: S\$0.00
Date of Inspection	: 11/06/2018	Est. Duration of Repair	: 6 days
Inspection At	: Tan Chong Motor Sales (HQ) 913 Bukit Timah Road Singapore 589622		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,683.84
Revised Amount	:S\$	4,883.08
Check Items (Estimated)	:S\$	595.76
Total	:S\$	5,478.84
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	119,000.00
COE / PARF Rebate	:S\$	61,076.00
Salvage Value	:S\$	
Margin for Repair	:S\$	57,924.00

### **Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :