

27/04/2015

ASS. REC. BY:

REF:

CS / FCL18010672 / KFD39H

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

CWS

Karen Tan

of

FCI

Date/Time:

12/6/15 @ 11:22am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 9561Y

Insured:

SHC 3986A

at Workshop m/s

Massive Trading

Tel:

91082728

of

Blk 5038 # 01-405 AMK Ind. Park 2

Policy No:

Claim No:

D18004649 MP8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/06/2015

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

12:40pm @ 12/6/15

Person Contacted:

Anthony

Vehicle

IN OUT

Date/Time

Action/Instruction

(✓) Estimate

SLN 9561Y - X

SHC 3986A - X

28/6

11 Lp @ 16,600 Confirm Anthony (Red: 10967.36/39%)

ASS. REC. BY:

REF: 1621

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

13/6 File pass to Catherine, CH not ready

RECEIVED-29 JUN-2018

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to?

11/08/16 Typist

Date/Time: File Return to?



: Prel. Report



: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

: Fuel \$

: Others \$

TOTAL

18x15=270

170+270

50

50

45

45

585

Report Format:

Lump Sum / L.B.I. (\$

TP

16,600

MOTOR SURVEY ASSIGNMENT

Date	11-06-2018	Our Ref No. D18004649MFSH
Accident Date	10-06-2018	Claim Type. Third Party
Insured Vehicle	SHC3986A	Third Party Vehicle. SLN9561Y
Survey Location	Blk 5038 #01-405 Ang mo kio industrial Pk 2	
Contact Person.	ANTHONY	
Contact No.	0/ 91082728	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MASSIVE TRADING & AUTO	Attention. NIL
Cc : TP Solicitor	TEO KENG SIANG LLC	TP Solicitor Fax No. 63335676
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18010672/Ktd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 12-06-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3986A	Veh. Inspected	SLN 9561Y
Policy No.		Coverage (\$)	0.00
Claim No.	D18004649MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	12/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/06/2018	Inspection Date	12/06/2018
Survey held at	BLK 5038 AMK IND PARK 2 #01-405		
Repairer	MASSIVE TRADING & AUTO		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

- 1pc Front bonnet ✓
- 1pc Front bonnet lock ?
- 1pc Front bonnet emblem ✓
- 1pc Front fender o/s ✓
- 1pc Front fender innershield L/H ✓
- 1pc Front fender arch protector ✓
- 1pc Front fender top rubber X
- 2pc Front headlamp assy o/s? ✓
- 1pc Front headlamp H/A unit ?
- 1pc Front headlamp lower bracket ?
- 1pc Front grille ✓
- 1pc Front support panel ?
- 1pc Front support panel top rubber ✓
- 1pc Front air duct centre ✓
- 1pc Front air cleaner assy ?
- 1pc Front bumper ✓
- 1pc Front bumper reinforcement ?
- 1pc Front bumper lower beam ?
- 2pc Front bumper bracket ?
- 1pc Front bumper sponge ?
- 1pc Front tow cover ✓
- 2pc Front bumper fog lamp ✓ o/s
- 2pc Front bumper fog lamp garnish o/s ✓
- 2pc Front bumper fog lamp garnish top ✓ MS
- 2pc Front bumper side retainer ✓
- 1pc Front bumper lower grille ✓
- 1pc Front bumper lower garnish ✓
- 2pc Front bumper lower side garnish ✓
- 2pc Front bumper sensor centre ?
- 1pc Front engine lower cover ?
- 2pc Front bumper side sensor ✓

- 1pc Air Gun Conduces. ?
- 1pc Radiator Assy X
- 1pc Radiator Fan cooling ?
- 2pc Radiator Fan cooling lower side garnish ?
- 1pc No plate garnish ✓
- 2pc Wiper side moulding 4 ds
- 1pc Radiator Fan Assy. ?
- 1pc Front c/h chassis bracket. ?

S Nxt.

- 1pc Front no plate - 45.00 ✓
- 50pc Clip - 23.00 - 60.00 ✓

Labour

- Panel bent - 1600
- Spray paint - 1600
- Wing - 60.00
- Air Gun - 240.00
- Sensor reset - 280.00
- Wheel Alignment - 80.00
- Chassis bent - 280.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/06/2018 11:29
Date Of Accident	10/06/2018 17:45
Exact Location Of Accident	UPPER SERANGOON CRESCENT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN9561Y
Insured/Policyholder	
Name Of Registered Owner	CHOONG BUAT KEN
NRIC No	S0117509B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98306202
Alternative Phone No	OTHERS-98306202

Vehicle Particulars

Manufacturer	BMW
Model	X1 SDRIVE18i-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN828952
Cover Note Number	23/05/2017 - 22/05/2019

Driver

Name of Driver	CHOONG BUAT KEN
NRIC No	S0117509B
Date Of Birth	20/07/1948
Occupation	INDOOR
Date Of Driving Pass	30/04/1973
Driving Experience	45 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98306202
Fax Number	
Contact Number	OTHERS-98306202
Email Address	NOEMAIL

Address	18 STRATTON DRIVE
Postcode	806877
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC3986A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	SOO YAP FOOK
NRIC/Passport Number	S1844492E
Contact Number	96868303
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	CHOONG BUAT KEN
Approximate Age	

Injuries Sustain	NECK PAIN
Injured person in which vehicle?	SLN9561Y
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigation relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

Date of accident: 10.6.2018 Time: 5.45 pm Location: Upper Serangoon Crescent
 My Vehicle A: SLN 9561Y Vehicle B: SHC 3986A Vehicle C: -

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 10.6.2018 at 5.45pm, I was driving along Upper Serangoon Crescent towards Upper Serangoon Rd. At this junction, vehicle B suddenly from my left make a sharp right turn and cut into my lane. I immediately applied my brake to avoid the collision but failed. Later an ambulance arrived at the scene.

Car B - Soo Yap took
 51844420
 9686 9302

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop: MASSIVE TRADING
 Email address: MASSIVE TRADING@gmail.com
 & myself:
 Email address:

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Company's Representative's Signature
 Name:
 NRIC/FIN No.:

MASSIVE TRADING COMPANY

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
H/P 91082728

Vehicle No : SLN 9561 Y
Make : BMW X1
Year : 2017

Not Notarized
21 Pm @ 16,400h
Resurvey After Pains
8 days

Estimate Cost Of Repair

QTY	DESCRIPTION	UNIT PRICE	TOTAL PRICE	REMARKS
1 pc	Front bonnet			
2 pcs	Front bonnet lock			
1 pc	Front bonnet emblem			
2 pcs	Front fender			
1 pc	Front n/s fender innershield			
1 pc	Front n/s fender arch protector			
2 pcs	Front fender top rubber			
2 pcs	Front headlamp assy			
2 pcs	Front headlamp HID unit			
2 pcs	Front headlamp lower bracket			
2 pcs	Front grille			
1 pc	Front support panel			
1 pc	Front support strut bar			
1 pc	Front support panel top rubber			
1 pc	Front center air duct			
1 pc	Front air cleaner assy			
1 pc	Front bumper			
1 pc	Front bumper reinforcement			
1 pc	Front bumper lower beam			
2 pcs	Front bumper bracket			
2 pcs	Front bumper side retainer			
1 pc	Front bumper sponge			
1 pc	Front bumper tow cover			
2 pcs	Front bumper fog lamp			
2 pcs	Front bumper fog lamp grille			
2 pcs	Front bumper fog lamp grille top moulding			
1 pc	Front bumper lower grille			
1 pc	Front bumper lower garnish			
2 pcs	Front bumper lower side garnish			
2 pcs	Front bumper center sensor			
2 pcs	Front n/s bumper corner sensor			
1 pc	Front lower beam (inner)			
1 pc	Front lower beam bracket			

SLN 9561 Y

1 pc	Front engine lower cover	✓
1 pc	Air con condenser	?
1 pc	Inner cooler assy	refer photo
1 pc	Radiator assy	refer photo
1 pc	Radiator fan cowling	✓
1 pc	Radiator fan assy	X
2 pcs	Radiator fan cowling lower side garnish	? X
1 pc	Front no plate holder	✓
2 pcs	Wiper side moulding	o/s X
1 pc	Front n/s chassis bracket	? X

balance b/f \$20,287.03 17622.29

cor	\$255.75	✓
Ru	\$1,288.85	✓
Ru	\$854.75	✓
Ru	\$855.90	✓
cas	\$225.70	✓
Sm	\$935.95	
Sm	\$95.10	
nd	\$190.20	
nd	\$75.20	
dis	\$167.10	✓
R	\$205.10	
	\$334.20	✓ 107.10
	\$410.20	
	\$25,713.73	21,345.54
Less 10 %	\$2,571.37	2,134.55
	\$23,142.36	19,210.99

S. Nett Item

1 pc	Front no plate	✓
20 pcs	Clip	✓

\$45.00	✓
\$3.00	✓
\$60.00	✓
\$105.00	105.00

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,600.00 900

To putty & spray paint on accident affected portion.

\$1,600.00 1000

Check/reconnect wiring & to focus front headlamp.

\$60.00 201

Remove/refit air con condenser, fan including replenish 134 gas to facilitate repair.

\$240.00 1001

Remove/renew bumper sesor and to reset same.

\$280.00 1201

To respray anit rust proofing.

\$180.00 301

Check and realign wheel alignment

~ \$80.00 X

To conduct chassis alignment

~ \$280.00 X

Total \$27,567.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18010672/Ktd3q2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 03-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3986A	Veh. Inspected	SLN 9561Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004649MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	12/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. X1 (A)	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBAHS120805H48854	Colour	METALLIC GREY	
Odometer	10854	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	PIRELLI	9 mm	
L/H Front Tyre	225/50 R18	PIRELLI	9 mm	
R/H Rear Tyre	225/50 R18	PIRELLI	9 mm	
L/H Rear Tyre	225/50 R18	PIRELLI	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/06/2018	Inspection Date	12/06/2018	
Survey held at	BLK 5038 AMK IND PARK 2 #01-405			
Repairer	MASSIVE TRADING & AUTO			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 9561Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	BENT	1,882.45	1,882.45
2	FRONT BONNET LOCK @\$255.60	TO REPAIR SEE LABOUR	511.20	-
1	FRONT BONNET EMBLEM	NECESSARY	95.60	95.60
2	FRONT FENDER @\$744.69	N/S TO REPAIR SEE LABOUR / O/S BUCKLED	1,489.38	744.69
1	FRONT N/S FENDER INNERSHIELD	CRACKED	185.60	185.60
1	FRONT N/S FENDER ARCH PROTECTOR	DISTORTED	205.70	205.70
2	FRONT FENDER TOP RUBBER @\$155.20	SERVICEABLE	310.40	-
2	FRONT HEADLAMP ASSY @\$2866.70	MTG CRACKED	5,733.40	5,733.40
2	FRONT HEADLAMP HID UNIT @\$455.60	N/S DENTED	911.20	455.60
2	FRONT HEADLAMP LOWER BRACKET @\$165.10	TO REPAIR SEE LABOUR	330.20	-
2	FRONT GRILLE	CRACKED	418.60	418.60
1	FRONT SUPPORT PANEL	BENT	955.75	955.75
1	FRONT SUPPORT STRUT BAR	BENT	325.70	325.70
1	FRONT SUPPORT PANEL TOP RUBBER	CUT	187.60	187.60
1	FRONT CENTER AIR DUCT	CRACKED	265.60	265.60
1	FRONT AIR CLEANER ASSY	SERVICEABLE	446.65	-
1	FRONT BUMPER	BENT	1,050.10	1,050.10
1	FRONT BUMPER REINFORCEMENT	BENT	567.70	567.70
1	FRONT BUMPER LOWER BEAM	BENT	285.70	285.70
2	FRONT BUMPER BRACKET @\$176.20	N/S BENT	352.40	176.20
2	FRONT BUMPER SIDE RETAINER @\$85.10	DISTORTED	170.20	170.20
1	FRONT BUMPER SPONGE	CRACKED	175.20	175.20
1	FRONT BUMPER TOW COVER	DENTED	75.10	75.10
2	FRONT BUMPER FOG LAMP @\$376.20	N/S MTG CRACKED	752.40	376.20
2	FRONT BUMPER FOG LAMP GRILLE	N/S CRACKED	334.40	167.10
2	FRONT BUMPER FOG LAMP GRILLE TOP MOULDING @\$155.20	N/S NECESSARY	310.40	155.20
1	FRONT BUMPER LOWER GRILLE	CRACKED	187.20	187.20

Report Ref No. CS/FCI18010672/Ktd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER LOWER GARNISH	CRACKED	197.60	197.60
2	FRONT BUMPER LOWER SIDE GARNISH @\$197.10	DISTORTED	394.20	394.20
2	FRONT BUMPER CENTER SENSOR @\$305.10	SHORTED (1 PCS ONLY)	610.20	305.10
2	FRONT N/S BUMPER CORNER SENSOR @\$284.60	SHORTED	569.20	569.20
1	FRONT LOWER BEAM (INNER)	BENT	297.60	297.60
1	FRONT LOWER BEAM BRACKET LH	BENT	255.70	255.70
1	FRONT ENGINE LOWER COVER	CRACKED	255.75	255.75
1	AIR CON CONDENSER	PUNCTURE	1,288.85	1,288.85
1	INNER COOLER ASSY	PUNCTURE	854.75	854.75
1	RADIATOR ASSY	PUNCTURE	855.90	855.90
1	RADIATOR FAN COWLING	CRACKED	225.70	225.70
1	RADIATOR FAN ASSY	SERVICEABLE	935.95	-
2	RADIATOR FAN COWLING LOWER SIDE GARNISH @\$95.10	SERVICEABLE	190.20	-
1	FRONT NO PLATE HOLDER	DENTED	75.20	75.20
2	WIPER SIDE MOULDING @\$167.10	O/S CUT	334.20	167.10
1	FRONT N/S CHASSIS BRACKET	TO REPAIR SEE LABOUR	410.20	-
	LESS 10% DISCOUNT		-2,626.70	-2,058.48
			23,640.33	18,526.36
	SPECIAL NETT ITEMS			
1	FRONT NO PLATE (SN)	BENT	45.00	45.00
20	CLIP @\$3.00 (SN)	NECESSARY	60.00	60.00
			105.00	105.00
	LABOUR			
	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING ,WELDING & CUTTING.INCLUSIVE OF THE REPAIR OF FRONT BONNET LOCK,FRONT FENDER LH,FRONT HEADLAMP LOWER BRACKET AND FRONT N/S CHASSIS BRACKET .		1,600.00	900.00
	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION .		1,600.00	1,000.00
	CHECK /RECONNECT WIRING & TO FOCUS FRONT HEADLAMP .		60.00	20.00

Report Ref No. CS/FCI18010672/Ktd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIT AIR CON CONDENSER ,FAN INCLUDING REPLENISH 134 GAS TO FACILITATE REPAIR.		240.00	100.00
	REMOVE/RENEW BUMPER SENSOR AND TO RESET SAME.		280.00	120.00
	TO RESPRAY ANIT RUST PROOFING .		180.00	30.00
	CHECK AND REALIGN WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO CONDUCT CHASSIS ALIGNMENT .	NOT NECESSARY	280.00	-
			4,320.00	2,170.00
GRAND TOTAL			28,065.33	20,801.36

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				16,600.00
--	--	--	--	-----------

Report Ref No. CS/FCI18010672/Ktd3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.