

ASS. REC. BY:

REF: CS/FCL18010674/Khd3<sup>n2</sup> Special Instruction

From (Person): Calvin ASSIGNMENT (Office)

From (Person): Luruejaw of FCI Date/Time: 12/6/18 @ 11:43am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 1864B Insured: SHA 0518Z

at Workshop m/s: Premier Automotive Tel: 65446682 / 62148880

of 23 changi south ave 2 #03-02

Policy No: \_\_\_\_\_ Claim No: D18004646MPSH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 10/06/2018  
(Client's Record)

CA / REV / REP. / REV 24 HRS cup H.O.V. Endorsement: \_\_\_\_\_

Date/Time: 12:29pm @ 12/6/18 Person Contacted: Gary Vehicle: IN/OUT

| Date/Time | Action/Instruction (✓) Estimate         |              |
|-----------|---|--------------|
|           | SHD 1864B - C03 / AT616001889 / Hljg3n2 | QA: 27012016 |
|           | SHA 518Z - C03 / FCL17021859 / U1bn2    | DA: 13/12/17 |
|           | Pervert thru merimen                    |              |
|           |   |              |
|           |   |              |

108/11/13

Q Insur: Kalvin

REF:

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimate/Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workstop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / .REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHD1864 B Yr Regn: 16 Dec, 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry /  / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1.685...

Colour: Silver A/C:  Insured / Std / NI / NA

Sp. Reading: 35229 T/Radio:  Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNAKM414MFS561756

Gen. Cond: Good /  / Poor / Burnt

Steering: Inorder /  / Jammed / Leaked / Burnt or

Brake: Inorder /  / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD /  / Rim or

Tyre Size: F: 205 / 65 R. 16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Achilles

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 10/6/8 D.O.I. 12/6/8

Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear.

The UIC / Chassis frame / Body Structure affected due to collision.

| Date / Time          | Action / Instruction   |
|----------------------|--|
| 2/6/18               | Check up \$3650 / 3hp.<br>Red: \$2934.40, 45% <span style="float: right;">FCZ<br/>45.</span> |
| RECEIVED 11 JUL 2018 |  |

Date/Time, File Pass to?  : Prell. Report

1) typist  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

|     |
|-----|
| 145 |
| 50  |
| 30  |
| 35  |
|     |
|     |
|     |
| 280 |

Report Format: TP  
Lump Sum / H.B.T: (\$ 3650 )



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |                            |   |
|--|---|----------------------------|---|
| FIRST CAPITAL INSURANCE LTD  |   | Ref : CS/FC118010674/K1rd3 |   |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877  |   | Date : 12-06-2018          |  |
|  |   | Code : FCI2                |   |
| 1. Policy Particulars :- THIRD PARTY CLAIM   |   |                            |   |
| Insured Veh.   | SHA 518Z  | Veh. Inspected             | SHD 1864B   |
| Policy No.   |   | Coverage (\$)              | 0.00  |
| Claim No.  | D18004646MFSH   | Excess (\$)                | 0.00  |
| Assign From  | CWS (LURENE JAW)  | Assign Date                | 12/06/2018  |
| 2. Vehicle Particulars & Condition   |   |                            |   |
| Make & Model   |   | c.c                        | 0   |
| Engine No.   | HIDDEN  | Year of Reg.               |   |
| Chassis No.  |   | Colour                     |   |
| Odometer   | -   | Steering                   |   |
| Brakes   |   | Modification               |   |
| General  |   |                            |   |
| 3. Conditions of Tyres   |   |                            |   |
|  | Size  | Make                       | Balance   |
| R/H Front Tyre   |   |                            | mm  |
| L/H Front Tyre   |   |                            | mm  |
| R/H Rear Tyre  |   |                            | mm  |
| L/H Rear Tyre  |   |                            | mm  |
| 4. Description of Damages  |   |                            |   |
|  |   |                            |   |
| 5. General Information   |   |                            |   |
| Accident Date  | 10/06/2018  | Inspection Date            | 12/06/2018  |
| Survey held at   | PREMIER AUTOMOTIVE SERVICES PTE LTD<br>23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443 |                            |   |
| 5a. Remarks  |   |                            |   |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                            |   |

**MOTOR SURVEY ASSIGNMENT**

|                           |   |                                      |
|---------------------------|---|--------------------------------------|
| <b>Date</b>               | 11-06-2018                                | <b>Our Ref No.</b> D18004646MFSH     |
| <b>Accident Date</b>      | 10-06-2018                                | <b>Claim Type.</b> Third Party       |
| <b>Insured Vehicle</b>    | SHA0518Z                                  | <b>Third Party Vehicle.</b> SHD1864B |
| <b>Survey Location</b>    | 23 CHANGI SOUTH AVENUE 2 #03-02           |                                      |
| <b>Contact Person.</b>    | GOH WEE DEK                               |                                      |
| <b>Contact No.</b>        | 62148880/ 65446682                        | <b>Fax No.</b> 62141511              |
| <b>Survey Type</b>        | WITHOUT PREJUDICE: ACCIDENT NOT REPORTED: |                                      |
| <b>Appointed Surveyor</b> | LKK AUTO CONSULTANTS PTE LTD              |                                      |
| <b>Contact Person</b>     | NA  | <b>Fax No.</b> 68416315              |
| <b>Contact Number.</b>    | NA  |                                      |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                          |                                     |                                |
|--------------------------|-------------------------------------|--------------------------------|
| <b>Cc : Workshop</b>     | PREMIER AUTOMOTIVE SERVICES PTE LTD | <b>Attention.</b> NIL          |
| <b>Cc : TP Solicitor</b> | NA                                  | <b>TP Solicitor Fax No.</b> NA |
| <b>Officer Incharge</b>  | LURENE                              |                                |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241334)



PRI Documents



Close



## PRI Header Details

|                          |   |  |  |                                 |                 |
|--------------------------|---|--|--|---------------------------------|-----------------|
| <b>Claim No</b>          | D18004646MFSH   | <b>Policy No</b>                             | D-18088937MFSH   | <b>Claimant S.No &amp; Name</b> | 1 & PREMIER LTD |
| <b>Workshop Name</b>     | PREMIER AUTOMOTIVE SERVICES PTE LTD<br>(Contact Person : GOH WEE DEK) | <b>Survey Location &amp; Contact Details</b> | 23 CHANGI SOUTH AVENUE 2 #03-02<br><b>Mobile:</b> 65446682 , <b>Phone:</b> 62148880 , <b>Fax:</b> 62141511<br><b>EmailId:</b> WEEDEK.GOH@PREMIERTAXI.COM |                                 |                 |
| <b>Our Surveyor</b>      | LKK AUTO CONSULTANTS PTE LTD  | <b>Instructions To Surveyor</b>              | WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:  |                                 |                 |
| <b>Insured Name</b>      | CITYCAB PTE LTD   | <b>Insured Vehicle No</b>                    | SHA0518Z   | <b>TP Vehicle No</b>            | SHD1864B        |
| <b>PRI Recieved Date</b> | 11-06-2018 07:50:58 PM  | <b>Surveyor Appointed Date</b>               | 12-06-2018 11:42:01 AM   | <b>Surveyor Accept Date</b>     | 12-06-2018 1    |

## Survey Report Upload

|                                    |                      |                             |            |                                |  |
|------------------------------------|----------------------|-----------------------------|------------|--------------------------------|--|
| <b>Surveyor Inspection Date *:</b> | <input type="text"/> | <b>Surveyor Report Date</b> | 12-06-2018 | <b>Upload Survey Report *:</b> | <input type="button" value="Choose File"/> |
|------------------------------------|----------------------|-----------------------------|------------|--------------------------------|--|

## Vehicle Particulars

|                  |   |                       |  |                |  |
|------------------|---|-----------------------|--|----------------|--|
| <b>Make</b>      | <input type="text" value="Please Select Make"/> | <b>Model</b>          | <input type="text" value="Please Select Model"/> | <b>Year</b>    | <input type="text" value="Select Year"/> |
| <b>Chasis No</b> | <input type="text"/>                            | <b>Engine No</b>      | <input type="text"/>                             | <b>Mileage</b> | <input type="text"/>                     |
| <b>Color</b>     | <input type="text"/>                            | <b>Cubic Capacity</b> | <input type="text"/>                             |                |  |

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004646MFSH

Our Ref: CS/FCI18010674/K1rd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 1864B**

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12.06.2018 at the premises of M/s PREMIER AUTOMOTIVE PTE LTD and have the following to report:-

|                          |                       |
|--------------------------|-----------------------|
| Workshop Estimate Amount | : S\$ <u>6,584.40</u> |
| Revised Estimate Amount  | : S\$ <u>3,677.30</u> |
| "Check" Items Amount     | : S\$ <u>929.70</u>   |
| Market Value             | : S\$ <u>-</u>        |
| LTA Reimbursement Value  | : S\$ <u>-</u>        |
| Nett Value               | : S\$ <u>-</u>        |

Description of Damage:

The vehicle sustained damages at rear portion.



Yours faithfully  
KALVIN  
Automotive Assessor

Text size + -

### Enquire Transaction History

#### Transaction History Details

|                                     |                                 |                     |   |
|-------------------------------------|---------------------------------|---------------------|---|
| Log Date/Time:                      | 16 Dec 2014 / 08:45:58          | Receipt No.:        | AACCK001-AX239-141216-000007                  |
| Asset Type:                         | Vehicle                         | Transaction Amount: | \$65,101.00                                   |
| Asset ID:                           | SHD1864B                        | Channel:            | AA Counterless - CYCLE & CARRIAGE KIA PTE LTD |
| Transaction Type:                   | 01.02 Register New Vehicle (AA) |                     |   |
| Business Transaction Reference No.: | 20141216084556522439            |                     |   |

|                       |   |
|-----------------------|---|
| Vehicle No.:          | SHD1864B                                |
| Vehicle Type:         | H10 - Public Transport Taxi (Motor Car) |
| Vehicle Attachment 1: | Air-Con (Taxi)                          |
| Vehicle Attachment 2: | -                                       |
| Vehicle Attachment 3: | -                                       |
| Vehicle Scheme:       | Taxi (Company)                          |

|                             |                      |
|-----------------------------|----------------------|
| First Registration Date:    | 16 Dec 2014          |
| Original Registration Date: | 16 Dec 2014          |
| Vehicle Make:               | KIA                  |
| Vehicle Model:              | OPTIMA 1.7(A) DIESEL |
| Chassis No.:                | KNAGM414MF5561756    |
| Engine No.:                 | D4FDEH311899         |

|                       |             |
|-----------------------|-------------|
| Motor No.:            | -           |
| Trailer Chassis No.:  | -           |
| Propellant:           | Diesel      |
| Passenger Capacity:   | 4           |
| Engine Capacity:      | 1685        |
| Power Rating:         | -           |
| Unladen Weight:       | 1584        |
| Maximum Laden Weight: | 2050        |
| Primary Color:        | Silver      |
| Secondary Color:      | -           |
| Manufacturing Year:   | 2014        |
| Open Market Value:    | \$20,566.00 |
| Minimum PARF Benefit: | \$7,975.00  |

|                                |                      |
|--------------------------------|----------------------|
| PARF Eligibility:              | Y                    |
| No. of Transfer:               | 0                    |
| Effective Ownership Date/Time: | 16 Dec 2014 08:45:58 |
| COE No.:                       | 2014121601001525D    |
| COE Expiry Date:               | 15 Dec 2022          |
| COE Bid Category:              | -                    |
| Actual QP/PQP Paid Amount:     | \$51,668.00          |
| Lifespan Expiry Date:          | 15 Dec 2022          |

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

11-Jun-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1864 B

|       |   |    |                 |
|-------|---|----|-----------------|
| 1 pc  | Boot lid — <i>Best</i>  | \$ | 1,119.00        |
| 1 pc  | Boot lid lock X <i>su</i>                                     | \$ | 99.00           |
| 1 pc  | Bootlid striker X <i>su</i>                                   | \$ | 21.00           |
| 1 pc  | Bootlid emblem — <i>nd</i>                                    | \$ | 27.00           |
| 1 pc  | Bootlid CRDi — <i>nd</i>                                      | \$ | 29.00           |
| 1 pc  | Bootlid rubber weatherstrip X <i>su</i>                       | \$ | 96.00           |
| 1 pc  | Bootlid lower garnish X <i>repair</i>                         | \$ | 290.00          |
| 2 pcs | Bootlid hinges @ \$66.00 X <i>repair</i>                      | \$ | 132.00          |
| 1 pc  | End panel X <i>repair</i>                                     | \$ | 250.00          |
| 1 pc  | End panel garnish ✓ <i>ca</i>                                 | \$ | 74.00           |
| 1 pc  | Spare tyre clamp X <i>su</i>                                  | \$ | 6.00            |
| 1 pc  | Rear bumper — <i>nd</i>                                       | \$ | 696.00          |
| 1 pc  | Rear bumper lower cover — <i>ca</i>                           | \$ | 206.00          |
| 2 pcs | Rear bumper side bracket o/s & n/s @ \$29.00 ✓ <i>ca</i>      | \$ | 58.00           |
| 1 pc  | Rear bumper inner sponge ✓ <i>ca</i>                          | \$ | 114.00          |
| 1 pc  | Rear bumper reinforcement ✓ <i>ca</i>                         | \$ | 607.00          |
| 2 pcs | Rear bumper stay o/s & n/s @ <del>\$53.00</del> ✓ <i>ca</i>   | \$ | 108.00          |
| 2 pcs | Rear bumper reinforcement lower bracket @ \$18.00 ✓ <i>ca</i> | \$ | 36.00           |
| 2 pcs | Rear bumper reinforcement upper bracket @ \$18.00 ✓ <i>ca</i> | \$ | 36.00           |
| 2 pcs | Rear bumper reflector n/s & o/s @ \$46.00 X <i>su</i>         | \$ | 92.00           |
|       |   | \$ | 4,096.00        |
|       | Less 10%  | \$ | 409.60          |
|       |   | \$ | <u>3,686.40</u> |

### S/NETT

|       |   |    |                       |
|-------|---|----|-----------------------|
| 1 set | Rear bumper clips — <i>nd</i>             | \$ | 48.00                 |
| 1 set | End panel inner garnish clips X <i>su</i> | \$ | 30.00                 |
| 1 set | Bootlid lower garnish clips X <i>su</i>   | \$ | 60.00                 |
| 1 set | Bootlid stickers — <i>nd</i>              | \$ | 100.00                |
| 1 set | Reverse sensor — <i>nd</i>                | \$ | <del>280.00</del> 200 |
| 1 pc  | Rear bumper top protector — <i>nd</i>     | \$ | <del>80.00</del> 50   |

11-Jun-18

**ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1864 B**

|  |    |                                   |
|--|----|-----------------------------------|
| Sundry   | \$ | <del>50.00</del> 20 nec           |
| To dismantle / replace reverse sensor to new bumper and reset to the same  | \$ | <del>120.00</del> 20              |
| To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.   | \$ | <del>180.00</del> X <sup>na</sup> |
| To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off <del>the</del> the end panel. Including knock-out, straighten, repair, reshape and adjust of the same, etc. | \$ | <del>1,000.00</del> 600           |
| To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel  | \$ | <del>800.00</del> 720             |
| To apply rustproofing on the repaired and replaced panels.   | \$ | <del>150.00</del> 50              |
|  | \$ | <u>6,584.40</u>                   |

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

Kaiah 10/16/18  
M 12/6/18 1315 hrs  
3 Rep.  
Ys  
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile      |                                     |  |   |
|--|-------------------------------------|--|---|
| FIRST CAPITAL INSURANCE LTD  |                                     | Ref : CS/FCI18010674/K1rd3n2                     |   |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                  |                                     | Date : 11-07-2018                                |  |
|  |                                     | Code : FCI2                                      |   |
| 1. Policy Particulars :- THIRD PARTY CLAIM                             |                                     |  |   |
|  | Insured Veh.                        | SHA 518Z   | Veh. Inspected  |
|  | Policy No.                          | D-18088937MFSH                                   | Coverage (\$)   |
|  | Claim No.                           | D18004646MFSH                                    | Excess (\$)   |
|  | Assign From                         | LURENE   | Assign Date   |
|  |                                     |  | 12/06/2018  |
| 2. Vehicle Particulars & Condition                                     |                                     |  |   |
|  | Make & Model                        | KIA OPTIMA                                       | c.c   |
|  | Engine No.                          | HIDDEN   | Year of Reg.  |
|  | Chassis No.                         | KNAGM414MF5561756                                | Colour  |
|  | Odometer                            | 352129   | Steering  |
|  | Brakes                              | IN ORDER   | Modification  |
|  | General                             | FAIR   | STANDARD ALLOY RIM  |
| 3. Conditions of Tyres   |                                     |  |   |
|  |                                     | Size   | Make  |
|  | R/H Front Tyre                      | 205/65 R16                                       | ACHILLES  |
|  | L/H Front Tyre                      | 205/65 R16                                       | ACHILLES  |
|  | R/H Rear Tyre                       | 205/65 R16                                       | ACHILLES  |
|  | L/H Rear Tyre                       | 205/65 R16                                       | ACHILLES  |
|  |                                     |  | Balance   |
|  |                                     |  | 7 mm  |
| 4. Description of Damages  |                                     |  |   |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.                     |                                     |  |   |
| DAMAGES SEE DETAILS.   |                                     |  |   |
| 5. General Information   |                                     |  |   |
|  | Accident Date                       | 10/06/2018                                       | Inspection Date   |
|  |                                     |  | 12/06/2018  |
|  | Survey held at                      | PREMIER AUTOMOTIVE SERVICES PTE LTD              |   |
|  |                                     | 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443 |   |
| 5a. Remarks  |                                     |  |   |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.                              |                                     |  |   |
| B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.        |                                     |  |   |
| C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                     |  |   |
| 5b. Estimate Days of Repair  |                                     |  |   |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR: |  | 3 Working Days  |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1864B

| Qty                         | Description of Parts                             | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|--|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |  |                      |                           |                   |
| 1                           | BOOT LID   | BENT                 | 1,119.00                  | 1,119.00          |
| 1                           | BOOT LID LOCK                                    | SERVICEABLE          | 99.00                     | -                 |
| 1                           | BOOTLID STRIKER                                  | SERVICEABLE          | 21.00                     | -                 |
| 1                           | BOOTLID EMBLEM                                   | NECESSARY            | 27.00                     | 27.00             |
| 1                           | BOOTLID CRDI                                     | NECESSARY            | 29.00                     | 29.00             |
| 1                           | BOOTLID RUBBER WEATHERSTRIP                      | SERVICEABLE          | 96.00                     | -                 |
| 1                           | BOOTLID LOWER GARNISH                            | TO REPAIR SEE LABOUR | 290.00                    | -                 |
| 2                           | BOOTLID HINGES @\$66.00                          | TO REPAIR SEE LABOUR | 132.00                    | -                 |
| 1                           | END PANEL  | TO REPAIR SEE LABOUR | 250.00                    | -                 |
| 1                           | END PANEL GARNISH                                | CRACKED              | 74.00                     | 74.00             |
| 1                           | SPARE TYRE CLAMP                                 | SERVICEABLE          | 6.00                      | -                 |
| 1                           | REAR BUMPER                                      | DEFORMED             | 696.00                    | 696.00            |
| 1                           | REAR BUMPER LOWER COVER                          | CRACKED              | 206.00                    | 206.00            |
| 2                           | REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00      | CRACKED              | 58.00                     | 58.00             |
| 1                           | REAR BUMPER INNER SPONGE                         | TORN                 | 114.00                    | 114.00            |
| 1                           | REAR BUMPER REINFORCEMENT                        | CRACKED              | 607.00                    | 607.00            |
| 2                           | REAR BUMPER STAY O/S & N/S                       | BENT                 | 108.00                    | 108.00            |
| 2                           | REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00 | CRACKED              | 36.00                     | 36.00             |
| 2                           | REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00 | CRACKED              | 36.00                     | 36.00             |
| 2                           | REAR BUMPER REFLECTOR N/S & O/S @\$46.00         | SERVICEABLE          | 92.00                     | -                 |
|                             | LESS 10% DISCOUNT                                |                      | -409.60                   | -311.00           |
|                             |  |                      | 3,686.40                  | 2,799.00          |
| <b>SPECIAL NETT ITEMS</b>   |  |                      |                           |                   |
| 1                           | SET REAR BUMPER CLIPS (SN)                       | NECESSARY            | 48.00                     | 48.00             |
| 1                           | SET END PANEL INNER GARNISH CLIPS (SN)           | NOT NECESSARY        | 30.00                     | -                 |
| 1                           | SET BOOTLID LOWER GARNISH CLIPS (SN)             | NOT NECESSARY        | 60.00                     | -                 |
| 1                           | SET BOOTLID STICKERS (SN)                        | NECESSARY            | 100.00                    | 100.00            |

Report Ref No. CS/FCI18010674/K1rd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty   | Description of Parts  | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|---|---------------|---------------------------|-------------------|
| 1   | SET REVERSE SENSOR (SN)   | SHORTED       | 280.00                    | 200.00            |
| 1   | REAR BUMPER TOP PROTECTOR (SN)  | NECESSARY     | 80.00                     | 50.00             |
| 1   | SUNDRY (SN)   | NECESSARY     | 50.00                     | 20.00             |
|   |   |               | 648.00                    | 418.00            |
|   | <b>LABOUR</b>   |               |                           |                   |
|   | TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.  |               | 120.00                    | 20.00             |
|   | TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.  | NOT NECESSARY | 180.00                    | -                 |
|   | TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT/WELD, CUT-OFF THE END PANEL, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME, ETC. INCLUSIVE OF THE REPAIR OF BOOTLID LOWER GARNISH, BOOTLID HINGES AND END PANEL. |               | 1,000.00                  | 600.00            |
|   | TO PUTTY AND SPRAY PAINTING ON BOOTLID, BOOTLID LOWER GARNISH, REAR BUMPER, END PANEL.  |               | 800.00                    | 720.00            |
|   | TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.  |               | 150.00                    | 50.00             |
|   |   |               | 2,250.00                  | 1,390.00          |
| <b>GRAND TOTAL</b>  |   |               | <b>6,584.40</b>           | <b>4,607.00</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |   |               |                           | <b>3,650.00</b>   |

Report Ref No. CS/FCI18010674/K1rd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.