

ASS. REC. BY:

REF:

CS/FCI 8010675 / Vtd3n2

Special Instruction:

Surveyor

CWS

Sathy

ASSIGNMENT (Office)

From (Person)

Eileen Lee

of

FCI

Date/Time

12/6/18 @ 12:09pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 6721T

Insured:

SH 8858Y

at Workshop in/s

Sin Yew Hub

Tel:

67600819

of

393M Woodlands Rd Yew Tee Ind. Est.

Policy No:

Claim No:

D18001566 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04/06/2018

CA / REV / REP. / REV 24 HRS

1081

H.O.D. Endorsement:

Date/Time:

12:24pm @ 12/6/18

Person Contacted:

Jing Yee

Vehicle

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLJ 6721T - X

SH 8858Y - CS / ALH10009633 / Fmt Bys

DOA: 14052010

Part by Part \$21,259.00 (Red: 939; 302)

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No _____

Claims No _____

Sum Insured _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLJ 6721 T Yr Bgn: Dec 2016Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia CarensCC: 1685Colour: Black

A/C: Insured / Std / NI / NA

Sp Reading: 49412

T/Radio: Insured / Std / NI / NA

Eng/No: D4FDG H113345C/No: KNAHU815VG7164504Gen. Cond: Good / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55 R16R: 205/55 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pirelli (Front), Nexen (Rear)

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 4/6/2018D.O.I. 12/6/2018Survey held at Sin Yew HupDes. of Damages: Frt / Rear / O/S N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Sathya / PLS see my remarks.

RECEIVED 05 JUL 2018

22/6

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 4Resurvey No. of Trip: 3

Date/Time, File Return to?

2)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Insp (\$)

Survey Fee:

Transportation:

5 + P.S. 9

Photos:

Video:

130

50

50+50+50

33

363

Report Format :

TP

181 2125.90

MOTOR SURVEY ASSIGNMENT

Date	07-06-2018	Our Ref No. D18004566MFSH
Accident Date	04-06-2018	Claim Type. Third Party
Insured Vehicle	SH8858Y	Third Party Vehicle. SLJ6721T
Survey Location	393M WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE	
Contact Person.	JING YEE (MS)	
Contact No.	67600819/ 0	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SIN YEW HUP AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241236)



PRI Documents



Close



PRI Header Details

Claim No	D18004566MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & SIN YEW
Workshop Name	SIN YEW HUP AUTO PTE LTD (Contact Person : JING YEE (MS))	Survey Location & Contact Details	393M WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATI Mobile: 0 , Phone: 67600819 , Fax: 0 EmailId: SYHAPL@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH8858Y	TP Vehicle No	SLJ6721T
PRI Recieved Date	11-06-2018 08:06:30 PM	Surveyor Appointed Date	12-06-2018 12:08:04 PM	Surveyor Accept Date	12-06-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	12-06-2018	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



新友合汽车私人有限公司 SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg
Specialise in Insurance Claims and General Motor Repair Work

Co./GST Regn. No. 200921075G

11-Jun-18

THIRD PARTY CLAIM

Third Party Vehicle No : SH8858Y

Date of Accident : 04/06/2018

M/S HSC PIPELINE ENGINEERING PTE LTD

C/o 393M Woodlands Road

Yew Tee Industrial Estate

Singapore 677981

ESTIMATED COST OF KIA CARENS 1.7(A) DIESEL : SLJ6721T

A) Chassis No : KNAHU815VG7164504

B) Date of Registration : 21 Dec 2016

S/No.	Pc/s	Item(s) :-	
1	1	Front door RH ✓DT	914.00
2	2	Front door tape @\$26.00 ✓NEC	52.00
3	1	Front door outer handle RH ✓CRK	53.00
4	1	Key lock cover ✓CRK	32.00
5	1	Fender RH R	310.00
			1,361.00
			Less Discs : 10% -
			136.10
			1,224.90

Labour Charges :

- | | | |
|----|--|------------------|
| a) | Transfer front RH door mechanism. | 80.00 50 |
| b) | Antirust affected portions. | 60.00 30 |
| c) | To spray paint front bumper, fender RH, front door RH (inner and outer) and rear door RH. | 1,000.00 300 700 |
| d) | To remove and refit front door RH, fender RH and bumper, to panel beat rear door RH. | 700.00 600 400 |

GST (7%) :-

3,064.90

Total :-

214.54

3,279.44

Sathya Sai

12/6/2018

sebastianyeang@lkkauto.com

- Part by Part repair
- Question mark item photo
- Photo before paint

[Signature]
22/6/18

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COR:
1651
- 10%
945.9
+ 1180.0
2125.9 #



新友合汽车私人有限公司

SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981

Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg

Co./GST Regn. No. 2009210756

Specialise in Insurance Claims and General Motor Repair Work

11-Jun-18

THIRD PARTY CLAIM

Third Party Vehicle No : SH8858Y

Date of Accident : 04/06/2018

M/S HSC PIPELINE ENGINEERING PTE LTD

C/o 393M Woodlands Road

Yew Tee Industrial Estate

Singapore 677981

Parts 1,051.00
- (10%) 105.10
945.90
Labour 1,480.00
2,425.90

ESTIMATED COST OF KIA CARENS 1.7(A) DIESEL : SLJ6721T

A) Chassis No : KNAHU815VG7164504

B) Date of Registration : 21 Dec 2016

S/No.	Pc/s	Item(s) :-	
1	1	Front door RH ✓ OT	914.00
2	2	Front door tape @\$26.00 ✓ NEC	52.00
3	1	Front door outer handle RH ✓ CRK	53.00
4	1	Key lock cover ✓ CRK	32.00
5	1	Fender RH R	310.00
			1,361.00
			Less Discs : 10% -
			136.10
			1,224.90

Labour Charges :

- a) Transfer front RH door mechanism. 80.00 50
- b) Antirust affected portions. 60.00 30
- c) To spray paint front bumper, fender RH, front door RH (inner and outer) and rear door RH. 1,000.00 200
- d) To remove and refit front door RH, fender RH and bumper, to panel beat rear door RH. 700.00 600

GST (7%) :- 3,064.90
Total :- 214.54
3,279.44

Sathya Sai
12/6/2018
sebastiany@lkkauto.com
- Part by Part repair
- Question mark item photo
- Photo before paint.

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Before Paint
Sathya Sai
13/6/2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18010675/Vtd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-07-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8858Y	Veh. Inspected	SLJ 6721T	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18004566MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	12/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA CARENS	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KNAHU815VG7164504	Colour	BLACK	
Odometer	49412	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	6 mm	
L/H Front Tyre	205/55 R16	PIRELLI	6 mm	
R/H Rear Tyre	205/55 R16	NEXEN	6 mm	
L/H Rear Tyre	205/55 R16	NEXEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/06/2018	Inspection Date	12/06/2018	
Survey held at	SIN YEW HUP AUTO PTE LTD BLK 4, 393M, WOODLANDS ROAD YEW TEE IND. ESTATE SINGAPORE 677981			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 6721T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR RH	DENTED	914.00	914.00
2	FRONT DOOR TAPE @\$26.00	NECESSARY	52.00	52.00
1	FRONT DOOR OUTER HANDLE RH	CRACKED	53.00	53.00
1	KEY LOCK COVER	CRACKED	32.00	32.00
1	FENDER RH	TO REPAIR SEE LABOUR	310.00	-
	LESS 10% DISCOUNT		-136.10	-105.10
			1,224.90	945.90
	LABOUR			
	TRANSFER FRONT RH DOOR MECHANISM.		80.00	50.00
	ANTIRUST AFFECTED PORTIONS.		60.00	30.00
	TO SPRAY PAINT FRONT BUMPER, FENDER RH, FRONT DOOR RH (INNER AND OUTER) AND REAR DOOR RH.		1,000.00	700.00
	TO REMOVE AND REFIT FRONT DOOR RH, FENDER RH AND BUMPER, TO PANEL BEAT REAR DOOR RH.		700.00	400.00
			1,840.00	1,180.00
	GRAND TOTAL		3,064.90	2,125.90
RECOMMENDED COST OF REPAIRS				2,125.90

Report Ref No. CS/FCI18010675/Vtd3n2

SATHYA SAI KATHIRRASEN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.