

ASS. REC. BY:

REF:

CS3 / ATG 18010676 / Dzud3er

Special Instruction:

Surveyor
Meinen

Bryun

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

12/6/18 @ 11:42am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SVV 9583R

Insured:

SLV 9802K

at Workshop m/s

Hiap Lek Automobile

Tel:

9660 1347

of

160 Sin Ming Drive #05-17

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

8/6/18

CA / REV / REP. / REV 24 HRS

lup

13062018

Date/Time:

12:18pm @ 12/6/18

Person Contacted:

Mr. Ong

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SVV 9583R - X
	SLV 9802K - X
14/6/18	Dismantled.
18/6/18	After Repair

Surveyor

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SSV 95837Yr Regn: 2010, Feb.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Cerato ForteC.C. 1591Colour: Red

A/C: Insured / Std / NI / NA

Sp. Reading: 130 115

T/Radio: Insured / Std / NI / NA

Eng/No: G4FLAH365311C/No: KNAFW611MA5202941Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/45 R17R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Ling Long

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 08/06/2018D.O.I. 13/06/2018

Survey held at

Hicap Luk Sin King

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	AIG PR8 SLV 9802K
	MV 18K
	VIA 11.5K
	NL 6.5K
	Front bumper x 1 distorted — " clip x 1 set H/C
	Front RH Headlamp x 1 cut
	Front RH Fog lamp x 1 mounting crack
	Front LH Fog lamp cover x 1 — " —
	Front LH Headlamp bracket x 1 Bt.
15/8/18	submit DAP report.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

\$ + RS. SI

Photos

Others

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

180

20

200

- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLV9802K AND SJV9583R ON 08/06/2018

From: Chin, Lee-Ying
To: assignments@lkkauto.com, Admin A
Cc: Fong, Andy-SY
Sent: 12/6/2018 11:42:06 AM
Attachments:  SLV9802K--PRI.TIF

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Marianti Bte AB Kahar [mailto:marianti@legaloptions.biz]
Sent: Monday, June 11, 2018 4:22 PM
To: Chan, Yoke Shi; Pinky Wong
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina; Fan, Winnie-LW
Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLV9802K AND SJV9583R ON 08/06/2018

Dear Sir/Mdm,

Our client rejected your list of surveyor.

We provide you herewith our client's list of surveyor: -

	SURVEYOR:	CONTACT PERSON:	CONTACT:
1.	PAR AUTOMOTIVE CONSULTANCY	B J LOI	94882266
2.	UNITED APPRAISAL AND MANAGEMENT PTE LTD	MARC	91461186
3.	OH APPRAISAL SERVICES	OH HAN CHEONG	97982959
4.	SK AUTO CONSULTANTS	KUMA (S. KU,AMAN)	90040225
5.	LEE AUTOMOBILE APPRAISERS SERVICES	LEE K W	81882833
6.		NG CHENG MENG	91459178

	CM AUTOMOTIVE CONSULTANCY		
7.	ISP MANAGEMENT PTE LTD	ZALI SAIDI	96553574
8.	AUTO PERFORMANCE APPRAISAL	LEK BOON HWEE	94301592

Your said surveyor may contact

Mr Ong Han Wei at 9660 1347, M/s Hiap Lek Automobile Trading at

160 Sin Ming Drive #05-17, Sin Ming Autocity, Singapore 575722

*

If we do not hear from you within 2 days of this email, our clients shall deem that you have agree that the surveyor appointed by our clients shall be our single joint expert for this matter.

Thanks & Regards,

Marianki

Secretary

LEGAL OPTIONS LLC

(GST Registration/UEN No. 201203825R)

Tel (65) 6513-2800 DID (65) 6513-2803 Fax (65) 6438-8275

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

LEGAL OPTIONS LLC
ADVOCATES & SOLICITORS
 Mediators - Commissioners for Oaths - Notary Public
法商律师事务所

Motor Accident & Personal Injuries
 Tel: (65) 6513 2800 Fax: (65) 6438 8275

Commercial, Litigation, Property, Trust & Estate, Family
 Tel: (65) 6438 8039 Fax: (65) 6734 8230

We do not accept service of Court Documents by fax

Your Ref : SLV 9802K
 Our Ref : 18-A14-9372-VL.jp.mr

11th June 2018

M/S AIG ASIA PACIFIC INSURANCE PTE LTD
 78 Shenton Way #07-16
 AIG Building
 Singapore 079120
 (Attn: Motor Claims Department)

Dear Sirs.

CLAIMANT : KUA HIONG YONG
ACCIDENT INVOLVING VEHICLE NOS. SJV 9583R & SLV 9802K AT CARPARK OF TAMAN
JURONG SHOPPING ON 08/06/2018

We are instructed by MR KUA HIONG YONG to notify you of a road traffic accident on 8th JUNE 2018 at about 20:45 HOURS 9802K AT CARPARK OF TAMAN JURONG SHOPPING involving our client's vehicle registration number SJV 9583R and vehicle registration number SLV 9802K driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully



Encl
 Cc: Clients (SJV 9583R)

Directors
 Joan Lim Pheok Hoon LL.B (Hons)
 Victor Leong Wai Meng LL.B (Hons)

Junior Secretary's DID: 6513 2803
 Direct Fax: 6438 8275
 (Email: waicauti@legaloptions.biz)

Mailing Address for Accident Claims
 Documents Support:
 23 Kallit Bukit Avenue 4 #01-01 South Wing
 Singapore 415933

By Fax : 6415 3727/Post

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7952J
Vehicle Details	
Vehicle No.:	SJV9583R
Vehicle to be Exported:	Yes
Intended De-registration Date:	14 Aug 2018
Vehicle Make:	KIA
Vehicle Model:	CERATO FORTE KOUP 1.6 AT SX ABS D/AB SR
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	G4FCAH365311
Chassis No.:	KNAFW611MA5202941
Maximum Power Output:	92.7 kW (124 bhp)
Open Market Value:	\$15,754.00
Original Registration Date:	25 Feb 2010
First Registration Date:	25 Feb 2010
Transfer Count:	5
Actual ARF Paid:	\$15,754.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Feb 2020
PARF Rebate Amount:	\$8,664.00
Intended COE Rebate Details	
COE Expiry Date:	24 Feb 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$18,899.00
COE Rebate Amount:	\$2,889.00
Total Rebate Amount:	\$11,553.00

The information contained herein is correct as at 14 Aug 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jun 2018 Edit Reg		12 Jun 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	LIM AI CHOO , ID: S6924963I								
Main Claimant:	-								
Vehicle Reg. No.:	SJV9583R	Date of Loss:	08/06/2018 20:00 - :59 [99 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4035402592SG	Policy/Cover Note No.:	1800014916 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLV9802K	Policy No. (Claimant):							
		Excess:							
Repairer:	Hiap Lek Automobile Trading () Blk 14 #01-19 Sector B, Sin Ming Industrial Est, 575658 Sin Ming - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 25/07/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
<ul style="list-style-type: none"> AIG_SG (17/07/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJV9583R (4035402592SG)**
[SLV9802K]
















































TP

-
Jun 8 2018 8:00PM

[LIM AI CHOO]

Hiap Lek Automobile Trading

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Assessment Reports			1 per page <input type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/07/18 11:09	Accident Statement From: SC - Reg. No: SLV9802K, Claimant: LIM AI CHOO	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/08/18 18:14	Front View Right	Load JPG	<input checked="" type="checkbox"/>
2	14/08/18 18:14	Front View Left	Load JPG	<input checked="" type="checkbox"/>
3	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
4	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
5	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
6	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
7	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
8	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
9	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
10	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
11	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
12	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
13	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
14	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
15	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
16	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
17	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
18	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
19	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
20	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
21	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
22	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
23	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
24	14/08/18 18:14	General View	Load JPG	<input checked="" type="checkbox"/>
25	14/08/18 18:14	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
26	14/08/18 18:14	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
27	14/08/18 18:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
28	14/08/18 18:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	14/08/18 18:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	14/08/18 18:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	14/08/18 18:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	14/08/18 18:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
33	14/08/18 18:16	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	14/08/18 18:16	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	14/08/18 18:17	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
76	14/08/18 18:17	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
77	14/08/18 18:17	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
78	14/08/18 18:17	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
79	14/08/18 18:17	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
80	14/08/18 18:17	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18010676/DZ4D3E2

Date: 17/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800014916
Claimant Vehicle No : SJV9583R **Insured Vehicle No :** SLV9802K
 Date of Loss: 08/06/2018 Nature of Claim: TP Claim No: 4035402592SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJV9583R**
 Make & Model: KIA CERATO FORTE KOUP, 1.6 SX ABS D/AB SR (A) Engine No: G4FCAH365311
 Reg. Date: 25/02/2010 (Man. Year: 2009) Chassis No: KNAFW611MA5202941
 Colour: Red Odometer: 130115 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
 Front Left Side: Linglong 6 mm Rear Left Side: Linglong 6 mm
 Front Right Side: Linglong 6 mm Rear Right Side: Linglong 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 12/06/2018
 Date Inspected: 13/06/2018 Inspected At: 160 SIN MING DRIVE #05-17
 Repairer :Hiap Lek Automobile Trading
 Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI**Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	0.00 F	*- F
2	1		*SET FRONT BUMPER CLIP	Necessary	0.00 F	*- F
3	1		*FRONT LH HEADLAMP	Cut	0.00 F	*- F
4	1		*FRONT LH FOG LAMP	MTG Cracked	0.00 F	*- F
5	1		*FRONT LH FOG LAMP COVER	MTG Cracked	0.00 F	*- F
6	1		*FRONT LH HEADLAMP BRACKET	Bent	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >