

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9789T**AAD1806-066***Not Authorized
L1Bny 881006*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHB 9789T

VF1ABL15AUC273316

RENAULT

LATITUDE

6.6.2018

AIG

PART		LIST	
1	FENDER PANEL FRT LH	\$	<i>Bz</i> 783.83 ✓
1	WHEELARCH FRT LH	\$	<i>SL</i> 278.84 X
1	FENDER BRACKET LOWER LH	\$	<i>SL</i> 15.79 X
1	FENDER INSULATOR LH	\$	<i>SL</i> 130.84 X
1	DOOR PANEL FRT LH	\$	<i>Bz</i> 2,844.66 ✓
1	DOOR HINGE UPPER LH	\$	<i>N</i> 261.28 X
1	DOOR HINGE LOWER LH	\$	<i>N</i> 300.55 X
1	DOOR CHECK FRT LH	\$	<i>SL</i> 194.77 X
1	DOOR LOCK FRT LH	\$	<i>N</i> 908.75 X
1	DOOR CATCH FRT LH	\$	<i>SL</i> 131.23 X
1	DOOR HANDLE OUTER FRT LH	\$	<i>Ned</i> 477.76 ✓
1	DOOR HANDLE COVER FRT LH	\$	<i>SL</i> 13.22 X
1	DOOR HANDLE MODULE FRT LH	\$	<i>SL</i> 133.60 X
1	DOOR REGULATOR FRT LH	\$	<i>N</i> 505.19 X
1	DOOR REGULATOR MOTOR FRT LH	\$	<i>N</i> 796.46 X
1	DOOR REGULATOR GUIDE FRT LH	\$	<i>SL</i> 120.97 X
1	DOOR PANEL REAR LH	\$	<i>Bz</i> 2,844.66 ✓
1	DOOR GUIDE REAR LH	\$	<i>SL</i> 176.82
1	DOOR HINGE UPPER LH	\$	<i>N</i> 274.50
1	DOOR HINGE LOWER LH	\$	<i>N</i> 300.55
1	DOOR CHECK REAR LH	\$	<i>SL</i> 203.06
1	DOOR LOCK REAR LH	\$	<i>N</i> 908.75
1	DOOR HANDLE OUTER REAR LH	\$	<i>SL</i> 126.49
1	DOOR HANDLE CAP REAR LH	\$	<i>SL</i> 35.52
1	DOOR HANDLE SEAL REAR LH	\$	<i>SL</i> 7.89
1	DOOR HANDLE COVER REAR LH	\$	<i>SL</i> 13.22
1	DOOR HANDLE MODULE REAR LH	\$	<i>SL</i> 133.60
1	DOOR REGULATOR REAR LH	\$	<i>N</i> 1,135.10
1	DOOR REGULATOR MOTOR REAR LH	\$	<i>N</i> 893.75
1	DOOR REGULATOR NUT REAR LH	\$	<i>SL</i> 12.43

X

Trans-cab Auto Services Pte Ltd**AAD1806-066**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9789T

1	DOOR REGUALTOR MOTOR SCREW REAR L70Y	\$	6.31	} X
1	DOOR FINISHER REAR LH	\$	423.10	
1	DOOR MOULDING REAR LH	\$	176.82	
1	DOOR MOULDING CLIP L70Y	\$	5.92	
1	DOOR MOULDING SCREW L70Y	\$	6.91	
1	DOOR CASING REAR LH	\$	1,509.06	
1	DOOR WATER SHIELD REAR LH	\$	30.39	
1	DOOR CASING CLIP	\$	12.63	
1	DOOR CASING LIGHT L70Y	\$	48.74	
1	DOOR FINISHER INNER REAR LH	\$	323.44	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	46.97	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	20.33	
1	DOOR GRAB HANDLE REAR LH	\$	210.96	
1	DOOR BLIND REAR LH	\$	741.80	
1	DOOR WHEATHESTRIIP REAR LH	\$	410.66	
1	DOOR SEAL REAR LH	\$	162.02	
1	DOOR GLASS RUNNER SEAL REAR LH	\$	229.31	
1	DOOR WAIST SEAL OUTER REAR LH	\$	334.69	
1	DOOR WAIST SEAL INNER REAR LH	\$	115.64	
1	FENDER PANEL REAR LH	\$	3,299.13	} ✓
1	FENDER PANEL INNER TRIM REAR	\$	671.45	
1	WHEELARCH REAR LH	\$	543.47	
1	DOOR MIRROR ASSY LH	\$	1,483.40	
1	ROCKER PANEL INNER GARNISH LH	\$	466.51	
1	ROCKER PANEL INNER LH	\$	1,024.79	
1	ROCKER PANEL CENTER LH	\$	990.25	
1	LOWER ARM LH L70Y	\$	685.76	
1	KUNCKLE ARM LH L70Y	\$	846.98	} ✓
1	ABSORBER FRT LH L70Y	\$	360.54	

	\$	30,192.72
10%	\$	3,019.27
	\$	27,173.45

Trans-cab Auto Services Pte Ltd

AAD1806-066

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9789T

Special Nett

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	sn	30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00	60sn
1	FRONT DOOR STICKER 'Chassis'	\$	nn	50.00	15sn
1	REAR DOOR STICKER '6555 3333'	\$	nn	80.00	60sn
1	DOOR CHECK BOLT	\$	nn	22.69	} X
1	DOOR GUIDE SCREW	\$	nn	10.85	
1	DOOR HINGE BOLT	\$	nn	10.85	
1	DOOR HINGE NUT RH	\$	nn	14.60	
1	DOOR CHECK BOLT	\$	sn	22.69	
1	DOOR CHECK NUT	\$	sn	3.75	
1	DOOR LOCK SCREW L70Y	\$	sn	6.12	
1	DOOR CATCH SCREW L70Y	\$	sn	10.06	

TOTAL	\$	462.13
--------------	-----------	---------------

TOTAL PARTS	\$	27,635.58
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	4,500.00	7001
----	----------	------

Putty and spray painting of the affected portion.

\$	4,200.00	13201
----	----------	-------

To rust-proofing of the affected areas.

\$	170.00	901
----	--------	-----

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	380.00	801
----	--------	-----

To check steering geometry and computer wheel alignment

\$	nn	220.00	X
----	----	--------	---

Trans-cab Auto Services Pte Ltd

AAD1806-066

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9789T

To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>2q</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00 <i>6q</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00 <i>6q</i>
Towing Fees.	\$	120.00 <i>5q</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i> 380.00 <i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 <i>X</i>

TOTAL	\$	11,830.00
--------------	-----------	------------------

Over All Total	\$	39,465.58
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)**15 DAYS***6 day,*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: