

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7681H**AAD1806-079***Not Authorized*
L1 Smp B

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7681H

KL1LA69RJB092324

CHEVROLET

EPICA 2.0

8.6.2018

*Alt***PART****LIST**

1	1	Front Fender RH	\$	<i>B</i> 837.60	✓
2	1	Front Fender Liner RH	\$	<i>Dst</i> 47.00	✓
3	1	Fender Insulation RH	\$	<i>Sn</i> 39.00	
4	1	Front Fender Inner Wheel House Panel RH	\$	<i>R</i> 1,437.00	
5	1	Front Door RH	\$	<i>R</i> 1,133.00	
6	1	Front Door Glass Guide RH Chrome Moulding	\$	<i>Sn</i> 60.00	
7	1	Front Door Outer Moulding	\$	<i>Sn</i> 220.00	
8	1	Front Door Outer Handle	\$	<i>Sn</i> 125.00	
9	1	Front Door Handle Support	\$	<i>Sn</i> 3.00	
10	1	Front Door outer handle inner seal	\$	<i>Sn</i> 89.15	
11	1	Front Door outer key lock	\$	<i>Sn</i> 25.00	
12	1	Front Door Hinge Upper	\$	<i>R</i> 65.00	
13	1	Front Door Hinge Lower	\$	<i>R</i> 65.00	
14	1	Front Door inner lock	\$	<i>R</i> 586.00	
15	1	Front Door Inner Lock Latch RH	\$	<i>Sn</i> 206.00	
16	1	Front Door Check / Arrestor	\$	<i>Sn</i> 67.50	
17	1	Front Door Weatherstrip RH	\$	<i>Sn</i> 138.79	
18	1	Front Door glass channel weatherstrip	\$	<i>Sn</i> 160.00	
19	1	Front Door inner trim board	\$	<i>Sn</i> 455.69	
20	1	Front Door window glass	\$	<i>Sn</i> 456.12	
21	1	Front Door Power Window Motor (Master) RH	\$	<i>Sn</i> 284.97	
22	1	Front Door power window motor switch	\$	<i>Sn</i> 145.00	
23	1	Front Door Window Regulator Gear RH	\$	<i>Sn</i> 84.58	
24	1	Front Door Outer Pillar Panel RH	\$	<i>R</i> 715.00	
25	1	Front Door Pillar Inner Panel RH	\$	<i>R</i> 850.00	
26	1	Front Door Center Pillar Panel RH	\$	<i>R</i> 698.15	
27	1	Front Side View Mirror Assy RH	\$	<i>Sn</i> 1,191.00	

X

Trans-cab Auto Services Pte Ltd

AAD1806-079

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7681H

28	1	Front Side Rocker Panel Garnish RH	\$	cm 236.40	✓
29	1	Front Side Rocker Panel Outer RH	\$	n 600.00	X
30	1	Front Side Rocker Panel Inner RH	\$	n 519.30	X
31	1	Rear Door RH (Panel A-RR DR LH)	\$	n 1,133.00	X
32	1	Front Shock Absorber Assy RH	\$	216.17	7
33	1	Front Shock Absorber Top Mounting RH	\$	48.32	7
34	1	Front Lower Arm RH	\$	283.00	7
35	1	Front Knuckle Arm RH	\$	230.00	7
36	1	Front Hub Unit	\$	376.00	7

TOTAL	\$	13,826.74
10%	\$	1,382.67
	\$	12,444.07

Special Nett

1 Set	Front Bumper Fastener Clip	\$	nn 24.00	X
1 Set	Front licence plate with holder	\$	sn 192.00	X
1 Set	Radiator Grille clip	\$	nn 35.00	X
1 Set	Front Fender Liner clip	\$	nn 30.00	✓
1	Front Fender RR Bracket RH	\$	n 7.10	X

TOTAL	\$	288.10
--------------	-----------	---------------

TOTAL PARTS	\$	12,732.17
--------------------	-----------	------------------

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00	201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	4001
Putty and spray painting of the affected portion.	\$	4,000.00	8001
Towing Fees.	\$	nn 120.00	X

Trans-cab Auto Services Pte Ltd

AAD1806-079

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7681H

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	7
To check steering geometry and computer wheel alignment	\$	220.00	601
To transfer of tire, rim and on wheel balancing.	\$	170.00	7
To rust-proofing of the affected areas.	\$	170.00	391
To check steering geometry and computer wheel alignment	\$	<i>Repair</i> 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X
To transfer of fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X

TOTAL \$ 10,460.00**Over All Total \$ 23,192.17****Repair Days (Lump Sum) 15 days***3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: