

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9723H**AAD1806-076***Not Authorised
L/Sing &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9723H

VF1ABL15AUC273099

RENAULT

LATITUDE

7.6.2018

AIG**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>By</i> 1,108.46	—
2	1 BUMPER LOWER REAR	\$	<i>Original</i> 768.84	—
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	<i>Sn</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>By</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	225.95	?
12	1 BUMPER BEAM BRACKET RH REAR	\$	225.95	?
13	1 BOOT REAR	\$	<i>By</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>Sn</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05	X
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35	X
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35	X
18	1 BOOT BADGE 'RENAULT'	\$	<i>By</i> 225.36	—
19	1 BOOT BADGE	\$	<i>By</i> 225.36	—
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08	} X
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45	
25	1 BOOT SWITCH	\$	<i>Sn</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	}
28	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	

Trans-cab Auto Services Pte Ltd**AAD1806-076**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9723H

30	1 DOOR PANEL REAR LH	\$	<i>R</i> 2,844.66	}
31	1 FENDER PANEL INNER TRIM REAR LH	\$	<i>Sm</i> 671.45	
32	1 FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13	
33	1 WHEELARCH REAR LH	\$	<i>Sm</i> 543.47	
34	1 FENDER PANEL INNER TRIM REAR RH	\$	<i>Sm</i> 671.45	
35	1 FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13	
36	1 WHEELARCH REAR RH	\$	<i>Sm</i> 543.47	
37	1 TAILLAMP RH	\$	<i>Sm</i> 552.55	
38	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70	
39	1 TAILLAMP LH	\$	<i>Sm</i> 552.55	
40	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70	}
41	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77	
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Em</i> 404.56	
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i> 2,189.88	
44	1 SPARE WHEEL PANEL TRIM	\$	<i>Sm</i> 612.21	
45	1 EXHAUST REAR	\$	<i>R</i> 7,489.05	
46	1 EXHAUST CAP REAR	\$	<i>R</i> 230.49	
47	1 FUEL FLAP L70Y	\$	<i>Sm</i> 343.57	
48	1 FENDER WHEEL HOUSE PANEL REAR LH	\$	<i>R</i> 3,039.04	

TOTAL	\$	42,096.20
10%	\$	4,209.62
	\$	37,886.58

Special Nett

1	1SET PARKING AID	\$	<i>Shan</i> 700.00 <i>600.00</i>
2	1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00 —
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00 —
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00 X
5	1SET BUMPR RETAINER RH CLIP RR	\$	<i>na</i> 20.00 X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00 X
7	1SET BUMPR RETAINER CLIP LH RR	\$	<i>na</i> 20.00 X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00 X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00 —
10	1 EXHAUST MOUNTING REAR	\$	<i>Sm</i> 17.82 X
11	1SET BOOT FINISHER CLIP	\$	<i>na</i> 24.20 X
12	1 BOOT STICKER "Trans-cab"	\$	<i>na</i> 30.00 —
13	1 BOOT STICKER "6555-3333"	\$	<i>na</i> 30.00 —

Trans-cab Auto Services Pte Ltd**AAD1806-076**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9723H

14	1 BOOT INNER TRIM CLIP	\$	na	45.00	}	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00		
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00		
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00		
18	1 FENDER INNER TRIM CLIP LH	\$	na	28.00		
19	1 TAILLAMP CLIP RH	\$	na	5.00		
20	1 TAILLAMP CLIP LH	\$	na	5.00		
21	2 REAR WINDSCREEN SELANT	\$	na	80.00		
22	1 WINDSCREEN MOULDING	\$	na	100.00		
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00		
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	na	385.00	}	
25	1 SPARE TYRE	\$	na	330.00		

TOTAL	\$	2,225.02
--------------	-----------	-----------------

TOTAL PARTS	\$	40,111.60
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	6601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	6001
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	na	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1806-076**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9723H

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	~ 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	~ 380.00	X
TOTAL	\$	12,540.00	

Over All Total \$ 52,651.60**(LUMP SUM)****Repair Days**~~20 DAYS~~

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: