

ASS. REC. BY:

REF:

CS/FCI18010684/Vtd3n2

Special Instruction:

Surveyor
CWS

Sathya

ASSIGNMENT (Office)

From (Person):

Eileen lee

of

FCI

Date/Time

12/6/18 @ 9:27am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SLH 2960 G

Insured:

SHC 389EX

at Workshop m/s

World Auto

Tel:

63621776

of

No.1 Kranji loop

Policy No:

Claim No:

D18001738 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

28/02/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:33am @ 12/6/18

Person Contacted:

Ainee

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction	Estimate
	SLH 2960 G - X	
	SLH 3398 X - CS/FCI14012223/Jthw2	DA: 2606/14
22/6	Refer preli advise	
	Confirm lump sum \$1400/- (Red. 1720 : 55%)	

REF: FCI

ASSIGNMENT

From:

Date: 12/6/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLH 2960G

at Workshop m/s

World Auto

of

No. 1 Kranji Loop

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Ainee

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1wp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SLH 2960G Yr Regn: Oct 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezzel C.C. 1496

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 120312 T/Radio: Insured / Std / NI / NA

Eng/No: LEB5911690

C/No: RU31211680

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16

R: 215/60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Dunlop (Rear), Giti (Front)

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 28/02/2018 D.O.I. 12/6/2018

Survey held at World Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 23 AUG 2018

Date/Time: File Pass to?

☐ : Preli. Report

Days Of Repair: 2

12/3/18 Typist

☒ : Final Report

Resurvey No. of Trip:

Survey Fee:

Transportation

1) S + RE. SI

2) Photos

3) Others

TOTAL

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

TP
1400130
50
50
27

257



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18010684/Vtd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-06-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 3898X	Veh. Inspected	SLH 2960G
Policy No.		Coverage (\$)	0.00
Claim No.	D18001738MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	12/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/02/2018	Inspection Date	12/06/2018
Survey held at	NO. 1 PANDAN LOOP		
Repairer	WORLD AUTO PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001738MFSH_

Date: 22/6/2018

Our Ref: CS/FCI18010684/Vtd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLH 2960G

Please be informed that we had conducted the inspection of the abovementioned vehicle
22/06/2018 at the premises of M/s World Auto and have the following to report: -

Workshop Estimate Amount	: S\$ <u>3,120.00</u>
Revised Estimate Amount	: S\$ <u>1,770.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Sathya

Automotive Assessor

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 22 June 2018 3:35 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001738MFSH/1
Attachments: PRELI ADVISED SLH 2960G.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLH 2960G**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 12 June 2018 9:43 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001738MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 12 June 2018 9:26 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001738MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

Denise Tay (LKKAUTO)

From: tggtan@worldauto.com.sg
Sent: Thursday, 23 August 2018 4:15 PM
To: Denise Tay (LKKAUTO)
Subject: RE: SLH 2960G Our ref: TP/1924/18

Hi Denise

Finalised \$1400 (lump sum) and 2 days of repairs.

Rdgs
Sophia Tan
World Auto Pte Ltd (Kranji)

-----Original Message-----

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Thursday, 23 August 2018 3:41 PM
To: tggtan@worldauto.com.sg
Cc: SUR <sur@lkkauto.com>; Celine Fong (LKKAUTO) <celinefong@lkkauto.com>
Subject: RE: SLH 2960G Our ref: TP/1924/18

Dear Sophia,

Offer lump sum \$1400, 2 days

Please check and confirm

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: Denise Tay (LKKAUTO)
Sent: Thursday, 23 August 2018 11:49 AM
To: tggtan@worldauto.com.sg; Celine Fong (LKKAUTO) <celinefong@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLH 2960G Our ref: TP/1924/18

Dear Sophia,

Let me check and get back to you

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd

MOTOR SURVEY ASSIGNMENT

Date	01-03-2018	Our Ref No. D18001738MFSH
Accident Date	28-02-2018	Claim Type. Third Party
Insured Vehicle	SHC3898X	Third Party Vehicle. SLH2960G
Survey Location	NO.1, KRANJI LOOP	
Contact Person.	AINEE	
Contact No.	64513933/ 0	Fax No. 64557576
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WORLD AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235482)



PRI Documents



Close



PRI Header Details

Claim No	D18001738MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & WORLD A
Workshop Name	WORLD AUTO PTE LTD (Contact Person : AINEE)	Survey Location & Contact Details	NO.1, KRANJI LOOP Mobile: 0 , Phone: 64513933 , Fax: 64557576 EmailId: AINEE31@WORLD AUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC3898X	TP Vehicle No	SLH2960G
PRI Recieved Date	11-06-2018 05:15:56 PM	Surveyor Appointed Date	12-06-2018 09:26:05 AM	Surveyor Accept Date	12-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	12-06-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Sketch Plan #3

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7247065F



Name
NICHOLAS JAMES SIOW

Race
CHINESE

Date of birth
18-11-1972

Country/Place of birth
SINGAPORE

Sex
M

REPUBLIC OF SINGAPORE DRIVING LICENCE

Identity Card No. S7247065F



Name
NICHOLAS JAMES SIOW

Valid till
18 Nov 1992

Valid from
10 Feb 2000



Identity Card No. S7247065F



Date of issue
28-10-2016

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 1B Motorcycles not exceeding 200 cc
Class 2A Motorcycles between 201 cc and 400 cc
Class 3 Motor Cars and Motor Tractors the weight of which together does not exceed 3500 kilograms

Valid until

25 Oct 1992

26 Oct 1992

27 Aug 1992



No. 225A

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

FIRST CAPITAL INSSURANCE LIMITED

80 ROBINSON RD #09-02/03

068898

Attention : Motor Claim Department

Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES000162

Date : 11/06/2018

Vehicle Num. : SLH 2960G (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 28/02/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

1.		REAR BUMPER ✓ SCR	900.00	891
2.	1	REAR BUMPER REFLECTOR LENS RH X MM	250.00	
3.	1	REAR SIDE BUMPER - RH ✓ CUT	250.00	231
4.	1	REAR WHEEL ARCH MOULDING - RH X MM	250.00	

List Total S\$:

1,650.00

20.00% Discount S\$:

330.00

1,320.00

SPECIAL NETT ITEMS :

1.	1	REAR BUMPER CLIP ✓ NEC	50.00	
2.	1	REAR WHEEL ARCH MOULDING CLIPS X MM	50.00	

Special Nett Total S\$:

100.00

LABOUR :

LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.

900.00 400

PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)

800.00 400

Labour Total S\$:

1,700.00

E. & O.E.

Total S\$:

3,120.00

=====

for WORLD AUTO PTE LTD

Sathya Sai
12/6/2018

- Lump Sum Repair
- Photo after paint


22/6/18

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WORLD AUTO PTE LTD

47 Jalan Penjimpin #01-02/03

Halcyon 2, Singapore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldauto@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

FIRST CAPITAL INSURANCE LIMITED

80 ROBINSON RD #09-02/03

068898

Attention : Motor Claim Department

Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES000162

Date : 11/06/2018

Vehicle Num. : SLH 2960G (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 28/02/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	REAR BUMPER ✓ SCR		900.00
3.	1	REAR BUMPER REFLECTOR LENS RH X		-250.00
4.	1	REAR SIDE BUMPER - RH ✓ CUT		250.00
		REAR WHEEL ARCH MOULDING - RH X		-250.00

List Total S\$:

20.00% Discount S\$:

1,650.00

330.00

1,320.00

1150

230

1150

1.	1	SPECIAL NETT ITEMS :		
2.	1	REAR BUMPER CLIP ✓ NEC		50.00
		REAR WHEEL ARCH MOULDING CLIPS X		-50.00

Special Nett Total S\$:

100.00

50

LABOUR :

LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO
REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN
PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.

300.00 400

PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)

300.00 400

Labour Total S\$:

1,700.00

800

Lump sum \$ 1480 / ②

E. & O.E.

Total S\$: 3,120.00

1770

350

for WORLD AUTO PTE LTD

Sathya Sai
12/6/2012

- Lump Sum Repair
- Photo after paint

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18010684/Ntd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 24-08-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3898X	Veh. Inspected	SLH 2960G	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001738MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	12/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU31211680	Colour	RED	
Odometer	120312	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	6 mm	
L/H Front Tyre	215/60 R16	GITI	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/02/2018	Inspection Date	12/06/2018	
Survey held at	NO. 1 KRANJI LOOP			
Repairer	WORLD AUTO PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 2960G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	SCRATCHED	900.00	891.00
1	REAR BUMPER REFLECTOR LENS RH	NOT NECESSARY	250.00	-
1	REAR SIDE BUMPER-RH	CUT	250.00	231.00
1	REAR WHEEL ARCH MOULDING-RH	NOT NECESSARY	250.00	-
	LESS 20% DISCOUNT		-330.00	-224.40
			1,320.00	897.60
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIP (SN)	NECESSARY	50.00	50.00
1	REAR WHEEL ARCH MOULDING CLIPS (SN)	NOT NECESSARY	50.00	-
			100.00	50.00
	<u>LABOUR</u>			
	LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT,CUT/WELD,STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.		900.00	400.00
	PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER).		800.00	400.00
			1,700.00	800.00
	GRAND TOTAL		3,120.00	1,747.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,400.00

Report Ref No. CS/FCI18010684/Ntd3n2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.