

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0681/2018/PH
Date : 12-Jun-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle is : SLP 570 U

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Tan Swee Yong
Address : 23 Hillview Avenue
#01-04
Singapore 669557

Telephone : HP +65 97954993
Type of Claim : Third Party Claim
Policy No. : 151781
Vehicle No : **SLS 2008 Z**
Model Code : Audi A3 1.0 TFSI
Model / Year : Sep-17
Engine No : CHZ 512202
Chassis No : WAUZZZ8V0J1006701
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-Jun-18
Place of Accident : Slip road from KJE to Woodlands road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 2008 Z.

<u>S/N</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓	
2	To dismantle and renew rear bumper and rear spoiler. Re-organise rear crash management components. Reinstall all parts removed	\$ 900.00 500	
3	To respray rear bumper	\$ 800.00 550	
4	To carry out diagnostic check	S/N \$ 192.00 ✓	
LABOUR CHARGES		: \$ 2,172.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 2006 Z.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	BUMPER <i>ok</i>	\$ 1,697.00	✓
2	FIXING PARTS FOR BUMPER <i>ok</i>	\$ 166.00	X
3	SPOILER <i>ok</i>	\$ 206.00	✓
4	SIDE REINFORCEMENT <i>ok</i>	\$ 501.00	+
5	SENSOR <i>ok</i>	2 \$ 421.00	+
6	BRACKET - LH <i>ok</i>	\$ 23.00	+
7	BRACKET - RH <i>ok</i>	\$ 24.00	+
8	GUIDE SECTION - LH <i>ok</i>	\$ 57.00	+
9	GUIDE SECTION - LH <i>ok</i>	\$ 14.00	+
10	GUIDE SECTION - RH <i>ok</i>	\$ 14.00	+
11	GUIDE SECTION - RH <i>ok</i>	\$ 57.00	+
12	LOCKING MECHANISM <i>ok</i>	\$ 50.00	X
TOTAL SPARE PARTS		: \$ 3,230.00	
TOTAL LABOUR CHARGES		: \$ 2,172.00	
GRAND TOTAL		: \$ 5,402.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ly
Surveyed Date : 14/06/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised , 03 Days

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant