

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0681/2018/PH  
**Date** : 12-Jun-18

**Vehicle IN workshop. Kindly arrange for survey.**

**Your insured vehicle is** : SLP 570 U

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Tan Swee Yong  
**Address** : 23 Hillview Avenue  
#01-04  
Singapore 669557

**Telephone** : HP +65 97954993  
**Type of Claim** : Own Damage Claim  
**Policy No.** : 151781  
**Vehicle No** : **SLS 2008 Z**  
**Model Code** : Audi A3 1.0 TFSI  
**Model / Year** : Sep-17  
**Engine No** : CHZ 512202  
**Chassis No** : WAUZZZ8V0J1006701  
**Mileage** : -  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 10-Jun-18  
**Place of Accident** : Slip road from KJE to Woodlands road

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLS 2008 Z.

<u>S/N</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer rear parking aid.Check function.	S/N \$ 280.00	
2	To dismantle and renew rear bumper and rear spoiler.Re-organise rear crash management components.Reinstall all parts removed	\$ 900.00	
3	To respray rear bumper	\$ 800.00	
4	To carry out diagnostic check	S/N \$ 192.00	
	<b>LABOUR CHARGES</b>	<b>: \$ 2,172.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLS 2006 Z.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	BUMPER	\$ 1,697.00	
2	FIXING PARTS FOR BUMPER	\$ 166.00	
3	SPOILER	\$ 206.00	
4	SIDE REINFORCEMENT	\$ 501.00	
5	SENSOR	2 \$ 421.00	
6	BRACKET - LH	\$ 23.00	
7	BRACKET- RH	\$ 24.00	
8	GUIDE SECTION - LH	\$ 57.00	
9	GUIDE SECTION - LH	\$ 14.00	
10	GUIDE SECTION - RH	\$ 14.00	
11	GUIDE SECTION - RH	\$ 57.00	
12	LOCKING MECHANISM	\$ 50.00	
	<b>TOTAL SPARE PARTS</b>	: \$ 3,230.00	
	<b>TOTAL LABOUR CHARGES</b>	: \$ 2,172.00	
	<b>GRAND TOTAL</b>	: \$ 5,402.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** :  
**Surveyed Date** :  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant