

ASS. REC. BY:

REF:

CS/EG18010697/KIND3ⁿ²

Special Instruction:

Surveyor:

KALVIN

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGI

Date/Time:

12/6/18 @ 10:35am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8HC 6008D

Insured:

XD 4918X

at Workshop m/s

Premier taxis

Tel:

6544 6682

of

23 Changi South Ave 2 #03-02

Policy No:

Claim No:

XD 4918X / SL / pl

Sum Insured:

Excess:

Make of Veh:

D.O.A.

09/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

10:54am @ 12/6/18

Person Contacted:

Gary

Vehicle

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 6008D - CR6 / II 18006315 / Rpm3g2

DA: 11/11/15

XD 4918X - NA / IN 113011207 / m2

DA: 240613

13/6/18

Email preli revised to Pei Li

Kahn

RCE

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured _____

Excess _____

(Client's Record)

Make of Veh. _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt. Consistent? Yes or No

GIA / PR Seen Consistent? Yes or No

Est. Repairs days Res. Yes or No

Lump Sum % 3 Val. Yes or No

CA / REV / REP. / 24 HRS

Vehicle IN / OUT

Date: _____ Person Contacted: _____

SHC 6008 D

6 Jun 2014

M Car / M Cycle / Bus / Van / Lorry / Trailer / Mover /

Truck / Trailer or

Make

KIA optima

168r

Colour

Silver

0 Std / NI / NA

Reg. No.

428991

0 Std / NI / NA

Eng. No.

KNA6M414MES4 63200

Gen. Cond. Good / Fair / Poor / Broken

Steering In order / Jammed / Loose

Brake In order / Jammed / Loose

Mod. Nil / S/Rim / STD / Alloy

Tyre Size: F:

205/65R16

R:

BS / DUN / EXNOVA / GY / FS / SUMI /

TOYO / YOKO or

Achilles

Front

R. Bal. 7 mm

L. Bal. 7 mm

D.O.A. 9/6/8

Survey held at

Premier

Des. of Damages: Fnt / Rear / Top / Bottom

O/S Bdy

True UIC / Chassis frame

Relative to collision

Date / Time: _____ Action / Instruction

20/6/8 Contacted 468750 / 7 Rps. (Reel 8347.50, 5490)

Eng.
45

RECEIVED 21 JUN 20

File Time: File Pass to:



Prel. Report



Final Report

File Time: File Return to:

21/6- typist

Add Fee:



Site Insp. US



Interview US



Photo US



Witness US

Report Format

TP

Lump Sum / LB / LS

LS \$7050p

350




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI18010697/K1vd3	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 12-06-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 4918X	Veh. Inspected	SHC 6008D	
Policy No.		Coverage (\$)	0.00	
Claim No.	XD4918X/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	12/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/06/2018	Inspection Date	12/06/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: XD4918X/SL/pl

Our ref: CS/EGI18010697/K1vd3

Date : 13/6/2018

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SHC 6008D


We thank you for your instruction on 12/6/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12/6/2018 at the premises of M/s PREMIER AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$14,866.50
Revised Estimate Amount	: S\$5,849.30
"Check" Items Amount	: S\$2,516.40
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s body.



Comments/Present Status:

Damages Consistent

Yours faithfully,

KALVIN ANG

Automotive Assessor / Investigator

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 13 June 2018 1:25 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR; 'Yee Pei Li'
Subject: RE: XD4918X / TP : SHC6008D/LKK / DOA : 09/06/2018
Attachments: SHC 6008D PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SHC 6008D
Date of survey: 12/6/2018
Number of days :7 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 12 June 2018 11:20 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; 'Yee Pei Li' <peili.yee@ergo.com.sg>
Subject: RE: XD4918X / TP : SHC6008D/LKK / DOA : 09/06/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Tuesday, 12 June 2018 10:35 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>
Subject: OI : XD4918X / TP : SHC6008D/LKK / DOA : 09/06/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **PREMIER TAXIS PTE LTD.**

ADDRESS : 23 CHANGI SOUTH AVE 2
#01-02
SINGAPORE 486443

PERSON TO CONTACT : GARY SHI @ 6544 6682 / 6214 8880 EXT 68

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 12 June 2018 10:35 AM
To: 'admin-d@lkkauto.com'
Cc: 'ASSIGNMENTS@LKKAUTO.COM'
Subject: OI : XD4918X / TP : SHC6008D/LKK / DOA : 09/06/2018
Attachments: XD4918X - SAS.pdf; SHC6008D - SAS.pdf; SHC6008D - PRS FORM n SAS.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **PREMIER TAXIS PTE LTD.**

ADDRESS : 23 CHANGI SOUTH AVE 2
#01-02
SINGAPORE 486443

PERSON TO CONTACT : GARY SHI @ 6544 6682 / 6214 8880 EXT 68

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 12.06.2018
Our Reference: XD 4918X/SL/pl
Your Reference: SHC 6008D

Sent via Fax

or

Email

weedek.goh@premiertaxi.com /
gary.shi@premiertaxi.com /
vincent.chua@premiertaxi.com

To: PREMIER AUTOMOTIVE SERVICES PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SHC 6008D
Insured's Vehicle: XD 4918X
Date Of Accident: 09.06.2018


We acknowledge receipt of your request for PRS on: 11.06.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input checked="" type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us to date.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

Text size + -

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
Owner ID Type: Company
Owner Name: PREMIER TAXIS PTE. LTD.
Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
Mailing Address: -
Birth Date: -

Vehicle Particulars

Vehicle No.: SHC6008D
Previous Vehicle No.: -
Effective Date of Ownership: 06 Jun 2014
Original Regn Date: 06 Jun 2014
Registration Date: 06 Jun 2014
Year of Manufacture: 2013
Vehicle Type: Public Transport Taxi (Motor Car)
Vehicle Scheme: Taxi (Company)
Vehicle Attachment 1: Air-Con (Taxi)
Vehicle Attachment 2: -
Vehicle Attachment 3: -
Vehicle Make: KIA
Vehicle Model: OPTIMA 1.7(A) DIESEL
Primary Colour: Silver
Secondary Colour: -
Passenger Capacity: 4
Chassis No.: KNAGM414ME5463210
Engine No.: D4FDDH309685
Engine Capacity/Power Rating: 1685 cc / -
Maximum Power Output: 100.0 kW (134 bhp)
Propellant: Diesel
Max Unladen Weight: 1584 kg
Maximum Laden Weight: 2050 kg
Open Market Value: \$19,996.00
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 05 Jun 2022
Minimum PARF Benefit: \$7,497.00
No. of Transfers: 0
IU Label No.: 1050527846
COE No.: 2014060601001170E
COE Expiry Date: 05 Jun 2022
COE Category: A - Car (up to 1600cc & 97kW (130bhp))
COE Registration Category: A - Car (up to 1600cc & 97kW (130bhp))

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

12-Jun-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6008 D

1 pc	o/s head lamp	X <i>sun</i>	\$ 1,028.00
1 pc	Front bumper emblem	<i>sun</i>	\$ 44.00
1 pc	Front bumper	<i>Repl</i>	\$ 531.00
1 pc	Front bumper o/s side retainer	X <i>sun</i>	\$ 16.00
1 pc	Front o/s fender	<i>Repl</i>	\$ 384.00
1 pc	Front o/s fender inner shield	<i>sun</i>	\$ 120.00
1 pc	Front o/s lower arm	<i>Repl</i>	\$ 439.00
1 pc	Front o/s shock absorber	<i>Repl</i>	\$ 330.00
1 pc	Front o/s ball joint	<i>Repl</i>	\$ 59.00
1 pc	Front o/s tie rod end	<i>Repl</i>	\$ 61.00
1 pc	Front o/s knuckle bearing	<i>Repl</i>	\$ 157.00
1 pc	Front o/s stabilizer link	<i>Repl</i>	\$ 86.00
1 pc	Front o/s knuckle arm	<i>Repl</i>	\$ 547.00
1 pc	Front o/s rim	<i>Repl</i>	\$ 246.00
2 pcs	Front o/s wheel cover @ \$116.00	<i>17</i>	\$ 232.00
1 pc	Front o/s door	<i>Repl</i>	\$ 765.00
1 pc	Front o/s door lock	X <i>sun</i>	\$ 289.00
1 pc	Front o/s door inner trim	X <i>sun</i>	\$ 853.00
1 pc	Front o/s door motor	<i>sun</i>	\$ 308.00
1 pc	Front o/s door regulator gear	<i>Repl</i>	\$ 249.00
2 pcs	Front o/s door hinge @\$34.00	<i>Repl</i>	\$ 68.00
1 pc	Front o/s door checker	<i>Repl</i>	\$ 44.00
1 pc	Front o/s door outer handle	X <i>sun</i>	\$ 49.00
1 pc	Front o/s door outer moulding	X <i>sun</i>	\$ 73.00
1 pc	Rear o/s door	<i>Repl</i>	\$ 791.00
1 pc	Rear o/s door lock	X <i>sun</i>	\$ 289.00
1 pc	Rear o/s door inner trim	X <i>sun</i>	\$ 781.00
1 pc	Rear o/s door motor	<i>sun</i>	\$ 270.00
1 pc	Rear o/s door regulator gear	<i>Repl</i>	\$ 290.00
2 pc	Rear o/s door hinge @\$34.00	<i>Repl</i>	\$ 68.00
1 pc	Rear o/s door checker	<i>Repl</i>	\$ 44.00
1 pc	Rear o/s door outer handle	X <i>sun</i>	\$ 49.00
1 pc	Rear o/s door outer moulding	X <i>sun</i>	\$ 73.00

12-Jun-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6008 D

1 pc	Rear o/s fender	X repair	\$	1,205.00
1 pc	Rear o/s fender inner shield	X see	\$	120.00
1 pc	Rear windscreen moulding	X m	\$	87.00
			\$	11,045.00
		Less 10%	\$	1,104.50
			\$	9,940.50

S/NETT

1 set	Front o/s fender inner shield clips	an		
1 set	Front bumper clips	an		
1 pc	Front o/s fender sticker	X "		
1 set	o/s door sticker	an		
1 pc	Rear o/s door sticker	an		
1 pc	Sealant	X "		
		1 Calini 10/11/14		
		12/6/18 1375 hrs.		
		7 Day		
		After Repair Lot		
	Sundry		\$	50.00 20
	Towing Fee		\$	50.00 —
	To check wheel alignment x 2		\$	160.00 60
	To dismantle and replace front o/s undercarriage		\$	250.00 150
	To dismantle and refit the inner component of front o/s door into new shell door		\$	150.00 50
	To dismantle and refit the inner component of Rear o/s door into new shell door		\$	150.00 50
	To dismantle and refit the rear windscreen		\$	120.00 X "
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 50
	To labour charge for dismantle and renew the accident damaged parts. To cut/heat and weld on the rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the Rear bumper, o/s door centre pillar, front o/s windscreen pillar etc		\$	1,400.00 1000
	To putty and spray painting on front bumper, front o/s fender, front o/s door, rear o/s door, o/s centre pillar, front o/s windscreen pillar, o/s rocker panel, rear o/s fender, rear bumper, o/s mirror cover		\$	1,800.00 1130
	To apply rustproofing on the repaired and replaced panels.		\$	300.00 50
			\$	14,866.50

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

15,397.50

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____


PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

20-Jun-18

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6008 D

1 pc	o/s mirror Assy		\$	590.00
			Less 10%	\$ 59.00
				<hr/>
			\$	531.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.**




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18010697/K1vd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 25-06-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 4918X	Veh. Inspected	SHC 6008D	
Policy No.		Coverage (\$)	0.00	
Claim No.	XD4918X/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	12/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KNAGM414ME5463210	Colour	SILVER	
Odometer	428991	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	ACHILLES	7 mm	
L/H Front Tyre	205/65 R16	ACHILLES	7 mm	
R/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
L/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/06/2018	Inspection Date	12/06/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6008D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	O/S HEAD LAMP	SERVICEABLE	1,028.00	-
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
1	FRONT BUMPER	DEFORMED	531.00	531.00
1	FRONT BUMPER O/S SIDE RETAINER	SERVICEABLE	16.00	-
1	FRONT O/S FENDER	DENTED	384.00	384.00
1	FRONT O/S FENDER INNER SHIELD	TORN	120.00	120.00
1	FRONT O/S LOWER ARM	BENT	439.00	439.00
1	FRONT O/S SHOCK ABSORBER	BENT	330.00	330.00
1	FRONT O/S BALL JOINT	BENT	59.00	59.00
1	FRONT O/S TIE ROD END	BENT	61.00	61.00
1	FRONT O/S KNUCKLE BEARING	BENT	157.00	157.00
1	FRONT O/S STABILIZER LINK	BENT	86.00	86.00
1	FRONT O/S KNUCKLE ARM	BENT	547.00	547.00
1	FRONT O/S RIM	BENT	246.00	246.00
2	FRONT O/S WHEEL COVER @\$116.00	CRACKED	232.00	232.00
1	FRONT O/S DOOR	DENTED	765.00	765.00
1	FRONT O/S DOOR LOCK	SERVICEABLE	289.00	-
1	FRONT O/S DOOR INNER TRIM	SERVICEABLE	853.00	-
1	FRONT O/S DOOR MOTOR	SHATTERED	308.00	308.00
1	FRONT O/S DOOR REGAULATOR GEAR	CRACKED	249.00	249.00
2	FRONT O/S DOOR HINGE @\$34.00	BENT	68.00	68.00
1	FRONT O/S DOOR CHECKER	BENT	44.00	44.00
1	FRONT O/S DOOR OUTER HANDLE	SERVICEABLE	49.00	-
1	FRONT O/S DOOR OUTER MOULDING	SERVICEABLE	73.00	-
1	REAR O/S DOOR	DENTED	791.00	791.00
1	REAR O/S DOOR LOCK	SERVICEABLE	289.00	-
1	REAR O/S DOOR INNER TRIM	SERVICEABLE	781.00	-
1	REAR O/S DOOR MOTOR	SHATTERED	270.00	270.00
1	REAR O/S DOOR REGAULATOR GEAR	CRACKED	290.00	290.00
2	REAR O/S DOOR HINGE @\$34.00	BENT	68.00	68.00
1	REAR O/S DOOR CHECKER	BENT	44.00	44.00

Report Ref No. CS/EGI18010697/K1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR O/S DOOR OUTER HANDLE	SERVICEABLE	49.00	-
1	REAR O/S DOOR OUTER MOULDING	SERVICEABLE	73.00	-
1	REAR O/S FENDER	TO REPAIR SEE LABOUR	1,205.00	-
1	REAR O/S FENDER INNER SHIELD	SERVICEABLE	120.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	87.00	-
1	O/S MIRRO ASSY (ADDITIONAL)	BROKEN	590.00	590.00
	LESS 10% DISCOUNT		-1,163.50	-672.30
			10,471.50	6,050.70
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT O/S FENDER INNER SHIELD CLIPS (SN)	NECESSARY	28.00	28.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	FRONT O/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	SET O/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	REAR O/S DOOR STICKER (SN)	NECESSARY	60.00	60.00
1	SEALANT (SN)	NOT NECESSARY	50.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			366.00	256.00
	<u>LABOUR</u>			
	TOWING FEE.		50.00	50.00
	TO CHECK WHEEL ALIGNMENT.		160.00	60.00
	TO DISMANTLE AND REPLACE FRONT O/S UNDERCARRIAGE.		250.00	150.00
	TO DISMANTLE AND REFIT THE INNER COMPONENT OF FRONT O/S DOOR INTO NEW SHELL DOOR.		150.00	50.00
	TO DISMANTLE AND REFIT THE INNER COMPONENT OF REAR O/S DOOR INTO NEW SHELL DOOR.		150.00	50.00
	TO DISMANTLE AND REFIT THE REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO CUT/HEAT AND WELD ON THE REAR O/S FENDER. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE REAR BUMPER, O/S DOOR CENTRE PILLAR, FRONT O/S WINDSCREEN PILLAR ETC.		1,400.00	1,000.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER, FRONT O/S FENDER, FRONT O/S DOOR, REAR O/S DOOR, O/S CENTRE PILLAR, FRONT O/S WINDSCREEN PILLAR, O/S ROCKER PANEL, REAR O/S FENDER, REAR BUMPER, O/S MIRROR COVER.		1,800.00	1,130.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		300.00	50.00
			4,560.00	2,590.00
GRAND TOTAL			15,397.50	8,896.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,050.00

Report Ref No. CS/EGI18010697/K1vd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.