

ASS. REC. BY:

REF: CS/FCI18010705/Utber

Special Instruction:

Surveyor: Marcus  
aws

ASSIGNMENT (Office)

From (Person): May chua of FCI

Date/Time: 13/6/18 @ 5.56pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGU 9200L

Insured: SHA 4890X

at Workshop m/s Yew Tee Automobile

Tel: 67023113

of 25 kaki Bkt Rd 4 # 01-61

Policy No: \_\_\_\_\_ Claim No: D18004633MFSH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 08/06/2018  
(Client's Record)

CA / REV / REP. / REV 24 HRS 'Ds'

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 8.52am @ 13/6/18 Person Contacted: May

Vehicle IN / OUT

| Date/Time | Action/Instruction ( ) Estimate                   |
|-----------|---|
|           | SGU 9200L - X                                     |
|           | SHA 4890X - NS / INC 18002453 / MHbe2 OCA: 050218 |
|           |   |
|           |   |
|           |   |
|           |   |

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

Fail

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGU 9202

at Workshop m/s Yew Lee (Coker)

of \_\_\_\_\_

Insured: SHA 4890X

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value: 28

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 63841

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SGU 9202 Yr Regn: SI 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA 7

Make: Toyota Rush C.C. 1495

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 338388 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: J200E0010071

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 215/65R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Delinte

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 8/6/18 D.O.I. 12/6/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction coe until 28-5-2022

3yrs 11mths. LTA 1995-3 next box 7

12/6/18 consub L/S # 7200 with 5 hours.

(Red: 4711.76 : 39%)

RECEIVED 2 JUN 2018

Date/Time, File Pass to?

: Preli. Report

1) 22/6 Typist

: Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 12

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

Photos

Others

TOTAL

|        |
|--------|
| 170+15 |
| 50     |
| 50     |
| 124    |
|        |
| 409    |

Report Format: TP

Lump Sum / I.B.I.: (\$ 7000 - )

**MOTOR SURVEY ASSIGNMENT**

|                           |   |                                      |
|---------------------------|---|--------------------------------------|
| <b>Date</b>               | 11-06-2018  | <b>Our Ref No.</b> D18004633MFSH     |
| <b>Accident Date</b>      | 08-06-2018  | <b>Claim Type.</b> Third Party       |
| <b>Insured Vehicle</b>    | SHA4890X  | <b>Third Party Vehicle.</b> SGU9200L |
| <b>Survey Location</b>    | SYNERGY@KB, 25 KAKI BUKIT ROAD 4, #01-61,                   |                                      |
| <b>Contact Person.</b>    | MAY   |                                      |
| <b>Contact No.</b>        | 67023113/ 0   | <b>Fax No.</b> 0                     |
| <b>Survey Type</b>        | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED: |                                      |
| <b>Appointed Surveyor</b> | LKK AUTO CONSULTANTS PTE LTD                                |                                      |
| <b>Contact Person</b>     | NA  | <b>Fax No.</b> 68416315              |
| <b>Contact Number.</b>    | NA  |                                      |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                          |                                    |                                |
|--------------------------|------------------------------------|--------------------------------|
| <b>Cc : Workshop</b>     | YEW TEE AUTOMOBILE<br>TECH PTE LTD | <b>Attention.</b> NIL          |
| <b>Cc : TP Solicitor</b> | NA                                 | <b>TP Solicitor Fax No.</b> NA |
| <b>Officer Incharge</b>  | MAY CHUA                           |                                |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241316)



PRI Documents



Close



## PRI Header Details

|                          |   |  |   |                                 |              |
|--------------------------|---|--|---|---------------------------------|--------------|
| <b>Claim No</b>          | D18004633MFSH   | <b>Policy No</b>                             | D-18088936MFSH  | <b>Claimant S.No &amp; Name</b> | 1 & YEW TEE  |
| <b>Workshop Name</b>     | YEW TEE AUTOMOBILE TECH PTE LTD<br>(Contact Person : MAY) | <b>Survey Location &amp; Contact Details</b> | SYNERGY@KB, 25 KAKI BUKIT ROAD 4, #01-61,<br><b>Mobile: 0 , Phone: 67023113 , Fax: 0</b><br><b>EmailId: UTAUTO@SINGNET.COM.SG</b> |                                 |              |
| <b>Our Surveyor</b>      | LKK AUTO CONSULTANTS PTE LTD                              | <b>Instructions To Surveyor</b>              | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM   |                                 |              |
| <b>Insured Name</b>      | COMFORT TRANSPORTATION PTE LTD                            | <b>Insured Vehicle No</b>                    | SHA4890X  | <b>TP Vehicle No</b>            | SGU9200L     |
| <b>PRI Recieved Date</b> | 11-06-2018 08:04:00 PM                                    | <b>Surveyor Appointed Date</b>               | 12-06-2018 05:55:39 PM  | <b>Surveyor Accept Date</b>     | 13-06-2018 1 |

## Survey Report Upload

|                                    |                      |                             |            |                                |  |
|------------------------------------|----------------------|-----------------------------|------------|--------------------------------|--|
| <b>Surveyor Inspection Date *:</b> | <input type="text"/> | <b>Surveyor Report Date</b> | 13-06-2018 | <b>Upload Survey Report *:</b> | <input type="button" value="Choose File"/> |
|------------------------------------|----------------------|-----------------------------|------------|--------------------------------|--|

## Vehicle Particulars

|                  |   |                       |  |                |  |
|------------------|---|-----------------------|--|----------------|--|
| <b>Make</b>      | <input type="text" value="Please Select Make"/> | <b>Model</b>          | <input type="text" value="Please Select Model"/> | <b>Year</b>    | <input type="text" value="Select Year"/> |
| <b>Chasis No</b> | <input type="text"/>                            | <b>Engine No</b>      | <input type="text"/>                             | <b>Mileage</b> | <input type="text"/>                     |
| <b>Color</b>     | <input type="text"/>                            | <b>Cubic Capacity</b> | <input type="text"/>                             |                |  |

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                |
|----------------------------|--------------------------------|
| Date Of Report             | 08/06/2018 15:06               |
| Date Of Accident           | 08/06/2018 11:30               |
| Exact Location Of Accident | CHANGI AIRPORT TERMINAL 2 BLVD |
| Country/State of Loss      | SINGAPORE                      |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SGU9200L             |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | LIM KIM CHEONG       |
| NRIC No                     | S2626384J            |
| Email Address               | NOEMAIL              |
| Mobile Phone No             | (LOCAL) +65-92704595 |
| Alternative Phone No        | OFFICE-92704595      |

### Vehicle Particulars

|  |             |
|--|-------------|
| Manufacturer   | TOYOTA      |
| Model  | RUSH 1.5 A  |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO          |
| If No, Please state action to be taken                                       | THIRD PARTY |
| Vehicle Category   | PRIVATE CAR |

### Insurance Company

|                           |  |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage          | COMPREHENSIVE                          |
| Fleet Policy              | NO                                     |
| Policy Number             | 5100730466                             |
| Cover Note Number         |  |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | LIM KIM CHEONG        |
| NRIC No              | S2626384J             |
| Date Of Birth        | 04/11/1961            |
| Occupation           | INDOOR                |
| Date Of Driving Pass | 09/03/1992            |
| Driving Experience   | 26 YEARS AND 2 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-92704595  |
| Fax Number           |                       |
| Contact Number       | OFFICE-92704595       |
| EEmail Address       | NOEMAIL               |

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

|   |                                      |
|---|--------------------------------------|
| Name  | PANG AI PENG                         |
| Approximate Age                                     |                                      |
| Injuries Sustain                                    |                                      |
| Injured person in which vehicle?                    | SGU9200L                             |
| Were seat belts worn?                               | YES                                  |
| Was this injured conveyed to hospital by ambulance? | YES                                  |
| Address   | APT BLK 111 RIVERVALE WALK<br>#07-11 |
| Postcode  | 540111                               |

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I front was a traffic junction and it is going to turn red.  
I slowing down my car. Suddenly CAR B hit into my rear  
side.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                |
|----------------------------|--------------------------------|
| Date Of Report             | 08/06/2018 15:06               |
| Date Of Accident           | 08/06/2018 11:30               |
| Exact Location Of Accident | CHANGI AIRPORT TERMINAL 2 BLVD |
| Country/State of Loss      | SINGAPORE                      |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SGU9200L             |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | LIM KIM CHEONG       |
| NRIC No                     | S2626384J            |
| Email Address               | NOEMAIL              |
| Mobile Phone No             | (LOCAL) +65-92704595 |
| Alternative Phone No        | OFFICE-92704595      |

### Vehicle Particulars

|  |             |
|--|-------------|
| Manufacturer   | TOYOTA      |
| Model  | RUSH 1.5 A  |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO          |
| If No, Please state action to be taken                                       | THIRD PARTY |
| Vehicle Category   | PRIVATE CAR |

### Insurance Company

|                           |  |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage          | COMPREHENSIVE                          |
| Fleet Policy              | NO                                     |
| Policy Number             | 5100730466                             |
| Cover Note Number         |  |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | LIM KIM CHEONG        |
| NRIC No              | S2626384J             |
| Date Of Birth        | 04/11/1961            |
| Occupation           | INDOOR                |
| Date Of Driving Pass | 09/03/1992            |
| Driving Experience   | 26 YEARS AND 2 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | +65-92704595          |
| Fax Number           |                       |
| Contact Number       | OFFICE-92704595       |
| EMail Address        | NOEMAIL               |

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name PANG AI PENG  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SGU9200L  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance? YES  
Address APT BLK 111 RIVERVALE WALK #07-11  
Postcode 540111

**DETAILS OF INJURED PERSON 2**

Name PASSENGER 2  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SGU9200L  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance?  
Address  
Postcode

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I front was a traffic junction and it is going to turn red.  
I slowing down my car. Suddenly CAR B hit into my rear  
side.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20180608/2130

Police Station Of Origin:  
Changi N.P.C  
9 Simei Street 2 SINGAPORE 529914  
Tel No: 1800-5872999

2 of 4

Report No. T/20180608/2130

## CONTINUATION OF REPORT

| Details of Person Involved        |                         |  |                                      |
|-----------------------------------|-------------------------|--|--------------------------------------|
| Any Pedestrian Involved: No       |                         |  |                                      |
| No. of Pedestrians Injured: NIL   |                         | Use of Pedestrian Crossing: NA         |                                      |
| Name                              | HANG AI PENG            | ID No.                                 | S1717320J                            |
| Related Vehicle                   | SGU9200L (Car)          | Contact No.                            | 96561512                             |
| Hospital/Clinic                   | CHANGI GENERAL HOSPITAL | Class of Driving Licence & Expiry Date | Class: NIL<br>Date of Expiry: NIL    |
| Date Treatment                    | 08/06/2018              | Date Discharge                         | 08/06/2018                           |
| No. of Days granted Medical Leave | 07                      | Degree of Injury                       | Slight                               |
| Driver                            |                         |  |                                      |
| Name                              | LIM KIM CHEONG          | ID No.                                 | S2626384J                            |
| Related Vehicle                   | NIL                     | Contact No.                            | 92704595                             |
| Hospital/Clinic                   | NIL                     | Class of Driving Licence & Expiry Date | Class: 2B,3,4<br>Date of Expiry: NIL |
| Date Treatment                    | NIL                     | Date Discharge                         | NIL                                  |
| No. of Days granted Medical Leave | NIL                     | Degree of Injury                       | NIL                                  |

**Brief Details.**

I picked up a passenger as a Grab hitch booking from Blk 9F Yuan Ching Road and was headed to Changi Airport. While I was driving my car along Airport Boulevard just outside Terminal 2, My wife, Hang Ai Peng sat in the front passenger while my other passenger sat behind. The traffic light turned red just outside terminal 2, I was on the most right lane and stopped my car just before the white line. After which I felt an impact from the rear. A taxi collided into my rear. After the accident I got out to make a check and exchanged particulars. My passenger went to Changi Airport to catch her flight, at that point of that time she felt giddy.

The taxi driver claimed that I jammed my brakes suddenly however I was stationary for quite awhile as the traffic light was red. An ambulance came and conveyed my wife to the hospital.

Particulars of my passenger:  
Tanprasert Watcharaphon  
S7489139Z  
Blk 9F Yuan Ching Road # 08-64

Particulars of the taxi driver:  
Abdul Mohamed S/O T H Abdul Rahim  
S6898081Z



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Changi N.P.C  
9 Simei Street 2 SINGAPORE 529914  
Tel No: 1800-5872999



T/20180608/2130

3 of 4

Report No. T/20180608/2130

CONTINUATION OF REPORT

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

| <b>Vehicle Owner Particulars</b>  |                          |
|---|--------------------------|
| Owner ID Type:  | Singapore NRIC           |
| Owner ID:   | 6384J                    |
| <b>Vehicle Details</b>  |                          |
| Vehicle No.:  | SGU9200L                 |
| Vehicle to be Exported:   | No                       |
| Intended De-registration Date:  | 20 Jun 2018              |
| Vehicle Make:   | TOYOTA                   |
| Vehicle Model:  | RUSH 1.5 A               |
| Primary Colour:   | Black                    |
| Manufacturing Year:   | 2006                     |
| Engine No.:   | 3SZ1718405               |
| Chassis No.:  | J200E0010071             |
| Maximum Power Output:   | 80.0 kW (107 bhp)        |
| Open Market Value:  | \$15,888.00              |
| Original Registration Date:   | 29 May 2007              |
| First Registration Date:  | 29 May 2007              |
| Transfer Count:   | 2                        |
| Actual ARF Paid:  | \$17,477.00              |
| <b>Intended PARF Rebate Details</b>   |                          |
| PARF Eligibility:   | Forfeited                |
| PARF Eligibility Expiry Date:   | -                        |
| PARF Rebate Amount:   | \$0.00                   |
| <b>Intended COE Rebate Details</b>  |                          |
| COE Expiry Date:  | 28 May 2022              |
| COE Category:   | A - Car (1600cc & below) |
| COE Period(Years):  | 5                        |
| PQP Paid:   | \$25,333.00              |
| COE Rebate Amount:  | \$19,953.00              |
| <b>Total Rebate Amount:</b>   | <b>\$19,953.00</b>       |
| <b>Message</b>  |                          |
| Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. |                          |

The information contained herein is correct as at 13 Jun 2018

OK



Toyota Rush

Price Range ▼

Depreciation ▼

&gt; 10 year(s) ▼

Vehicle Type ▼

Home » Used Cars » Cars Connect » Toyota Rush 1.5A (COE till 01/2022)

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Car Leasing

**CL LEASING**  
YOUR PREFERRED CAR LEASING  
OPTION IN SINGAPORE

6769 7117 8720 5000 8720 8000

## Toyota Rush 1.5A (COE till 01/2022)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

## Car Details

**Price** \$28,800**Depreciation** \$7,920 /yr**Reg Date** 14-Feb-2007  
(3yrs 7mths 18days COE left)**Manufactured** 2006**Mileage** 118,000 km (10.4k /yr)**Transmission** Auto**Engine Cap** 1,495 cc**Road Tax** \$750 /yr**Power** 80.0 kW (107 bhp)  
View specs of the Toyota Rush (2006-2013)**Curb Weight** 1,150 kg**Features** Powerful, Reliable Yet Fuel Efficient 4 Cylinder 16 Valve  
Toyota VVTi Engine, ABS, Dual Airbags, Reliable 4 Auto  
Transmission, Folding Mirrors.**Accessories** Sporty Black Rush With Black Sporty Leather Seats  
That Is Like New, Sports Rims, Reverse Sensors, Fog  
Lamps, Remote Control.**Description** Wow! It's A Great Unit! 1 Single Owner All This While,  
Low Mileage Done! High Paper Value Means Low, Fixed  
And Safe Depreciation, Amazing Condition, Don't Look  
Like A More Than 10 Years Old Car, Low Down  
Payment And Low Monthly With Low Interest Rates,  
Serviced On Time Regularly, A Popular Sporty Compact  
SUV That Is Fun And Stylish! Very Clean Neat Interior,  
Appointment To View Please!**COE** \$25,323

## Seller Infor

## Company

## Address

## Location

## Contact Perso

## Useful Servi

Compare



toyota rush Price Range Depreciation > 10 year(s) Vehicle Type

Home » Used Cars » 360 VR Cars » Toyota Rush 1.5A (COE till 04/2022)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Leasing

**CL LEASING**  
YOUR PREFERRED CAR LEASING  
OPTION IN SINGAPORE

6769 7117 8720 5000 8720 8000

Toyota Rush 1.5A (COE till 04/2022)

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions

Car Details

|                      |   |   |
|----------------------|---|---|
| <b>Price</b>         | \$26,000  |   |
| <b>Depreciation</b>  | \$6,700 /yr   | ? |
| <b>Reg Date</b>      | 30-Jun-2007<br>(3yrs 10mths 17days COE left)  |   |
| <b>Manufactured</b>  | 2007  | ? |
| <b>Mileage</b>       | -   |   |
| <b>Transmission</b>  | Auto  |   |
| <b>Engine Cap</b>    | 1,495 cc  |   |
| <b>Road Tax</b>      | \$750 /yr   | ? |
| <b>Power</b>         | 80.0 kW (107 bhp)<br>View specs of the Toyota Rush (2006-2013)  |   |
| <b>Curb Weight</b>   | 1,150 kg  | ? |
| <b>Features</b>      | 1.5L 4 Cylinder 16 Valves DOHC VVT-i Engine, Fuel Economical, ABS, Dual SRS Airbags, 4 Speed Automatic Transmission 16 Valves Engine. |   |
| <b>Accessories</b>   | All Wear N Tear Parts Replaced With Receipt To Proof. No Repairs Needed.  |   |
| <b>Description</b>   | Road Tax Renewed Till Dec 2018, Well Maintained, Well Kept Interior, Low Fuel Consumption,view To Believe, Viewing By Appointment.    |   |
| <b>COE</b>           | \$25,115  | ? |
| <b>OMV</b>           | \$16,117  | ? |
| <b>ARF</b>           | \$17,729  | ? |
| <b>Dereg Value</b>   | \$19,500 as of today (change)   | ? |
| <b>No. of Owners</b> | 3   | ? |



Seller Infor

Company

Address

Location

Office No

Contact Perso

Compare

**Yew Tee Automobile Tech Pte Ltd** (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61  
Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

**INSURER : FIRST CAPITAL INSURANCE LTD**

**PARTICULARS OF CLAIM**

|                   |                 |                          |                  |
|-------------------|-----------------|--------------------------|------------------|
| Claim Type:       | TP              | Ref. No:                 | YTKB/TP/1806/006 |
| Policy No:        | 5100730466      | Date of Loss:            | 08/01/2018       |
| Vehicle Reg. No.: | <b>SGU9200L</b> | Driveable?               | no               |
| Driver Age:       | 04/11/1961      | Third Party Vehicle No.: | SHA4890X         |
| Any Injuries?     | yes             | Contact No:              | 92704595         |
| Insured/Claimant: | LIM KIM CHEONG  | Driver:                  | LIM KIM CHEONG   |

|                 |                             |                              |            |
|-----------------|-----------------------------|------------------------------|------------|
| Make/Model:     | Toyota, RUSH 1.5A - J200E00 | Vehicle Reg. Date:           | 29/05/2007 |
| Vehicle Colour: | BLACK                       | Engine Number:               | 3SZ1718405 |
| Chassis No:     | J200E0010071                | Odometer:                    |            |
| Total Loss?     | <b>NO</b>                   | Est. Duration of Repair(Day) | 12         |

Description of Accident/loss: HEAD TO REAR  
Remarks: DUE TO THE CAR IS MORE THAN 10YEARS OLD, WE PROPOSE LUMP SUM REPAIR AT THE COST OF \$7500.00 BEFORE GST FOR COR ONLY.  
Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

**COST OF CLAIMS**

|                          | Amount           |
|--------------------------|------------------|
| Parts                    | 8,910.26         |
| Miscellaneous Items      | 396.00           |
| Labour                   | 1,730.00         |
| Paintwork Labour         | 875.00           |
| Towing                   | 0.00             |
| <b>Gross Total(S\$):</b> | <b>11,911.26</b> |
| <b>GST 7.00%(S\$):</b>   | <b>833.79</b>    |
| <b>Nett Amount(S\$):</b> | <b>12,745.05</b> |

This claim is handled by: **Shaun Toh L M**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*not actual*  
*h/w*  
*n/s \$ 7200/2*  
*12/6/18*  
*1207.58*  
*to be paid after rep*

**REPAIR DETAILS**

**Estimates On Parts**

| No.  | Qty | Particulars                                       | Rate                      | Amount         | %Disc  | After Disc      |
|--|-----|---|---------------------------|----------------|--------|-----------------|
| 1  | 1   | REAR TAILGATE <i>50300 1404.10</i>                | 1,460.30                  | 1,460.30       | -25.00 | 1,095.23        |
| 2  | 1   | REAR TAILGATE HINGE TOP <i>but</i>                | 68.50                     | 68.50          | -25.00 | 51.38           |
| 3  | 1   | REAR TAILGATE HINGE BOTTOM <i>but</i>             | 68.50                     | 68.50          | -25.00 | 51.38           |
| 4  | 1   | REAR TAILGATE RUSH EMBLEM <i>ner</i>              | 55.00                     | 55.00          | -25.00 | 41.25           |
| 5  | 1   | REAR SPARE TYRE BRACKET <i>net/ner</i>            | 265.79                    | 265.79         | -25.00 | 199.34          |
| 6  | 1   | REAR SPARE TYRE INNER COVER <i>one</i>            | 385.10                    | 385.10         | -25.00 | 288.83          |
| 7  | 1   | REAR SPARE TYRE OUTER COVER <i>one</i>            | 497.35                    | 497.35         | -25.00 | 373.01          |
| 8  | 1   | REAR TAILGATE INNER BOARD <i>ner</i>              | 485.51                    | 485.51         | -25.00 | 364.13          |
| 9  | 1   | REAR WINDSCREEN GLASS <i>shotter</i>              | 1,320.00                  | 1,320.00       | -25.00 | 990.00          |
| 10   | 1   | REAR WIPER MOTOR <i>11</i>                        | 509.00                    | 509.00         | -25.00 | 381.75          |
| 11   | 1   | REAR WIPER ARM <i>11</i>                          | 129.20                    | 129.20         | -25.00 | 96.90           |
| 12   | 1   | REAR TAILLAMP LH <i>11</i>                        | 428.50                    | 428.50         | -25.00 | 321.38          |
| 13   | 1   | REAR TAILLAMP RH <i>one</i>                       | 428.50                    | 428.50         | -25.00 | 321.38          |
| 14   | 1   | REAR FENDER RH <i>50300/ner</i>                   | 970.20                    | 970.20         | -25.00 | 727.65          |
| 15   | 1   | REAR BUMPER <i>D.S</i>                            | 624.50                    | 624.50         | -25.00 | 468.38          |
| 16   | 1   | REAR BUMPER REFLECTOR RH <i>one</i>               | 68.50                     | 68.50          | -25.00 | 51.38           |
| 17   | 1   | REAR BUMPER SIDE RETAINER LH <i>but</i>           | 55.60                     | 55.60          | -25.00 | 41.70           |
| 18   | 1   | REAR BUMPER SIDE RETAINER RH <i>but</i>           | 55.60                     | 55.60          | -25.00 | 41.70           |
| 19   | 1   | REAR FENDER LH <i>ner</i>                         |                           | 0.00           | -25.00 | 0.00            |
| 20   | 1   | REAR END PANEL <i>B. 50300</i>                    | 519.80                    | 519.80         | -25.00 | 389.85          |
| 21   | 1   | REAR END PANEL TOP GARNISH <i>ner</i>             | 214.90                    | 214.90         | -25.00 | 161.18          |
| 22   | 1   | REAR FENDER INNER SHIELD RH <i>To. 1</i>          | 124.10                    | 124.10         | -25.00 | 93.08           |
| 23   | 1   | REAR EXHAUST PIPE <i>ner</i>                      | 822.60                    | 822.60         | -25.00 | 616.95          |
| 24   | 1   | REAR NUMBER PLATE LAMP <i>one</i>                 | 128.50                    | 128.50         | -25.00 | 96.38           |
| 25   | 1   | REAR TAILGATE RUBBER <i>ner 269.10</i>            | 370.50                    | 370.50         | -25.00 | 277.88          |
| 26   | 1   | REAR DOOR RH                                      |                           | 0.00           | -25.00 | 0.00            |
| 27   | 1   | REAR FLOOR PANEL <i>crumpled/ner</i>              | 409.10                    | 409.10         | -25.00 | 306.83          |
| 28   | 1   | REAR END PANEL INNER MEMBER <i>ner</i>            | 606.00                    | 606.00         | -25.00 | 454.50          |
| 29   | 1   | REAR EXHAUST MOUNTING <i>ner</i>                  | 48.60                     | 48.60          | -25.00 | 36.45           |
| 30   | 1   | REAR TAILGATE LOCK <i>ner</i>                     | 265.79                    | 265.79         | -25.00 | 199.34          |
| 31   | 1   | REAR FENDER QUARTER GLASS C/W MOULDING <i>ner</i> | 494.80                    | 494.80         | -25.00 | 371.10          |
| <p><i>ner fender inner trim o/s dis 395.10</i></p> |     |   |                           |                |        |                 |
|  |     |   | <b>Total Parts (\$\$)</b> | <u>8327.84</u> |        | <u>8,910.26</u> |
|  |     |   |                           | <u>6246.88</u> |        |                 |

**Estimates of Miscellaneous Items**

| No. | Qty | Particulars                                  | Rate                    | Amount     | %Disc | After Disc    |
|-----|-----|--|-------------------------|------------|-------|---------------|
| 1   | 1   | REAR TAILGATE INNER BOARD CLIP <i>ner</i>    | 20.00                   | 20.00      | 0.00  | 20.00         |
| 2   | 1   | REAR WINDSCREEN GLASS SEALANT <i>ner</i>     | 40.00                   | 40.00      | 0.00  | 40.00         |
| 3   | 1   | REAR REVERSE SENSOR <i>shut</i>              | 200.00                  | 200.00     | 0.00  | 200.00        |
| 4   | 1   | REAR END PANEL TOP GARNISH CLIP <i>ner</i>   | 20.00                   | 20.00      | 0.00  | 20.00         |
| 5   | 1   | REAR FENDER INNER SHIELD CLIP <i>ner</i>     | 25.00                   | 25.00      | 0.00  | 25.00         |
| 6   | 1   | REAR NUMBER PLATE <i>but</i>                 | 40.00                   | 40.00      | 0.00  | 40.00         |
| 7   | 1   | REAR FENDER QUARTER GLASS SEALANT <i>ner</i> | 40.00                   | 40.00      | 0.00  | 40.00         |
| 8   | 1   | REAR WIPER BLADE <i>11</i>                   | 11.00                   | 11.00      | 0.00  | 11.00         |
|     |     |  | <b>Sub Total (\$\$)</b> | <u>385</u> |       | <u>396.00</u> |

**Estimates On Labour**

| No. | Qty | Particulars | Rate | Amount | %Disc | After Disc |
|-----|-----|-------------|------|--------|-------|------------|
|-----|-----|-------------|------|--------|-------|------------|

|                                |   |   |          |          |      |                 |     |
|--------------------------------|---|---|----------|----------|------|-----------------|-----|
| 1                              | 1 | To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.   | 100.00   | 100.00   | 0.00 | 100.00          | 60  |
| 2                              | 1 | To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.   | 180.00   | 180.00   | 0.00 | 180.00          | 60  |
| 3                              | 1 | To Remove and Refit Rear Bumper Sensor.   | 80.00    | 80.00    | 0.00 | 80.00           | 50  |
| 4                              | 1 | To Dismantle and Refit Rear Fender Glass.   | 60.00    | 60.00    | 0.00 | 60.00           | ✓   |
| 5                              | 1 | To Dismantle and Refit Rear Windscreen Glass.   | 100.00   | 100.00   | 0.00 | 100.00          | ✓   |
| 6                              | 1 | To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.  | 30.00    | 30.00    | 0.00 | 30.00           | ✓   |
| 7                              | 1 | To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools. | 1,100.00 | 1,100.00 | 0.00 | 1,100.00        | 108 |
| 8                              | 1 | To Transfer Rear Tailgate.  | 80.00    | 80.00    | 0.00 | 80.00           | 60  |
| <b>Gross Labour Cost (S\$)</b> |   |   |          |          |      | <u>1,730.00</u> |     |

#### Estimates On Paint Work Labour

| No.                            | Qty | Particulars  | Rate   | Amount | %Disc | After Disc    |    |
|--------------------------------|-----|--|--------|--------|-------|---------------|----|
| 1                              | 1   | To Carry-Out Body Cavity Preservation.   | 30.00  | 30.00  | 0.00  | 30.00         | ✓  |
| 2                              | 1   | To Supply Spray Terostat Sealant On The Cutting Areas.   | 45.00  | 45.00  | 0.00  | 45.00         | 40 |
| 3                              | 1   | To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available. | 800.00 | 800.00 | 0.00  | 800.00        | ✓  |
| <b>Gross Labour Cost (S\$)</b> |     |  |        |        |       | <u>875.00</u> |    |

< END OF ESTIMATES >

2370  
9000ff  
7200.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |                            |   |
|--|---|----------------------------|---|
| FIRST CAPITAL INSURANCE LTD  |   | Ref : CS/FCI18010705/Utbe2 |   |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877  |   | Date : 29-06-2018          |  |
|  |   | Code : FCI2                |   |
| 1. Policy Particulars :- THIRD PARTY CLAIM   |   |                            |   |
| Insured Veh.   | SHA 4890X   | Veh. Inspected             | SGU 9200L   |
| Policy No.   | D-18088936MFSH  | Coverage (\$)              | 0.00  |
| Claim No.  | D18004633MFSH   | Excess (\$)                | 0.00  |
| Assign From  | MAY CHUA  | Assign Date                | 13/06/2018  |
| 2. Vehicle Particulars & Condition   |   |                            |   |
| Make & Model   | TOYOTA RUSH (A)   | c.c                        | 1495  |
| Engine No.   | HIDDEN  | Year of Reg.               | 2007  |
| Chassis No.  | J200E0010071  | Colour                     | BLACK   |
| Odometer   | 338388  | Steering                   | IN ORDER  |
| Brakes   | IN ORDER  | Modification               | SPORTS RIM  |
| General  | GOOD  |                            |   |
| 3. Conditions of Tyres   |   |                            |   |
|  | Size  | Make                       | Balance   |
| R/H Front Tyre   | 215/65 R16  | DELINTE                    | 6 mm  |
| L/H Front Tyre   | 215/65 R16  | DELINTE                    | 6 mm  |
| R/H Rear Tyre  | 215/65 R16  | DELINTE                    | 6 mm  |
| L/H Rear Tyre  | 215/65 R16  | DELINTE                    | 6 mm  |
| 4. Description of Damages  |   |                            |   |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.   |   |                            |   |
| 5. General Information   |   |                            |   |
| Accident Date  | 08/06/2018  | Inspection Date            | 12/06/2018  |
| Survey held at   | YEW TEE AUTOMOBILE TECH PL<br>BLK 25 KAKI BUKIT ROAD 4<br>#01-61 SYNERGY @ KAKI BUKIT<br>SINGAPORE 417800 |                            |   |
| 5a. Remarks  |   |                            |   |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                            |   |
| 5b. Estimate Days of Repair  |   |                            |   |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | 12 Working Days            |   |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 9200L

| Qty                                | Description of Parts         | Condition              | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|------------------------------|------------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                              |                        |                           |                   |
| 1                                  | REAR TAILGATE                | BADLY DENTED           | 1,460.30                  | 1,404.10          |
| 1                                  | REAR TAILGATE HINGE TOP      | BENT                   | 68.50                     | 68.50             |
| 1                                  | REAR TAILGATE HINGE BOTTOM   | BENT                   | 68.50                     | 68.50             |
| 1                                  | REAR TAILGATE RUSH EMBLEM    | NECESSARY              | 55.00                     | 55.00             |
| 1                                  | REAR SPARE TYRE BRACKET      | BENT / TWISTED         | 265.79                    | 265.79            |
| 1                                  | REAR SPARE TYRE INNER COVER  | CRACKED                | 385.10                    | 385.10            |
| 1                                  | REAR SPARE TYRE OUTER COVER  | CRACKED                | 497.35                    | 497.35            |
| 1                                  | REAR TAILGATE INNER BOARD    | NOT NECESSARY          | 485.51                    | -                 |
| 1                                  | REAR WINDSCREEN GLASS        | SHATTERED              | 1,320.00                  | 1,320.00          |
| 1                                  | REAR WIPER MOTOR             | NOT NECESSARY          | 509.00                    | -                 |
| 1                                  | REAR WIPER ARM               | NOT NECESSARY          | 129.20                    | -                 |
| 1                                  | REAR TAILLAMP LH             | NOT NECESSARY          | 428.50                    | -                 |
| 1                                  | REAR TAILLAMP RH             | CRACKED                | 428.50                    | 428.50            |
| 1                                  | REAR FENDER RH               | BADLY DENTED / BUCKLED | 970.20                    | 970.20            |
| 1                                  | REAR BUMPER                  | DISTORTED              | 624.50                    | 624.50            |
| 1                                  | REAR BUMPER REFLECTOR RH     | CRACKED                | 68.50                     | 68.50             |
| 1                                  | REAR BUMPER SIDE RETAINER LH | BENT                   | 55.60                     | 55.60             |
| 1                                  | REAR BUMPER SIDE RETAINER RH | BENT                   | 55.60                     | 55.60             |
| 1                                  | REAR FENDER LH (NPA)         | TO REPAIR SEE LABOUR   | -                         | -                 |
| 1                                  | REAR END PANEL               | BADLY DENTED           | 519.80                    | 519.80            |
| 1                                  | REAR END PANEL TOP GARNISH   | TWISTED                | 214.90                    | 214.90            |
| 1                                  | REAR FENDER INNER SHIELD RH  | TORN                   | 124.10                    | 124.10            |
| 1                                  | REAR EXHAUST PIPE            | TO REPAIR SEE LABOUR   | 822.60                    | -                 |
| 1                                  | REAR NUMBER PLATE LAMP       | CRACKED                | 128.50                    | 128.50            |
| 1                                  | REAR TAILGATE RUBBER         | TWISTED                | 370.50                    | 269.10            |
| 1                                  | REAR DOOR RH (NPA)           | TO REPAIR SEE LABOUR   | -                         | -                 |
| 1                                  | REAR FLOOR PANEL             | CRUMPLED / BUCKLED     | 409.10                    | 409.10            |

Report Ref No. CS/FCI18010705/Utbe2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts   | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|---------------|---------------------------|-------------------|
| 1   | REAR END PANEL INNER MEMBER  | NO SUCH PARTS | 606.00                    | -                 |
| 1   | REAR EXHAUST MOUNTING  | NOT NECESSARY | 48.60                     | -                 |
| 1   | REAR TAILGATE LOCK   | NOT NECESSARY | 265.79                    | -                 |
| 1   | REAR FENDER QUARTER GLASS C/W MOULDING   | NOT NECESSARY | 494.80                    | -                 |
| 1   | REAR FENDER INNER TRIM O/S   | DISTORTED     | 395.10                    | 395.10            |
|     | LESS 25% DISCOUNT  |               | -3,068.86                 | -2,081.96         |
|     |  |               | 9,206.58                  | 6,245.88          |
|     | <b><u>SPECIAL NETT ITEMS</u></b>   |               |                           |                   |
| 1   | REAR TAILGATE INNER BOARD CLIP (SN)  | NECESSARY     | 20.00                     | 20.00             |
| 1   | REAR WINDSCREEN GLASS SEALANT (SN)   | NECESSARY     | 40.00                     | 40.00             |
| 1   | REAR REVERSE SENSOR (SN)   | SHORTED       | 200.00                    | 200.00            |
| 1   | REAR END PANEL TOP GARNISH CLIP (SN)   | NECESSARY     | 20.00                     | 20.00             |
| 1   | REAR FENDER INNER SHIELD CLIP (SN)   | NECESSARY     | 25.00                     | 25.00             |
| 1   | REAR NUMBER PLATE (SN)   | BENT          | 40.00                     | 40.00             |
| 1   | REAR FENDER QUARTER GLASS SEALANT (SN)   | NECESSARY     | 40.00                     | 40.00             |
| 1   | REAR WIPER BLADE (SN)  | NOT NECESSARY | 11.00                     | -                 |
|     |  |               | 396.00                    | 385.00            |
|     | <b><u>LABOUR</u></b>   |               |                           |                   |
|     | TO REMOVE AND REFIT CARPET AND TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.  |               | 100.00                    | 60.00             |
|     | TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REAR EXHAUST SILENCER AND MOUNTINGS.  |               | 180.00                    | 60.00             |
|     | TO REMOVE AND REFIT REAR BUMPER SENSOR.  |               | 80.00                     | 50.00             |
|     | TO DISMANTLE AND REFIT REAR FENDER GLASS.  |               | 60.00                     | 60.00             |
|     | TO DISMANTLE AND REFIT REAR WINDSCREEN GLASS.  |               | 100.00                    | 100.00            |
|     | TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS.   |               | 30.00                     | 30.00             |
|     | TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF REAR FENDER LH, REAR EXHAUST PIPE AND REAR DOOR RH. |               | 1,100.00                  | 1,080.00          |

Report Ref No. CS/FCI18010705/Utbe2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty | Description of Parts   | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|-----------|---------------------------|-------------------|
|     | TO TRANSFER REAR TAILGATE.   |           | 80.00                     | 60.00             |
|     | TO CARRY-OUT BODY CAVITY PRESERVATION.   |           | 30.00                     | 30.00             |
|     | TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.   |           | 45.00                     | 40.00             |
|     | TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE. |           | 800.00                    | 800.00            |
|     |  |           | 2,605.00                  | 2,370.00          |
|     | <b>GRAND TOTAL</b>   |           | <b>12,207.58</b>          | <b>9,000.88</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>  |           |                           | <b>7,200.00</b>   |

Report Ref No. CS/FCI18010705/Utbe2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.