

VIC

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146

Email: allswell@allswellmotortraders.com.sg

(3rd party claim against Indura Int'l insured SGT 5835C

Estimate repair

Vehicle No.

: SGT 6249R

Submitted by

: Ben

Make & Model

: Toyota Innova

COE expiry

: 18-12-2026

Chassis No.

Engine No.

Date of survey

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	Front bumper	01	\$1,109.00		DE /
02	RH bumper retainer	01	\$102.00		Re /
03	RH fender	01	\$690.00	X	Repair
04	RH fender cover (no hole) mis /	01	\$92.00	} suppl	
05	RH sunshield de /	01	\$179.30		
Special Ref					
01	Cups @ \$11.00 each (bumper)	02	\$22.00		Re /
Labour description (included)					
01	Dismantle / Assembly of affected parts	01	\$360		300
02	Spray painting of all parts (bumper / fender)	01	\$760.00		400
03	Panel beating of RH fender	01	\$260 X		R4suc #p 9000068
				4 days	
				\$18 p/p	
				13/06/18 @ 1820	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

Date:

Resurvey after by repair paint

1482.30

25%

1111.72

22

700

1111.72

22.00

700.00

1833.72

4 days

7/p