

SERVICE ESTIMATE

89155 - C00001 SL: SERVICE SALES - PC

Mr Willy Tjahyadi Iwan
68 Toh Tuck Road
#04-01

Singapore 596733

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 07/05/2018

WIP No. : 59387

Veh.In/Out:

*Tel.No. : Mobile: 82981688

Reg.No. : SKB3313L

Reg.date : 30/03/2017

Mileage : 0

Chassis No: SAJAB4AG0HA972285

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Willy Tjahyadi Iw

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR LH FENDER	0	3400.00	0		3,400.00 S	1275
800	TO PUTTY SPRAYPAINT ON	0	1500.00	0		1,500.00 S	750
REAR LH FENDER							
280	TO CHECK WIRING INCLUDE	0	486.00	0		486.00 S	✓
RESETTING OF ALL ELECTRICAL MODULES							
419	WHEEL ALIGNMENT	0	280.00	0		280.00 S	X
802	TO REMOVE & INSTALL	0	1700.00	0		1,700.00 S	X
INTERIOR PARTS							
	QUARTER PANEL LH REA	1.0 EA	1538.40			1,538.40 S	Ry
	REAR WINDSCREEN XE	1.0 EA	1179.30			1,179.30 S	xm
	D PRIMER GLASS & P	1.0 EA	37.40			37.40 S	xm
	JC2D7026/SEALANT WIN	2.0 EA	159.70			319.40 S	xm
	NOISE DEADENING PAD	1.0 EA	500.00			500.00 S	xm

Gross Total. 10,940.50

Labour Total 7,366.00
Parts Total 3,574.50
Package Total 0.00

Net..... 10,940.50
GST @ 7.0% 765.84
Total..... 11,706.35
Paid..... 0.00
Please Pay.. 11,706.35

GST: S=StdRated; 0=Out of S

Wearnes Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damage details during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

www.wearnesauto.com

Signature:

Date:

Tanpin 97495749
- WP - 20/8/18 R 123
3-4 days
surv @ 1/week. w m
Ready after repair