

SERVICE ESTIMATE

89155 - C00001 SL: SERVICE SALES - PC

Mr Willy Tjahyadi Iwan

68 Toh Tuck Road

#04-01

Singapore 596733

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 07/05/2018

WIP No. : 59387

Veh.In/Out:

*Tel.No. : Mobile: 82981688

Reg.No. : SKB3313L

Reg.date : 30/03/2017

Mileage : 0

Chassis No: SAJAB4AG0HA972285

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Willy Tjahyadi Iw

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR LH FENDER	0	3400.00	0	3,400.00	S	1275
800	TO PUTTY SPRAYPAINT ON	0	1500.00	0	1,500.00	S	750
REAR LH FENDER							
280	TO CHECK WIRING INCLUDE	0	486.00	0	486.00	S	✓
RESETTING OF ALL ELECTRICAL MODULES							
419	WHEEL ALIGNMENT	0	280.00	0	280.00	S	X
802	TO REMOVE & INSTALL	0	1700.00	0	1,700.00	S	X
INTERIOR PARTS							
	QUARTER PANEL LH REA	1.0 EA	1538.40		1,538.40	S	Ry
	REAR WINDSCREEN XE	1.0 EA	1179.30		1,179.30	S	X
	D PRIMER GLASS & P	1.0 EA	37.40		37.40	S	X
	JC2D7026/SEALANT WIN	2.0 EA	159.70		319.40	S	X
	NOISE DEADENING PAD	1.0 EA	500.00		500.00	S	X

Gross Total. 10,940.50

Labour Total 7,366.00
 Parts Total 3,574.50
 Package Total 0.00

Net..... 10,940.50
 GST @ 7.0% 765.84
 Total..... 11,706.35
 Paid..... 0.00
 Please Pay.. 11,706.35

GST: S=StdRated; 0=OutOfS

WKA Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items, must be resurveyed and is subject to final approval from Insurance Company

www.wearnesauto.com

Signature:

Date:

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T +65 6430 4200

Co reg no. 199501400R / GST reg no. M28920628X

Tanm 97495749
 - WP' 20/8/18 @ 12
 3-4 days
 sur @ 1/Wearnes.wm
 Resurvey after repair