

SERVICE ESTIMATE

89155 - C00001 SL: SERVICE SALES - PC

Mr Willy Tjahyadi Iwan

68 Toh Tuck Road

#04-01

Singapore 596733

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Willy Tjahyadi Iw

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 07/05/2018

WIP No. . : 59387

Veh.In/Out:

*Tel.No. . : Mobile: 82981688

Reg.No. . : SKB3313L

Reg.date .: 30/03/2017

Mileage .. : 0

Chassis No: SAJAB4AG0HA972285

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR LH FENDER	0	3400.00	0		3,400.00	S
800	TO PUTTY SPRAYPAINT ON	0	1500.00	0		1,500.00	S
REAR LH FENDER							
280	TO CHECK WIRING INCLUDE	0	486.00	0		486.00	S
RESETTING OF ALL ELECTRICAL MODULES							
419	WHEEL ALIGNMENT	0	280.00	0		280.00	S
802	TO REMOVE & INSTALL	0	1700.00	0		1,700.00	S
INTERIOR PARTS							
	QUARTER PANEL LH REA	1.0 EA	1538.40			1,538.40	S
	REAR WINDSCREEN XE	1.0 EA	1179.30			1,179.30	S
	D PRIMER GLASS & P	1.0 EA	37.40			37.40	S
	JC2D7026/SEALANT WIN	2.0 EA	159.70			319.40	S
	NOISE DEADENING PAD	1.0 EA	500.00			500.00	S

Gross Total. 10,940.50

Labour Total 7,366.00
 Parts Total 3,574.50
 Package Total 0.00

Net..... 10,940.50
 GST @ 7.0% 765.84
 Total..... 11,706.35
 Paid..... 0.00
 Please Pay.. 11,706.35

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated