



JCN
AUTOLUTION

JCN Autolution Pte Ltd

COMPANY REG. NO.: 291813305V

No.1 Kaki Bukit Ave 6, BIK D #01-85, AutoBay @ Kaki Bukit,
Singapore 417883.

+65 6881 1772 sales@jcngrp.com

ESTIMATE

JK59 TRANSPORT PTE LTD JK59 TRANSPORT
55 ... AVE #04-04, PARC PALAIS Singapore
59 ...

Company No: 97229759

Code : C100005

Date in : 18/06/2018

Vehicle Num. : PA9559B

Model : ISUZU BUS

Chassis/Eng# : JALLT434PG7000072/6HK1685081

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BODY PANEL	1	7800.00	7,800.00 ⁴⁵⁰⁰ <i>cut ✓</i>
FRONT GRILLE	1	1772.00	1,772.00 <i>Rp</i>
FRONT GRILLE CHROME GARNISH	1	870.00	870.00 <i>cut ✓</i>
FRONT GRILLE SLY CLIP	1	15.00	15.00 <i>net ✓</i>
Subtotal before discount			10,457.00 <i>5385</i>
Percentage discount 0%			0.00
Sub-total 1			10,457.00
FRONT BODY PANEL NUMBER PLATE	1	30.00	30.00 <i>cut ✓</i>
Subtotal before discount			30.00
Percentage discount 0%			0.00
Sub-total 2			30.00
Parts-total			10,487.00 <i>5415</i>

LABOUR

Description	Price
TO REMOVE, REINSTALL FRONT FENDER GLASS. (TO FR)	300.00 <i>200</i>
TO RESPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	1,200.00 <i>600</i>
TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODY PARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	3,000.00 <i>1500</i>
Labour Total	4,500.00
Parts & Labour Total	14,987.00 <i>2300</i>

5415
2300
7715
*415 / 6150 * 7 days.*