

CC 3 / LOR 180 10713, Kja302

LKK:
IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

trans car



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time	STAGE	DATE / PIC
19/6	Non-Reporting ltr (1st):	
July	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☒ ☐
	After call ltr to OI:	☒ ☐
	Authorisation To Act:	☒ ☐
	Release Voucher:	☒ ☐
	Final Repair Bill:	☒ ☐
	Car Rental Invoice:	☒ ☐
	Towing Invoice:	☒ ☐
	LTA / GIA:	☒ ☐
	Medical Bill:	☒ ☐
	PIR:	☒ ☐
	Mandate/Reject Instruction:	☒ ☐
	LOD	☒ ☐
	Payment Breakdown Form:	☐ ☐
	Post-Repair Photos:	☐ ☐
	Others:	☐ ☐
PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	SS	Confirm by:
Final Liability:	%	Email ☐ Call ☐
Repair Cost:	SS	
Loss of Rental (LOR):	SS	
Loss of Use (LOU):	SS	
Loss of Income (LOI):	SS	
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐ [Tick only one]	
GIA/LTA Search	SS	
Medical:	SS	
Disbursement:	SS	
Legal Cost	SS	
Total:	SS	
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	SS	Name 1:
Payee 2: (Strike if N.A.)	SS	Name 2:
Payee 3: (Strike if N.A.)	SS	Name 3:

OID - CHANGED LANE
TP - STRAIGHT

July 2-718

CHANGING LANE

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT

ASS. REC. BY:

REF:

AIG/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

12/6/16 Pk parts to Carhome

L/S \$6,350

R (\$45,485.74 / 88%)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Prell. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fixtures

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/LCR18010713/Kja3		
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 12-06-2018		
		Code : LCR		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLH 5166M	Veh. Inspected	SHC 5600A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	12/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	04/06/2018	Inspection Date	11/06/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5600A**AAD1806-045***Not Authored
11 May 8*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5600A

VF1ABL15AUC279401

RENAULT

LATITUDE

4.6.2018

AIG

PART		LIST	
1	FENDER PANEL FRT RH	\$	<i>Ben</i> 783.83
1	WHEELARCH FRT RH	\$	<i>Sen</i> 278.84 X
1	FENDER BRACKET LOWER RH	\$	<i>Sen</i> 15.79 X
1	FENDER INSULATOR RH	\$	<i>Sen</i> 130.84 X
1	DOOR PANEL FRT RH	\$	<i>Ben</i> 2,844.66
1	DOOR HINGE UPPER RH	\$	<i>M</i> 261.28
1	DOOR HINGE LOWER RH	\$	<i>M</i> 300.55
1	DOOR CHECK FRT RH	\$	<i>Sen</i> 194.77 X
1	DOOR LOCK FRT RH	\$	<i>M</i> 908.75
1	DOOR CATCH FRT RH	\$	<i>Sen</i> 131.23
1	DOOR HANDLE OUTER FRT RH	\$	<i>Sen</i> 477.76
1	DOOR HANDLE COVER FRT RH	\$	<i>Sen</i> 13.22
1	DOOR HANDLE MODULE FRT RH	\$	<i>Sen</i> 133.60
1	DOOR REGULATOR FRT RH	\$	505.19
1	DOOR REGULATOR MOTOR FRT RH	\$	796.46
1	DOOR REGULATOR GUIDE FRT RH	\$	<i>Sen</i> 120.97 X
1	DOOR PANEL REAR RH	\$	<i>Ben</i> 2,844.66
1	DOOR GUIDE REAR RH	\$	<i>Sen</i> 176.82
1	DOOR HINGE UPPER RH	\$	<i>M</i> 274.50
1	DOOR HINGE LOWER RH	\$	<i>M</i> 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>Sen</i> 203.06
1	DOOR LOCK REAR RH	\$	<i>M</i> 908.75
1	DOOR HANDLE OUTER REAR RH	\$	<i>Sen</i> 126.49 X
1	DOOR HANDLE CAP REAR RH	\$	<i>Sen</i> 35.52
1	DOOR HANDLE SEAL REAR RH	\$	<i>Sen</i> 7.89
1	DOOR HANDLE COVER REAR RH	\$	<i>Sen</i> 13.22
1	DOOR HANDLE MODULE REAR RH	\$	<i>Sen</i> 133.60
1	DOOR REGULATOR REAR RH	\$	<i>Sen</i> 1,135.10
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>Sen</i> 893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>Sen</i> 12.43

Trans-cab Auto Services Pte Ltd**AAD1806-045**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5600A

1	DOOR REGUALTOR MOTOR SCREW REAR L70Y	\$	Su 6.31
1	DOOR FINISHER REAR RH	\$	Su 423.10
1	DOOR MOULDING REAR RH	\$	Su 176.82
1	DOOR MOULDING CLIP L70Y	\$	na 5.92
1	DOOR MOULDING SCREW L70Y	\$	na 6.91
1	DOOR CASING REAR RH	\$	Su 1,509.06
1	DOOR WATER SHIELD REAR RH	\$	Su 30.39
1	DOOR CASING CLIP	\$	na 12.63
1	DOOR CASING LIGHT L70Y	\$	Su 48.74
1	DOOR FINISHER INNER REAR RH	\$	Su 323.44
1	DOOR FINISHER BRACKET INNER REAR RH	\$	Su 46.97
1	DOOR FINISHER BRACKET INNER REAR RH	\$	Su 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	Su 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	Su 20.33
1	DOOR GRAB HANDLE REAR RH	\$	Su 210.96
1	DOOR BLIND REAR RH	\$	Su 741.80
1	DOOR WHEATHESTRIIP REAR RH	\$	Su 410.66
1	DOOR SEAL REAR RH	\$	Su 162.02
1	DOOR GLASS RUNNER SEAL REAR RH	\$	Su 229.31
1	DOOR WAIST SEAL OUTER REAR RH	\$	Su 334.69
1	DOOR WAIST SEAL INNER REAR RH	\$	Su 115.64
1	FENDER PANEL REAR RH	\$	na 3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	Su 671.45
1	WHEELARCH REAR RH	\$	Su 543.47
1	DOOR MIRROR ASSY RH	\$	Su 1,483.40
1	ROCKER PANEL INNER GARNISH RH	\$	Su 466.51
1	ROCKER PANEL INNER RH	\$	na 1,024.79
1	ROCKER PANEL CENTER RH	\$	na 990.25
1	VEHICLE HARNESS PASS ROOM	\$	Su 10,003.86
1	DOOR HARNESS WIRE	\$	Su 2,670.00
1	CENTRE PILLAR OUTER	\$	na 880.14
1	CENTER PILLAR INNER	\$	na 907.76
1	CENTER PILLAR REINFORCEMENT LH	\$	na 1,176.15

\$	43,937.34
----	------------------

10% \$	4,393.73
--------	-----------------

\$	39,543.61
----	------------------

Trans-cab Auto Services Pte Ltd

AAD1806-045

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5600A

Specical Nett

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn 70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	nn 20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	nn 30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	nn 30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn 80.00	60SA
1	FRONT DOOR STICKER 'Chassis'	\$	nn 50.00	15SA
1	REAR DOOR STICKER '6555 3333'	\$	nn 80.00	60SA
1	DOOR CHECK BOLT	\$	nn 22.69	} X
1	DOOR GUIDE SCREW	\$	nn 10.85	
1	DOOR HINGE BOLT	\$	nn 10.85	
1	DOOR HINGE NUT RH	\$	nn 14.60	
1	DOOR CHECK BOLT	\$	nn 22.69	
1	DOOR CHECK NUT	\$	nn 3.75	
1	DOOR LOCK SCREW L70Y	\$	nn 6.12	
1	DOOR CATCH SCREW L70Y	\$	nn 10.06	

TOTAL	\$	462.13
--------------	-----------	---------------

TOTAL PARTS	\$	40,005.74
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	6001
Putty and spray painting of the affected portion.	\$	4,200.00	11001
To rust-proofing of the affected areas.	\$	170.00	901
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	601
To check steering geometry and computer wheel alignment	\$	nn 220.00	X

Trans-cab Auto Services Pte Ltd

AAD1806-045

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5600A

To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>2d</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	<i>X</i>
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	<i>6d</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	<i>6d</i>
Towing Fees.	\$	<i>na</i> 120.00	<i>X</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>na</i> 380.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i> 380.00	<i>X</i>

TOTAL \$ 11,830.00**Over All Total \$ 51,835.74²****LUMP SUM (REPAIR DAY)****~~15 DAYS~~*****4 days***

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jun 2018 Edit Reg		11 Jun 2018 00:00 Edit Adj Rpt	S\$6,350.00 Edit Estimates	S\$6,350.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHC5600A	Date of Loss:	04/06/2018 18:00 - :59 [44 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 6793745178SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SLH5166M	Policy No. (Claimant):	VPX/P1680520
		Excess:	
Repairer:	Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Gan, Angie-GL] Angiegeokling.Gan@aig.com		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 22/06/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (13/06/2018): TP GIA REPORT

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SHC5600A (6793745178SG)**
[SLH5166M]
TP
TRANS-CAB SERVICES PTE LTD
Jun 4 2018 6:00PM
[LCRF PTE LTD]
Trans-cab Auto Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		☒			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print				
1	(Draft)		Third Party Express Settlement – Payment Breakdown											1	Edit					
Photos/Images															3 per page		☒			
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print				
1	16/11/18 13:37		General View											1	Load JPG		☒			
2	16/11/18 13:37		General View											1	Load JPG		☒			
3	16/11/18 13:37		General View											1	Load JPG		☒			
4	16/11/18 13:37		General View											1	Load JPG		☒			
5	16/11/18 13:37		General View											1	Load JPG		☒			
6	16/11/18 13:37		General View											1	Load JPG		☒			
7	16/11/18 13:37		General View											1	Load JPG		☒			
8	16/11/18 13:37		General View											1	Load JPG		☒			
9	16/11/18 13:37		General View											1	Load JPG		☒			
10	16/11/18 13:37		General View											1	Load JPG		☒			
11	16/11/18 13:37		General View											1	Load JPG		☒			
12	16/11/18 13:37		General View											1	Load JPG		☒			
13	16/11/18 13:37		General View											1	Load JPG		☒			
14	16/11/18 13:37		General View											1	Load JPG		☒			
15	16/11/18 13:37		General View											1	Load JPG		☒			
Documentation															1 per page		☒			
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print				
1	19/06/18 18:09		TP ESTIMATE - MARKED											1	Load PDF					
2	19/06/18 18:09		TP GIA REPORT											1	Load PDF					
3	02/07/18 09:48		LETTER TO LCRF											1	Load PDF					
4	20/12/18 08:49		AUTHORISATION TO ACT											1	Load PDF					
5	20/12/18 08:49		LTA SEARCH											1	Load PDF					
6	20/12/18 08:49		RELEASE VOUCHER											1	Load PDF					
7	20/12/18 08:49		RENTAL MILEAGE											1	Load PDF					
8	20/12/18 08:49		RENTAL RECEIPT											1	Load PDF					
9	20/12/18 08:49		WORKSHOP INVOICE											1	Load PDF					
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)											Thumbnail		Print				
1	13/06/18 10:49		OI GIA REPORT											1	Load PDF					

Documents Checklist

DOCUMENTS CHECKLIST																		Reset	Save	Print
There are no document checklists configured.																				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLH5166M (Insd veh)	Model:	RENAULT LATITUDE 2.0 DCI
	SHC5600A (TP veh)		AUTO D/AB 4DR (A)
Date of Accident:	04/06/2018		

Global Sum Settlement	:	[X]	Yes	[]	No	
Repair Estimate	:	\$				55,464.22
Final Repair Cost	:	\$				7,400.00
Loss of Use	:	\$				4.00 days at \$50.00 per day
Rental (if any)	:	\$				4 days
LTA / GIA Search Fee	:	\$				
Others:	:	\$				
	:	\$				
Final Settlement Sum (GLOBAL SUM)	:	\$				7,400.00
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)						
A) For Non GIA Registered Workshop:			Agreed Liability _____ 100 _____ (%)			
B) For GIA Registered Workshop:			BOLA Applicable: Yes/ No BOLA Scenario No: _____			
BOLA Liability: _____ (%)			Assessed Liability (*): _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.						
Remarks: _____						

Payment Instruction: Payee's Breakdown			
1)	Trans-Cab Auto Services Pte Ltd	:	\$ 7,400.00
2)		:	\$
3)		:	\$
4)		:	\$
5)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

20 Dec
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/LCR18010713/KJA3S2

Date: 20/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SHC5600A

Insured Vehicle No : SLH5166M

Date of Loss: 04/06/2018

Nature of Claim: TP

Claim No: 6793745178SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC5600A

Make & Model: RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)

Engine No: M9R8839C001939

Reg. Date: 30/09/2014 (Man. Year: 2014)

Chassis No: VF1ABL15AUC279401

Colour: Metallic White/Red

Odometer: 536308 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 7 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 7 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,005.72	5,960.83	34,044.89	85.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,830.00	1,990.00	9,840.00	83.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	51,835.72	7,950.83	43,884.89	84.66
Approved Total (Overridden) (S\$)		6,350.00		
(S\$)	51,835.72	6,350.00	45,485.72	87.75
+ GST 7.00/7.00% (S\$)	3,628.50	444.50	3,184.00	87.75
Nett Amount (S\$)	55,464.22	6,794.50	48,669.72	87.75
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$101.46/day) (S\$)		405.84		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		7,407.83		
Global Sum Settlement (S\$)		7,400.00		

INSPECTION

Date of Assignment: 11/06/2018

Date Inspected: 11/06/2018 Inspected At:

 Trans-cab Auto Services Pte Ltd
 No 2 Ang Mo Kio Street 63
 Singapore 569111

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER PANEL FRT RH	Buckled	783.83 FL	*783.83 FL
2	1		*WHEELARCH FRT RH	Serviceable	278.84 FL	*- FL
3	1		*FENDER BRACKET LOWER RH	Serviceable	15.79 FL	*- FL
4	1		*FENDER INSULATOR RH	Serviceable	130.84 FL	*- FL
5	1		*DOOR PANEL FRT RH	Bent	2,844.66 FL	*2,844.66 FL
6	1		*DOOR HINGE UPPER RH	Repair	261.28 FL	*- FL
7	1		*DOOR HINGE LOWER RH	Repair	300.55 FL	*- FL
8	1		*DOOR CHECK FRT RH	Serviceable	194.77 FL	*- FL
9	1		*DOOR LOCK FRT RH	Repair	908.75 FL	*- FL
10	1		*DOOR CATCH FRT RH	Serviceable	131.23 FL	*- FL
11	1		*DOOR HANDLE OUTER FRT RH	Serviceable	477.76 FL	*- FL
12	1		*DOOR HANDLE COVER FRT RH	Serviceable	13.22 FL	*- FL
13	1		*DOOR HANDLE MODULE FRT RH	Serviceable	133.60 FL	*- FL
14	1		*DOOR REGULATOR FRT RH	Serviceable	505.19 FL	*- FL
15	1		*DOOR REGULATOR MOTOR FRT RH	Serviceable	796.46 FL	*- FL
16	1		*DOOR REGULATOR GUIDE FRT RH	Serviceable	120.97 FL	*- FL
17	1		*DOOR PANEL REAR RH	Bent	2,844.66 FL	*2,844.66 FL
18	1		*DOOR GUIDE REAR RH	Serviceable	176.82 FL	*- FL
19	1		*DOOR HINGE UPPER RH	Repair	274.50 FL	*- FL
20	1		*DOOR HINGE LOWER RH	Repair	300.55 FL	*- FL
21	1		*DOOR CHECK REAR LH/RH L70Y	Serviceable	203.06 FL	*- FL
22	1		*DOOR LOCK REAR RH	Repair	908.75 FL	*- FL
23	1		*DOOR HANDLE OUTER REAR RH	Serviceable	126.49 FL	*- FL
24	1		*DOOR HANDLE CAP REAR RH	Serviceable	35.52 FL	*- FL
25	1		*DOOR HANDLE SEAL REAR RH	Serviceable	7.89 FL	*- FL
26	1		*DOOR HANDLE COVER REAR RH	Serviceable	13.22 FL	*- FL
27	1		*DOOR HANDLE MODULE REAR RH	Serviceable	133.60 FL	*- FL
28	1		*DOOR REGULATOR REAR RH	Serviceable	1,135.10 FL	*- FL
29	1		*DOOR REGULATOR MOTOR REAR RH	Serviceable	893.75 FL	*- FL
30	1		*DOOR REGULATOR NUT REAR L70Y	Serviceable	12.43 FL	*- FL
31	1		*DOOR REGULATOR MOTOR SCREW REAR L70Y	Serviceable	6.31 FL	*- FL
32	1		*DOOR FINISHER REAR RH	Serviceable	423.10 FL	*- FL
33	1		*DOOR MOULDING REAR RH	Serviceable	176.82 FL	*- FL
34	1		*DOOR MOULDING CLIP L70Y	Not Necessary	5.92 FL	*- FL
35	1		*DOOR MOULDING SCREW L70Y	Not Necessary	6.91 FL	*- FL
36	1		*DOOR CASING REAR RH	Serviceable	1,509.06 FL	*- FL
37	1		*DOOR WATER SHIELD REAR RH	Serviceable	30.39 FL	*- FL
38	1		*DOOR CASING CLIP	Not Necessary	12.63 FL	*- FL
39	1		*DOOR CASING LIGHT L70Y	Serviceable	48.74 FL	*- FL
40	1		*DOOR FINISHER INNER REAR RH	Serviceable	323.44 FL	*- FL
41	1		*DOOR FINISHER BRACKET INNER REAR RH	Serviceable	46.97 FL	*- FL
42	1		*DOOR FINISHER BRACKET INNER REAR RH	Serviceable	20.33 FL	*- FL
43	1		*DOOR FINISHER BRACKET INNER REAR RH	Serviceable	20.33 FL	*- FL
44	1		*DOOR FINISHER BRACKET INNER REAR RH	Serviceable	20.33 FL	*- FL
45	1		*DOOR GRAB HANDLE REAR RH	Serviceable	210.96 FL	*- FL
46	1		*DOOR BLIND REAR RH	Serviceable	741.80 FL	*- FL
47	1		*DOOR WEATHERSTRIP REAR RH	Serviceable	410.66 FL	*- FL
48	1		*DOOR SEAL REAR RH	Serviceable	162.02 FL	*- FL
49	1		*DOOR GLASS RUNNER SEAL REAR RH	Serviceable	229.31 FL	*- FL
50	1		*DOOR WAIST SEAL OUTER REAR RH	Serviceable	334.69 FL	*- FL
51	1		*DOOR WAIST SEAL INNER REAR RH	Serviceable	115.64 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
53	1		*FENDER PANEL INNER TRIM REAR	Serviceable	671.45 FL	*- FL
54	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
55	1		*DOOR MIRROR ASSY RH	Serviceable	1,483.40 FL	*- FL
56	1		*ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	*- FL
57	1		*ROCKER PANEL INNER RH	Repair	1,024.79 FL	*- FL
58	1		*ROCKER PANEL CENTER RH	Repair	990.25 FL	*- FL
59	1		*VEHICLE HARNESS PASS ROOM	Serviceable	10,003.86 FL	*- FL
60	1		*DOOR HARNESS WIRE	Serviceable	2,670.00 FL	*- FL
61	1		*CENTRE PILLAR OUTER	Repair	880.14 FL	*- FL
62	1		*CENTRE PILLAR INNER	Repair	907.76 FL	*- FL
63	1		*CENTRE PILLAR REINFORCEMENT RH	Repair	1,176.15 FL	*- FL
64	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
65	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
66	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
67	1		*SET WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*- FS
68	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
69	1		*FRONT DOOR STICKER CHASSIS	Necessary	50.00 FS	*15.00 FS
70	1		*REAR DOOR STICKER 6555 3333	Necessary	80.00 FS	*60.00 FS
71	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
72	1		*DOOR GUIDE SCREW	Not Necessary	10.85 FS	*- FS
73	1		*DOOR HINGE BOLT	Not Necessary	10.85 FS	*- FS
74	1		*DOOR HINGE NUT RH	Not Necessary	14.60 FS	*- FS
75	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
76	1		*DOOR CHECK NUT	Not Necessary	3.75 FS	*- FS
77	1		*DOOR LOCK SCREW L70Y	Not Necessary	6.12 FS	*- FS
78	1		*DOOR CATCH SCREW L70Y	Not Necessary	10.06 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	44,399.46	6,608.15
- List Item Discount on L Items 10.00/10.00% (\$\$)	4,393.74	647.32
Total Parts (\$\$)	40,005.72	5,960.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	4,500.00	600.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	4,200.00	1,100.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	90.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	60.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
6	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	20.00
8	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
9	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	60.00
10	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	60.00
11	TOWING FEES.	New	120.00	0.00
12	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	New	380.00	0.00
13	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
Gross Labour Cost (\$\$)			11,830.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >