



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SKG 1349 X

Parts	(a) Cost / List Price Items	_____
	Plus/Less	_____
	Total of Cost / List	=====
	(b) Nett Price Items	\$ 1,701.42
	Less 10%	\$ 170.14
	Total of Nett Item	\$ 1,531.28
	(c) Special Nett Items	_____
Total Parts Cost	\$	1,531.28
Labour	\$	820.00
Total	\$	2,351.28

The above total will be subjected to 7% G.S.T.

*Not Authorised
Repair By paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Name of Surveyor : Kennerth
Company : LKK
Survey conducted on : 12/6/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Sc Date: 12/6/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SKG 1349 X**
Make & Model : **NISSAN QASHQAI**
Chassis No : **SJNFBAJ10U2467383**

Submit By : **Carmen Lim**
Year Manufacture : **2012**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH front door <i>Red/warp</i>	1	\$1,215.30	N	✓
2	RH front door chrome <i>new</i>	1	\$278.30	N	✓
3	RH front door protector	1			
4	RHF door glass outer moulding <i>See</i>	1	\$207.80	N	X
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SKG 1349 X** Submit By : **Carmen Lim**
Make & Model : **NISSAN QASHQAI** Year of Manufacture : **2012**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (RH FRONT DOOR)	\$300.00	2001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (RH FRONT DOOR)	\$300.00	2201
3	To check wiring	\$50.00	201
4	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$120.00	601
5	To tuff coat	\$50.00	301

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.