

15/5/2010

INS. CASE OWNER:

Nall

CC 4 AGM
AXA1801 0715, A

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

12/6/18

Date / Time:

12/6/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKZ 5751R

Name of Insured:

LYNETTE WONG U-LIN

Insured Tel No.:

HP:

93388888

Excess Sec II :SS

D.O.A:

10/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SKM0087 / 51253

Policy No.:

VPA / 12/12/16

Make / Model:

BMW

Place of Accident:

FORO KUT MEYER KOL

Tanjong Rhu Rd TMS EUP

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT (YES / NO) : TP GIA REPORT (YES / NO)

Insured Liability:

% Final ? Yes / No

SFS 8125R

INSRS:
WSP:
Tel:
Liability:
RMKS:RICO
60INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

12/6/18
TIM

SFS 8125R 3 hrs / 12/6/18 (y 12/6/18)

SKZ 5751R

Smartclaim

- PROCEEDED - TO COV IN.

OI re-endered to P. send letter to OI.

08/11/18

- HUF REVIEWED. OI KETIK-BALDIP TP.
GANDI LATER 4 EMAIL TO OI TO
NOTIFY TP CLAIM & NCB 1000ES.

05/11/18

- AXA APPROVED UNPAID

08/11/18

- GANDI 1ST OFFER TO TP.

12/11/18

- TP ACCEPTED OFFER.

- ALL BOCA IN ORDER.

- TO CLOSE.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 08/11/18 - VLO

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: 49

SS 3,100.00 (3 days) Reduction: 86 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost: (w/acc)

SS 3,803.49

COI LTR - ENJOYED TO

Loss of Rental (LOR):

SS 450.00 (5 days) x 490

Loss of Use (LOU):

SS - (S x days)

Loss of Income (LOI):

SS - (S x days)

LOR only ☒ LOU only ☐LOR + LOU ☐ LOR + LO ☐ [Tick only one]

GIA/LTA Search

SS 66.49

Medical:

SS -

Disbursement:

SS - (e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee: 4380.00

Total:

SS 3,803.49

Global Sum SS: -

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS 3,803.49

Name 1:

RICO GO AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

SS -

Name 2:

-

Payee 3: (Strike if N.A.)

SS -

Name 3:

-

REF:

ASS. REC. BY: Adrian Ling**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKS82SR Yr Regn: 200 / AugustType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Scirocco C.C. 1350Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 95638 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVWZZZBZAV448875Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/40R18R: 235/40R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. D.O.I. 12/06/18Survey held at Pico 60Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AXA.45 \$3,100.00(Net: \$19,064.97 / 86%)MV: 35KRV: 19.5KNet: 15.5K

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / L.B.L. (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp. (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18010715/Aub3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 12-06-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 5751R	Veh. Inspected	SKS 8125R	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	12/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/06/2018	Inspection Date	12/06/2018	
Survey held at	RICO 60			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4

Premier @ Kaki Bukit

#02-24, Singapore 415875

Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

Vehicle No.:	SKS 8125 R
Make & Model:	VOLKSWAGEN SCIROCCO
Chassis No.:	WVWZZZ13ZAV448875

TPAYA

Thin Thin

NO.	DESCRIPTION - PARTS	QTY.	PRICE
8	REAR BUMPER <i>torn</i>		\$ 1,348.97
9	REAR BUMPER SIDE RETAINER L+R <i>me</i>		\$ 184.32
10	REAR BUMPER BRACKET L+R <i>Not on</i>		\$ 190.42
11	REAR BUMPER REINFORCEMENT <i>Not on</i>		\$ 698.61
12	REAR BUMPER CARRIER <i>Cracked</i>		\$ 289.78
13	REAR BUMPER REFLECTOR L+R <i>Not on</i>		\$ 287.50
14	REAR BUMPER TOW COVER <i>Not on</i>		\$ 86.90
15	REAR NUMBER PLATE LAMP L+R <i>Not on</i>		\$ 359.85
16	REAR END PANEL <i>2</i>		\$ 896.32
17	REAR END PANEL TOP GARNISH <i>Not on</i>		\$ 279.41
18	REAR SPARE WHEEL TOP BOARD		\$ 599.31
19	TAILLAMP L+R <i>2</i>		\$ 1,140.89
20	TAILLAMP PANEL L+R		\$ 443.56
21	REAR EXHAUST PIPE GASKET <i>Not on</i>		\$ 120.00
22	REAR EXHAUST PIPE MOUNTING		\$ 156.58
23	REAR EXHAUST PIPE HEAT SHIELD		\$ 347.80
24	REVERSE SENSOR WIRE ASSY <i>Not on</i>		\$ 986.41
	<i>1681.40</i> SUBTOTAL		\$ 8,416.63
	<i>151326</i> LESS 10%		\$ 841.66
	PARTS TOTAL		\$ 7,574.97
NO.	SPECIAL NETT	QTY.	PRICE
1	REAR NUMBER PLATE <i>Not on</i>	1	\$ 80.00

120730

2	REAR BUMPER EMBLEM- MASTER TUNE <i>Not done</i>	1	\$ 100.00	X.
3	REAR BUMPER LOWER LIPS <i>coated</i>	1	\$ 1,800.00	800
4	REVERSE SENSOR <i>Byd</i>	1	\$ 320.00	200
5	REVERSE CAMERA <i>Byd</i>	1	\$ 480.00	380
6	READ END PANEL SEALANT <i>new</i>	1	\$ 80.00	+
7	REAR BUMPER CLIPS <i>new</i>	1	\$ 60.00	30
8	REAR EXHAUST ASSY <i>2 Repair</i>	1	\$ 4,800.00	+
9	REAR EXHAUST CHROME TIP <i>Not Best</i>	4	\$ 1,200.00	300
10	TAILLAMP CLIPS <i>Not done 1710</i>	1	\$ 30.00	+
11	TAILLAMP TINT <i>Not done</i>	2	\$ 120.00	+
SPECIAL NETT TOTAL			\$ 9,070.00	
NO.	LABOUR	QTY.	PRICE	
1	TO R&R ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK AND ALIGN		\$ 1,600.00	200
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA		\$ 1,500.00	200
3	TO RUST PROOF ACCIDENT AFFECTED AREA		\$ 100.00	X
4	TO R&R REAR WINDSCREEN <i>2</i>		\$ 180.00	+
5	TO R&R REAR BOOT MECHANISM <i>Not done</i>		\$ 250.00	+
6	TO R&R REAR LUAGGAGE COMPARTMENT		\$ 350.00	+
7	TO R&R UPHOSTERY, GARNISH AND ATTACHMENT PARTS		\$ 300.00	X
8	TO R&R REVERSE SENSOR AND CHECK FUNCTION		\$ 100.00	50
9	TO R&R EXHAUST SYSTEM AND ATTACHMENT PARTS		\$ 200.00	150
10	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION		\$ 180.00	30
11	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE		\$ 400.00	X
12	TO DO WATER LEAK TEST		\$ 180.00	+
13	TO R&R REVERSE CAMERA AND CHECK FUNCTION		\$ 150.00	50
LABOUR TOTAL			\$ 5,490.00	
GRAND TOTAL COST			\$ 22,134.97	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Parts prices subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 350326

L/S: 3-1K

Adrian Lij
L/S 12/06/18
0322



Service Request Details

Claim

S8M00K8F

Reference

None 

Loss Date

June 10, 2018

Request Date

June 12, 2018

Due Date

June 20, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

12062018 @ 953am

Kelvin. veh in

Adrian

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKS8125R

Make

TPVD VOLKSWAGEN

Model

SCIROCCO

Service Address

...

Primary Contact/Insured

LYNETTE WONG LI-LIN

33 FORT ROAD, #11-04, 439092, Singapore

93888338

WONGLYNETTE@YAHOO.COM.SG

Claim Handler

OH Vale

6568804897

vale.oh@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Vic (LKKAUTO)

From: Rico 60 <claims@rico60.com>
Sent: Saturday, 10 November, 2018 4:52 PM
To: Vic (LKKAUTO)
Cc: Admin A; Vic (LKKAUTO)
Subject: RE: Your Ref: SKS 8125R_ACCIDENT INVOLVING VEHICLES SKZ 5751R
ANDSKS8125R ON 10/06/2018 LKK REF CC4/ASM18010715/Ahb3
Attachments: Discharge Voucher.pdf

Dear Vic,

Attached signed DV as per your pursuant.
Kindly release cheque.

Thank you.

Best Regards,
Cass Chua



RICO 60 AUTO SERVICES PTE. LTD.
Co. & GST Reg. No.: 201807623M
8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit
#02-24, Singapore 415875
Tel: +65 6286 6060 | Fax: +65 6286 7060
Email: claims@rico60.com

From: Rico 60
Sent: Thursday, 8 November 2018 3:50 PM
To: Vic (LKKAUTO)
Cc: Admin A; Vic (LKKAUTO)
Subject: RE: Your Ref: SKS 8125R_ACCIDENT INVOLVING VEHICLES SKZ 5751R ANDSKS8125R ON 10/06/2018 LKK REF CC4/ASM18010715/Ahb3

Dear Vic,

The offer has been accepted.
Will get the DV signed ASAP.

Thank you.

Best Regards,
Cass Chua



RICO 60 AUTO SERVICES PTE. LTD.
Co. & GST Reg. No.: 201807623M
8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875
Tel: +65 6286 6060 | Fax: +65 6286 7060
Email: claims@rico60.com

From: Vic (LKKAUTO)
Sent: Thursday, 8 November 2018 1:58 PM
To: Rico 60
Cc: Admin A; Vic (LKKAUTO)
Subject: Your Ref: SKS 8125R_ACCIDENT INVOLVING VEHICLES SKZ 5751R AND SKS8125R ON 10/06/2018 LKK REF CC4/ASM18010715/Ahb3

Without Prejudice

Dear Sir/Madam,

ACCIDENT INVOLVING VEHICLES SKZ 5751R AND SKS 8125R ON 10/06/2018

We refer to your below email.

Purely for an amicable settlement on a without prejudice basis and without admission of liability to our Insured's part, we have our principal's mandate and we offer to settle your client's claim as below:

Cost of Repair (w/gst)	\$ 3,317.00
Loss of Rental (\$90 x 5 days)	\$ 450.00
LTA/GIA Search Fee	\$ 36.49
TOTAL	\$ 3,803.49

If agreeable, kindly let the owner sign the attached DV then forward to a copy to us for payment processing.

The above amount is to be made payable to **RICO 60 AUTO SERVICES PTE LTD.**

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disc

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKZ 5751R (Insd veh)	Model:	VOLKSWAGEN SCIROCCO
	SKS 8125R (TP veh)		
Date of Accident:	10/06/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	23,684.42
Final Repair Cost	:	\$	3,317.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	450.00 5 days
LTA / GIA Search Fee	:	\$	36.49

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	3,803.49

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop:	Agreed Liability ____100____(%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: ____
BOLA Liability: ____ (%)	Assessed Liability (*): ____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	

Remarks

Payment Instruction: Payee's Breakdown			
1)	RICO 60 AUTO SERVICES PTE. LTD.	:	\$ 3,803.49

NUR SHAQILAH BTE ABDOL
WAHAB

21/11/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18010715/Ahb3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: VALE OH		Date : 21-11-2018 Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 5751R	Veh. Inspected	SKS 8125R	
Policy No.	VPA/P1724266	Coverage (\$)	0.00	
Claim No.	S8M00K8F	Excess (\$)	0.00	
Assign From	VALE OH	Assign Date	12/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN SCIROCCO	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WVWZZZ13ZAV448875	Colour	BLUE	
Odometer	95638	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/40R18	BRIDGESTONE	6 mm	
L/H Front Tyre	235/40R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	235/40R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	235/40R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/06/2018	Inspection Date	12/06/2018	
Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 8125R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (CONSISTENT)	TORN	1,348.97	1,207.30
1	REAR BUMPER SIDE RETAINER L+R (CONSISTENT)	NECESSARY	184.32	184.32
1	REAR BUMPER BRACKET L+R (CONSISTENT)	NOT NECESSARY	190.42	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	698.61	-
1	REAR BUMPER CARRIER (CONSISTENT)	CRACKED	289.78	289.78
1	REAR BUMPER REFLECTOR L+R (CONSISTENT)	NOT NECESSARY	287.50	-
1	REAR BUMPER TOW COVER (CONSISTENT)	NOT NECESSARY	86.90	-
1	REAR NUMBER PLATE LAMP L+R (CONSISTENT)	NOT NECESSARY	359.85	-
1	REAR END PANEL (CONSISTENT)	NOT NECESSARY	896.32	-
1	REAR END PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	279.41	-
1	REAR SPARE WHEEL TOP BOARD (CONSISTENT)	NOT NECESSARY	599.31	-
1	TAILLAMP L+R (CONSISTENT)	NOT NECESSARY	1,140.89	-
1	TAILLAMP PANEL L+R (CONSISTENT)	NOT NECESSARY	443.56	-
1	REAR EXHAUST PIPE GASKET (CONSISTENT)	NOT NECESSARY	120.00	-
1	REAR EXHAUST PIPE MOUNTING (CONSISTENT)	NOT NECESSARY	156.58	-
1	REAR EXHAUST PIPE HEAT SHIELD (CONSISTENT)	NOT NECESSARY	347.80	-
1	REVERSE SENSOR WIRE ASSY (CONSISTENT)	NOT NECESSARY	986.41	-
	LESS 10% DISCOUNT		-841.66	-168.14
			7,574.97	1,513.26
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR BUMPER EMBLEM - MASTER TUNE (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR BUMPER LOWER LIPS (SN) (CONSISTENT)	CRACKED	1,800.00	800.00
1	REVERSE SENSOR (SN) (CONSISTENT)	DAMAGED	320.00	200.00
1	REVERSE CAMERA (SN) (CONSISTENT)	DAMAGED	480.00	380.00
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	60.00	30.00
1	REAR EXHAUST ASSY (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	4,800.00	-
4	REAR EXHAUST CHROME TIP (SN) (CONSISTENT)	BENT	1,200.00	300.00

Report Ref No. CC4/ASM18010715/Ahb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILLAMP CLIPS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
2	TAILLAMP TINT (SN) (CONSISTENT)	NOT NECESSARY	120.00	-
			9,070.00	1,710.00
	LABOUR			
	TO R&R ACCIDENT DAMAGE PARTS, CUT / WELD, KNOCK AND ALIGN. INCLUSIVE OF THE REPAIR OF REAR EXHAUST ASSY.		1,600.00	200.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.		1,500.00	200.00
	TO RUST PROOF ACCIDENT AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO R&R REAR WINDSCREEN.	NOT NECESSARY	180.00	-
	TO R&R REAR BOOT MECHANISM.	NOT NECESSARY	250.00	-
	TO R&R REAR LUGGAGE COMPARTMENT.	NOT NECESSARY	350.00	-
	TO R&R UPHOLSTERY, GARNISH AND ATTACHMENT PARTS.	NOT NECESSARY	300.00	-
	TO R&R REVERSE SENSOR AND CHECK FUNCTION.		100.00	50.00
	TO R&R EXHAUST SYSTEM AND ATTACHMENT PARTS.		200.00	150.00
	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION.		180.00	30.00
	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT COD.	NOT NECESSARY	400.00	-
	TO DO WATER LEAK TEST.	NOT NECESSARY	180.00	-
	TO R&R REVERSE CAMERA AND CHECK FUNCTION.		150.00	50.00
			5,490.00	680.00
GRAND TOTAL			22,134.97	3,903.26
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,100.00

Report Ref No. CC4/ASM18010715/Ahb3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.