

Yang Yun Xin Bus Service

50 Serangoon North Ave 4
#01-23, First Centre Singapore 555856
Tel :285 7585 Fax: 6382 5058

Date : 16/4/18

Estimate repair bill for CB7285C
DOA : 5/3/18

S/N	Description	Unit	Amount
1	Front windscreen <i>CH</i>	1	\$2,500 ?
2	Windscreen rubber <i>REC</i>	1	\$500 ?
3	Front panel <i>repair x</i>	1	\$3,000
4	Front-right signal light <i>CH</i>	1	\$350 ?
5	Front bumper <i>cut</i>	1	\$2,500 ?
6	Front-right door <i>repair x</i>	1	\$3,000

Labour

1	To supply labour and materials to remove, replace and align damaged bumper/ fibre cap	\$5,000 <i>1000</i>
2	to putty and spray paint all affected area and panels	\$1,500 <i>800</i>
3	Computer artwork for Logo	\$250 <i>150</i>
5	Wiring and testing	\$500 <i>30</i>

Total \$19,100

** ABOVE PRICE QUOTED ARE BEFORE GST

Guo Qiang - 82880282
Guo Qiang @ 1kk auto. com

8 Days

Unsym repair

After repair photos

02/5/18

Victor Ong
9679 2545

victor@yyx.com.sg