

CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS
翠 NOTARY PUBLIC - 公证官
玲 COMMISSIONER FOR OATHS- 宣誓官
律
師 CATHERINE C.L.LIM
馆 DIRECTOR
LL.B (HONS) SINGAPORE-法律系-律師
M.B.A. (BUSINESS LAW)-商业系-硕士

20 Havelock Road #03-01
Central Square Singapore 059765
UEN No. 201310922K
GST Registration No. 201310922K
Tel: (65) 6438 5500
Fax: (65) 6438 0111
www.catherinelimllc.com
Email: info@catherinelimllc.com
CATHERINE LIM LLC is a law
corporation with limited liability

Your Ref: CC2/MIDA18010721/j
Our Ref: CL/180525/T/GP.wa

15 August 2018

M/S LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
#Paya Ubi Industrial Park
Singapore 408933
Attn: Claims Dept/ Ms Joy

WITHOUT PREJUDICE

VIA AIR REGISTERED

Dear Sir

ACCIDENT INVOLVING FY 533B / 46201MID ON 11.05.2018 ALONG YIO CHU KANG ROAD / UPPER THOMSON ROAD

We act for Muhammad Hasanuddin Bin Azmi, the owner of motor vehicle No FY 533B, which was involved in the above accident.

Our client has suffered loss and damage as a result of your Insured's negligence in the driving of motor vehicle No 46201MID.

We quantify our client's claim as follows :-

1. Cost of repair	\$ 6,874.11
2. Loss of use for 7 day @ \$40/day	\$ 280.00
3. Survey fee	\$ 426.00
4. Incidentals, transport & photocopying etc	\$ 53.50
5. Cost contribution	\$ 749.00

	\$ 8,382.61

We enclose herewith photocopies of our client's accident report, final repair bill, survey fee, survey report and original colour photographs of our client's damaged vehicle for your immediate attention.

Please let us know within the next 14 days from the receipt of this letter, whether you are prepared to admit liability and revert with a settlement proposal, failing which our clients shall have no alternative but to commence legal proceedings against your insured.

Yours faithfully

Encs
cc.clients

(Please note that if your motor vehicle was not driven by you, there is a presumption in law that the said driver was driving as your agent/ servant unless you let us know the particulars of your driver if your motor vehicle was not driven by you.)



GP Motoring Pte. Ltd.

282 Macpherson Rd

Singapore 348607

Tel: 67464240

Fax: 67464596

Roc & Gst No: 201205428D

180525

To: Whom it my concern,

Invoice No. GP/2018/0511/0533

Date: 13/08/2018

REGN NO: FY 533 B

LOSS OF USE:	7 DAYS
LUMP SUM REPAIR:	\$6424.40
7% GST	\$ 449.71
TOTAL:	\$6874.11

Regards,



Reg. No: 201205428D

Director of GP Motoring Pte Ltd

Loss Adjuster, Consulting Automotive Engineer, Accident Reconstruction & Analyst.**VEHICLE APPRAISAL REPORT**

Mr Muhammad Hasrul Bin Hamid
Apt Blk 814 #02-202
Jurong West Street 81
Singapore – 640 814

Our Ref : TP/1805/FY533/GP
Date : 18 July 2018

REFERENCE PARTICULARS

Your Reference No : Not Advised
Date of Accident : 11 May 2018

Date of Assignment : 19 May 2018
Date of Inspection : 19 May 2018
Date of Re-inspn. : N/A

PARTICULARS OF VEHICLE

Regn. No : FY 533B
Make : YAMAHA
Model : MT-09 ABS TRACER
Year : 2015 (COE.Exp : Sep 2025)

Odometer : 43188km
Color : Grey
Chassis No. : JYARN29K000000460
Engine No : N701E044222

TYRE / CONDITION

<u>Location</u>	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	Pirelli	120 / 70 R17	5 mm
Rear	Pirelli	180 / 55 R17	5 mm

DAMAGE PROFILE

The motor cycle sustained damage on Rear and left side.

Please refer to photographs and assessment of repairs for details.

ASSESSMENT SUMMARY

Repair cost to the vehicle is assessed as \$ **6424.40**

Survey conducted at: GP Motoring Pte Ltd

Enclosed (26) photographs depicting damage to the vehicle.

Estimated time required for repairs: (7) days.

The survey was conducted on a **WITHOUT PREJUDICE BASIS.**

3 Gambas Crescent, #07-14 Nordcom 1, Singapore 757088 Tel: 63966319 Fax: 63966320 Email: lhtas@singnet.com.sg

Loss Adjuster, Consulting Automotive Engineer, Accident Reconstruction & Analyst.

Mr Muhammad Hasrul Bin Hamid
Apt Blk 814 #02-202
Jurong West Street 81
Singapore – 640 814

Bill No : AA180709
OurRef : TP/1805/FY533/GP
Date : 18 July 2018

To our Services rendered in connection with the below matters: -

<u>Description</u>	<u>Amount</u>
Survey fees	\$ 340.00
Transportation and Photographs (26) Copies	60.00 26.00
Total	\$ <u>426.00</u>

Dollars: Four hundred and twenty six only

Please quote our bill No, or return a copy of our bill with your remittance. Cheque should be made payable to **L H Teo Appraisal Services.**

L H TEO APPRAISAL SERVICES



Teo Liak Hoo
Advance Automotive Engineer (UK)
Dip. Mech. Engr. M Prof BTM(Dip.BTM)
MIE, MIMI, AMSIM

ASSESSMENT FOR REPAIR : FY 533 B

<u>Qty</u>	<u>Description</u>	<u>Condition</u>	<u>Repairer's Estimate</u>	<u>Our Assessment</u>
1 pc	Handle bar	Bent	324.00	324.00
1 pc	Clutch Lever	Usable	97.00	~
1 set	Handle guard assy	Cut	484.00	484.00
1 pc	Mirror LH	Cut	91.00	91.00
1 pc	Front flasher light assy LH	Cut	62.00	62.00
1 pc	Front Side Panel LH	Grazed	199.00	199.00
1 pc	Panel Logo LH	Necessary	40.00	40.00
1 pc	Panel Graphic LH	Necessary	33.00	33.00
1 pc	Panel 3D Emblem "TRACER" LH	Necessary	30.00	30.00
1 pc	Inner Panel LH	Usable	235.00	~
1 pc	Front Fender	Grazed	240.00	240.00
2 pcs	Front Fender Emblem @22.00	Necessary	44.00	44.00
1 pc	Oil strainer lower cover assy	Cut	568.00	568.00
1 pc	Oil strainer lower cover gasket	Necessary	57.00	57.00
1 pc	Crankcase cover LH	Cut	339.00	339.00
1 pc	Crankcase cover gasket LH	Necessary	35.00	35.00
1 pc	Shift pedal assy	Bent	197.00	197.00
1 pc	Front footrest assy LH	Cut	103.00	103.00
1 pc	Front footrest bracket LH	Usable	167.00	~
			<hr/>	
			3,345.00	2,846.00
		Less 10%	<hr/>	
			334.50	284.60
			<hr/>	
			3,010.50	2,561.40
	<u>Special Nett Items</u>			
1 set	Side box complete, Givi Trekker	Cut	2,500.00	2,500.00
1 set	Side box decorative stickers	Necessary	120.00	100.00
1 pc	Rear number plate	Cut / Bent	18.00	15.00
1 set	Handle grip end, R&G	Cut	168.00	168.00
1 set	Front wheel slider, R&G	Cut	180.00	180.00
1 set	Front fender stickers	Necessary	80.00	60.00
1 set	Front fog light, Tourex	Cut	240.00	240.00
1 pc	Engine protection bar LH	Cut	250.00	250.00
1 set	Steering cone & bearing	Necessary	180.00	180.00
			<hr/>	
			3,736.00	3,693.00
	<u>Labour Charges</u>			
1	Repair and straighten front forks		350.00	250.00
2	Repair and polish engine block		250.00	220.00
3	Workmanship to remove, pair and renew damaged areas		400.00	350.00
			<hr/>	
			1,000.00	820.00
	 Total Parts & Labours Concluded		 <hr/>	
			7,746.50	7,074.40

Our Ref.: TP/1805/FY533/GP

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle. We have listed the breakdown of our findings and our recommendation as per assessment above.

Inspected by



Dylan Lee

Faithfully Yours
L H TEO Appraisal Services



Teo Liak Hoo
Advance Automotive Engineer (UK)
Dip. Mech. Engr. M Prof BTM(Dip.BTM)
MIIIE, MIMI, AMSIM