



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Officer in Charge : YOYO TIAN Tel : Email :	Attn : Tel : Fax :

Quotation No : QO18/06-1089	Quotation Date : 08/06/2018	Terms : 30 DAYS
Vehicle No : SLM3699D	Chassis No : JM6BN22A8H0149528	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: QBE, INSURED'S VEH NO:XD2851S, DATE OF ACCIDENT: 07.06.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	FRONT BUMPER	1	826.0000	826.00 X
2	FRONT BUMPER SIDE RETAINER LHS	1	92.0000	92.00 X
3	FRONT FENDER LHS	1	334.0000	334.00 BT -
4	FRONT FENDER INNER WHEEL HOUSE PANEL LHS	1	1,547.0000	1,547.00 Repair
5	FRONT FENDER INNER COWLING LHS	1	130.0000	130.00 DG -
6	FRONT FENDER INNER COWLING CLIP	10	4.5000	45.00 M -
7	FRONT FENDER AIR BAFFLE REAR	2	35.0000	70.00 ?
8	FRONT FENDER AIR BAFFLE REAR CLIPS	2	5.0000	10.00 ?
9	FRONT SHOCK ABSORBER LHS	1	287.0000	287.00 ?
10	FRONT SHOCK ABSORBER TOP MOUNT	1	92.0000	92.00 ?
11	FRONT LOWER ARM	1	485.0000	485.00 ?
12	FRONT WHEEL KNUCKLE	1	384.0000	384.00 ?
13	FRONT WHEEL BEARING WITH HUB	1	542.0000	542.00 ?
14	FRONT STABILIZE BAR	1	1,219.0000	1,219.00 ?
15	FRONT STABILIZE BAR BUSHING	2	28.5000	57.00 ?
16	FRONT STABILIZE BAR LINK	2	65.0000	130.00 ?
17	FRONT DOOR LHS	1	1,062.0000	1,062.00 Repair
18	DOOR LHS HINGE TOP	1	42.0000	42.00 X
19	DOOR LHS HINGE BOTTOM	1	40.0000	40.00 X
20	DOOR SIDE MIRROR COVER	1	123.0000	123.00 X
21	FRONT LHS WHEEL COVER	1	99.8000	99.80 DG -
22	LESS 20% ITEM (1-21)	1	-1,523.3600	-1,523.36
23	FRONT LHS RIM	1	250.0000	250.00 Repair

C/F 0.00

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : YOYO TIAN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/06-1089	Quotation Date : 08/06/2018	Terms : 30 DAYS
Vehicle No : SLM3699D	Chassis No : JM6BN22A8H0149528	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: QBE, INSURED'S VEH NO:XD2851S, DATE OF ACCIDENT: 07.06.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	FRONT LHS TYRE	1	350.0000	350.00 X
25	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	80.0000	80.00 X
26	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	1	150.0000	150.00 60
27	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	600.0000	600.00 300
28	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	500.0000	500.00 400
29	TO TRANSFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST	1	120.0000	120.00 X
30	SUSPENSION UNDERCARRIAGE PARTS, REMOVE AND RENEWAL OF PARTS, TO PERFORM FINAL CHECKING AND TESTING	1	108.0000	108.00 /

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Rasul
 Hp 90010068
 4 days
 p/p
 12/06/18 @ 1100
 Resurvey by paint

Sub Total	8,251.44
GST(7.00%)	577.60
Total (SGD)	8,829.04

Please conduct the survey at
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216