

INSURANCE

INS. CASE OWNER:

CC6 /AIG1801 0730, 14/6/18

LKE:

IDAC:

Surveyor:

Murinus

DOI:

ASSIGNMENT

12/6/18

Date / Time:

12/6/18

Registered in Merimen:

12/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLW 2014J

Name of Insured:

FENTONE Singapore Pte

Insured Tel No.:

HP:

11/6/18

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MOHAMED AMIN BIN KARIM

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

141878462057

Policy No.:

180002091

Make / Model:

mitsubishi

Place of Accident:

Moubray Ave 3 TMS OF
DEFU LANE 12

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SGC 6435P



INSRS:
WSP:
Tel:
Liability:
RMKS:

Tan
Lim



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

19/6/18

my

15-8-18 1105 W/OI STEVEN. CONFIRMED
ACC. AGREED, NO
NED ISSUE.

RECEIVED 24 AUG 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

15-8-18 JOY

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

☒

☐

After call ltr to OI:

☒

☐

Authorisation To Act:

☒

☐

Release Voucher:

☒

☐

Final Repair Bill:

☒

☐

Car Rental Invoice:

☒

☐

Towing Invoice

☒

☐

LTA / GIA:

☒

☐

Medical Bill:

☒

☐

PIR:

☒

☐

Mandate/Reject Instruction:

☒

☐

LOD

☒

☐

Payment Breakdown Form:

☒

☐

Post-Repair Photos:

☐

☐

Others:

☐

☐

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days) Reduction:

%

Email ☐

Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with

JOHANSON

Email ☐

Cal ☐

Final Liability:

%

(Agreed / Assessed) BCIA S/N No. : 28

If NO or B 28. Ass. Lia : 0

Repair Cost:

GST

SS

3,424.44

Loss of Rental (LOR):

SS

510 (560 x 8.5 days)

Loss of Use (LOU):

SS

510 (560 x 8.5 days)

Loss of Income (LOI):

SS

(5 x days)

LOR only ☐

LOU only ☐

LOR + LOU ☐

LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

7.49

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/Independent)

Legal Cost

SS

3,941.49

Total:

SS

3,941.49

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐

Cal ☐

Payee 1:

SS

3,941.49

Name 1:

TAN LIM MOTOR PTE LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

marcus

REF: ALH

ASSIGNMENT

From: Date: 12/06/2018
 Estimated Cost:
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SGC 6935P
 at Workshop m/s: Tun Lim
 of: B1 Defu Lane 10
 Insured:
 Policy No: SLW 2014J
 Claims No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh:

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 18k.
 ID No. Accident Report: Consistent? : Yes or No
 C/A / PR Seen: Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

8740C

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SGC 6935P Yr Regn: 1 06
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or (A)
 Make: Toyota corolla AH15 C.C. 15-98
 Colour: Gold A/C: Insured / Std / NI / NA
 Sp. Reading: 36452 / T/Radio: Insured / Std / NI / NA
 Eng. No:
 C/No: MA0532EC 107109797
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Bm / STD A/Rim or
 Tyre Size: F: 185/75R14
 R:
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or FALKEN
 Front: 6 mm Rear: 6 mm
 R/Bal: 6 mm L/Bal: 6 mm
 D.O.A.: 11/6/18 D.O.I.: 12/6/18
 Survey held at: —
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 14797 count. 1 23-01-2017 bal 2yrs. 7mths.

11/6/18 conf. with d/s \$3200 with karmen.

R (\$2,814.33 / 47%)

CompTime: File Pass to?

☐

Prel. Report

Days Of Repair:

1)

☐

Final Report

Resurvey No. of Trip:

CompTime: File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

Survey Fee

Transportation

1) S + F + SI

2) Station

3) Other

Report Format :

Lump Sum / I.B.R (\$

TOTAL




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18010736/Ujb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 12-06-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLW 2014J	Veh. Inspected	SGC 6935P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	11/06/2018	Inspection Date	12/06/2018
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Date of Accident : 11 June 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Miss Sim Poh Eng

Date : 11 June 2018

confirm with
marcus
12.06.2018

Estimate To Repair SGC6935P - Toyota Corolla 1.6

Chassis No : MR053ZEC107109797

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	bootlid <i>W/Buc</i>	\$ 850.00
02	1 pc	bootlid lock <i>tw</i>	\$ 60.00
03	1 pc	bootlid lock stricker <i>11</i>	\$ 26.00
04	1 pc	bootlid weatherstrip <i>Torn</i>	\$ 75.00
05	1 pc	bootlid 1.6 badge <i>nu</i>	\$ 45.00
06	1 pc	bootlid E badge <i>nu</i>	\$ 38.00
07	1 pc	bootlid corolla badge <i>nu</i>	\$ 24.10
08	1 pc	bootlid altis badge <i>nu</i>	\$ 24.10
09	1 pc	bootlid centre logo badge <i>11</i>	\$ 48.00
10	1 pc	bootlid outer chrome panel <i>11</i>	\$ 175.00
11	2 pc	bootlid refelctor @ \$85.00 <i>Missen</i>	\$ 170.00
12	1 pc	rear end panel <i>Body</i>	\$ 625.00
13	1 pc	rear end panel inner trim <i>tw</i>	\$ 75.20
14	1 pc	rear bumper <i>W.S</i>	\$ 395.00
15	2 pc	rear bumper bracket @ \$20.00 <i>but N/S</i>	\$ 40.00
16	2 pc	rear bumper side retainer @ \$25.20 <i>but</i>	\$ 50.40
17	2 pc	rear bumper side holder @ \$33.20 <i>but</i>	\$ 66.40
18	6 pc	rear bumper clips @ \$4.30 <i>nu</i>	\$ 25.80
19	2 pc	rear lamp @ \$300.00 <i>N/S one</i>	\$ 600.00
20	1 pc	rear lamp apron panel <i>N/S but</i>	\$ 110.00
21	4 pc	rear lamp apron panel rivets @ \$4.30 <i>nu</i>	\$ 17.20
22	4 pc	rear lamp clip holder @ \$4.30 <i>11</i>	\$ 17.20
23	1 pc	spare tyre carboard <i>Torn</i>	\$ 78.10
24	1 pc	spare tyre clamp <i>11</i>	\$ 16.00
25	2 pc	rear license plate lamp @ \$71.80 <i>11</i>	\$ 143.60
		Less 25 %	\$ 3,795.10
			\$ 948.77
			\$ 2,846.33
		<u>SPECIAL NETT ITEMS</u>	
26	1 pc set	rear bumper parking sensor <i>shokid</i>	\$ 450.00
27	1 pc	rear license plate <i>but</i>	\$ 80.00
			\$ 530.00
		<u>LABOUR & MISC. CHARGES</u>	
01		Panel beating, knocking and straighten the necessary portion,	\$ 1,000.00
02		remove and renewal of parts, adjust and realign the same.	\$ 950.00
03		Putty and spray painting of the affected portion.	\$ 120.00
		To reinstall of rear bumper parking sensor.	\$



陳林摩多私人有限公司
TAN LIM MOTOR PTE LTD

Date of Accident : 11 June 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Miss Sim Poh Eng

Date : 11 June 2018

Estimate To Repair SGC6935P - Toyota Corolla 1.6

Chassis No : MR053ZEC107109797

S/No	Quantity	Description	Amount
		LABOUR & MISC. CHARGES	
04		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 180.00
05		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 150.00
06		To check electrical lighting concerned.	\$ 60.00
07		To rust-proofing of the affected areas.	\$ 180.00
			\$ 2,640.00
		Total	\$ 6,016.33

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2964.30
2223.22
4107.22
3285.78

60
80
20
60
4107.22

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 8740C

Vehicle Details

Vehicle No.: SGC6935P
Vehicle to be Exported: Yes
Intended De-registration Date: 22 Jan 2018
Vehicle Make: TOYOTA
Vehicle Model: COROLLA 1.6
Primary Colour: Gold
Manufacturing Year: 2005
Engine No.: 3ZZ4538482
Chassis No.: MR053ZEC107109797
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$16,772.00
Original Registration Date: 24 Jan 2006
First Registration Date: 24 Jan 2006
Transfer Count: 1
Actual ARF Paid: \$18,450.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 23 Jan 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$28,317.00
COE Rebate Amount: \$17,005.00
Total Rebate Amount: \$17,005.00

Message

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	8740C

Vehicle Details

Vehicle No.:	SGC6935P
Vehicle to be Exported:	No
Intended De-registration Date:	12 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA 1.6
Primary Colour:	Gold
Manufacturing Year:	2005
Engine No.:	3ZZ4538482
Chassis No.:	MR053ZEC107109797
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$16,772.00
Original Registration Date:	24 Jan 2006
First Registration Date:	24 Jan 2006
Transfer Count:	1
Actual ARF Paid:	\$18,450.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	23 Jan 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$28,317.00
COE Rebate Amount:	\$14,797.00
Total Rebate Amount:	\$14,797.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Jun 2018

OK



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Address: 51 Defu Lane 10 Singapore 539216

Tel: 6858 5151 Fax: 6858 0877

Our Ref : TP017062018

Date : 27.07.2018

Your Ref : SW2014J

WITHOUT PREJUDICE

Claims Department - **Motor Claims**

c/o **ALH ASIA PACIFIC INSURANCE P/L**

Dear Sir/Madam,

ACCIDENT INVOLVING SGC 6935P & SW2014J ON 14.06.2018

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

☐ Original survey report/ _____ copies of photographs _____

☒ Original Tax-invoice number TP0181017

☐ Original rental invoice number

☒ SAS / AS & IS / police report

☐ police result

☒ Certificate Of Insurance

☒ Vehicle search result

☒ Authorisation To Act

☐ _____

*Survey under insurance instruction - LKK

a)	Cost of repair (inclusive GST)	\$	3,424.00
b)	Survey fees / Photographs as per request	\$	
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$	7.49
d)	Loss of hire / use / rental / earnings / rental fees [120x9 days]	\$	1,080.00
e)	Scene photographs	\$	
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$	
g)		\$	
Total		\$	4,511.49

* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Johnson Chua

Email: johnson.chua@tlmotor.com.sg

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Wednesday, 15 August 2018 11:26 AM
To: 'steven.chia@kenzonegroup.com'
Cc: Admin A
Subject: ACCIDENT INVOLVING SLW 2014J / SGC 6935P / OTHERS ON 11/06/2018

Our ref: CC6/AIG18010736/Ujb3

KENZONE SINGAPORE PTE LTD

Policy Holder

Dear Sir,

ACCIDENT INVOLVING SLW 2014J / SGC 6935P / OTHERS ON 11/06/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

As discussed, we are following the guideline and as per standard procedure of settling chain collision cases, driver of the vehicle behind will be liable for the losses incurred by the vehicle immediately in front only to avoid costly litigation for collision damages. However, we take note that your vehicle was being pushed forward from behind in this incident.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Sim Poh Eng ("the third party claimant")
of Block 211D Compassvale Lane #05-286 Singapore 544111 (address),
owner of SGC6935P (vehicle no.) hereby authorize
Tan Lim Motor Pte Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SGC6935P that was
damaged pursuant to the accident which occurred on 11.06.2018 (date) along
Hougang Avenue 3 (location)
involving vehicle no/s SLW2014J ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 19 day of 06 (month) 20 18 (year)


Signed by "the third party claimant"

 
Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, TAN LIM MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$3,424.00 (Repair Cost), S\$510.00 (Loss of ^{USE} Rental) S\$7.49 (Disbursement) for vehicle no. SGC 6935P that was damaged pursuant to the accident which occurred on 11/06/2018 (date) along HOUGANG AVE 3 (location) involving vehicle no/s SLW 2014J. This is pursuant to the inspection conducted on 12/06/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SIM POH ENG ("the third party claimant") of vehicle no. SGC 6935P make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SGC 6935P (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 21st (day) of August (month) **2018** (year)



Signed by appointed surveyor

The image shows a handwritten signature and a circular stamp. The stamp contains the text "TAN LIM MOTOR PTE LTD" around the perimeter and "TEL: 6832 5151" in the center.

Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



TAX-INVOICE
NUMBER: TP0718/017

(Please quote our reference number TP017062018 for payment)

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Sim Poh Eng

Date: 05/07/2018

Vehicle No: SGC6935P
Model: TOYOTA COROLLA 1.6

Description	Amount
To lump sum repair as recommended by surveyor.	\$3,200.00
Reimbursement of LTA search fees.	\$7.00

Sub Total	\$3,207.00
Add 7% GST	\$224.49
Total	\$3,431.49



Tan Lim Motor Pte Ltd

1 Enquire Vehicle & Owner Information (Vehicle No. SLW2014J As At 11 Jun 2018 / 08:30:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: TLM(CAYMEN)SGC6935P

Current Owner Details

Owner ID Type: Company
Owner ID: 200204837C
Owner Name: KENZONE SINGAPORE PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.:150
Registered Street Name: UBI AVENUE 4
Registered Unit No.: # 05 - 07/08
Registered Building Name: UBI BIZ-HUB
Registered Postal Code: 408825

Current Vehicle Details

Vehicle No.: SLW2014J
Make Description/Model: MITSUBISHI / ATTRAGE 1.2 CVT
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jun 2018 Edit Reg		12 Jun 2018 00:00 Edit Adj Rpt	\$53,200.00 Edit Estimates	\$53,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	KENZONE SINGAPORE PTE LTD , Co. Reg. No.: -								
Main Claimant:	SIM POH ENG , ID: S1458740C								
Vehicle Reg. No.:	SGC6935P	Date of Loss:	11/06/2018 00:00 - :59 [148 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1918784620SG	Policy/Cover Note No.:	1800010291						
Vehicle Reg. No. (Insured):	SLW2014J	Policy No. (Claimant):	5052771920-06						
		Excess:							
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 22/06/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (13/06/2018): TP GIA REPORT									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGC6935P (1918784620SG)**
[SLW2014J]
TP
SIM POH ENG
Jun 11 2018 12:00AM
[KENZONE SINGAPORE PTE LTD]
Tan Lim Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser	
Letters/Correspondences													1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown												Edit		
Assessment Reports													1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)											Thumbnail	Print		
1	13/06/18 14:33	Accident Statement <small>From: SC - Reg. No: SLW2014J, Claimant: KENZONE SINGAPORE PTE LTD</small>												Load HTM		
Photos/Images													3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print		
1	12/06/18 17:55	Chassis Number												Load JPG <input checked="" type="checkbox"/>		
2	12/06/18 17:56	Odometer Reading												Load JPG <input checked="" type="checkbox"/>		
3	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
4	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
5	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
6	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
7	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
8	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
9	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
10	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
11	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
12	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
13	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
14	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
15	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
16	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
17	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
18	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
19	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
20	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
21	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
22	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
23	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
24	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
25	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
26	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
27	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
28	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
29	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		
30	12/06/18 17:56	General View												Load JPG <input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
32	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
33	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
34	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
35	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
36	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
37	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
38	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
39	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
40	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
41	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
42	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
43	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
44	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
45	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
46	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
47	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
48	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
49	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
50	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
51	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
52	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
53	12/06/18 17:56	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/06/18 18:37	TP ESTIMATE- MARKED	 Load PDF	
2	13/06/18 18:37	TP GIA REPORT	 Load PDF	
3	27/08/18 08:26	WORKSHOP INVOICE	 Load PDF	
4	27/08/18 08:26	AUTHORISATION TO ACT FORM	 Load PDF	
5	27/08/18 08:26	Release Voucher	 Load PDF	
6	27/08/18 08:26	LTA SEARCH	 Load PDF	
7	27/08/18 08:26	LETTER TO OI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLW2014J (Insd veh)	Model:	TOYOTA COROLLA 1.6 (A)
	SGC6935P (TP veh)		
Date of Accident:	11/06/2018		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$	6,437.46	
Final Repair Cost	:	\$	3,424.00	
Loss of Use	:	\$	510.00	8.50 days at \$60.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	7.49	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	3,941.49	

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability __100__ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ 0 _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Tan Lim Motor Pte Ltd	:	\$ 3,941.49
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

27 Aug
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18010736/UJB3Q2

Date: 27/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800010291
Claimant Vehicle No : SGC6935P **Insured Vehicle No :** SLW2014J
 Date of Loss: 11/06/2018 Nature of Claim: TP Claim No: 1918784620SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGC6935P**
 Make & Model: TOYOTA COROLLA, 1.6 (A) Engine No: 3ZZ4538482
 Reg. Date: 24/01/2006 (Man. Year: 2005) Chassis No: MR053ZEC107109797
 Colour: Gold Odometer: 364521 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/75 R14 Rear Tyre Size: 185/75 R14
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,376.32	2,437.22	939.10	27.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,640.00	1,670.00	970.00	36.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,016.32	4,107.22	1,909.10	31.73
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	6,016.32	3,200.00	2,816.32	46.81
+ GST 7.00/7.00% (S\$)	421.14	224.00	197.14	46.81
Nett Amount (S\$)	6,437.46	3,424.00	3,013.46	46.81
+ Loss of Use (8.5 x S\$60.00/day) (S\$)		510.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,941.49		

INSPECTION

Date of Assignment: 12/06/2018
 Date Inspected: 12/06/2018 Inspected At: Tan Lim Motor Pte Ltd (Defu)
 51 Defu Lane 10
 Singapore 539216

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Buckled	850.00 FL	*850.00 FL
2	1		*BOOTLID LOCK	Twisted	60.00 FL	*60.00 FL
3	1		*BOOTLID LOCK STICKER	Not Necessary	26.00 FL	*- FL
4	1		*BOOTLID WEATHERSTRIP	Torn	75.00 FL	*75.00 FL
5	1		*BOOTLID 1.6 BADGE	Necessary	45.00 FL	*45.00 FL
6	1		*BOOTLID E BADGE	Necessary	38.00 FL	*38.00 FL
7	1		*BOOTLID COROLLA BADGE	Necessary	24.10 FL	*24.10 FL
8	1		*BOOTLID ALTIS BADGE	Necessary	24.10 FL	*24.10 FL
9	1		*BOOTLID CENTRE LOGO BADGE	Not Necessary	48.00 FL	*- FL
10	1		*BOOTLID OUTER CHROME PANEL	Not Necessary	175.00 FL	*- FL
11	1		*BOOTLID REFLECTOR	N/S Scratched	170.00 FL	*85.00 FL
12	1		*REAR END PANEL	Badly Dented	625.00 FL	*625.00 FL
13	1		*REAR END PANEL INNER TRIM	Twisted	75.20 FL	*75.20 FL
14	1		*REAR BUMPER	Distorted	395.00 FL	*395.00 FL
15	1		*REAR BUMPER BRACKET	N/S Bent	40.00 FL	*20.00 FL
16	2		*REAR BUMPER SIDE RETAINER	Bent	50.40 FL	*50.40 FL
17	2		*REAR BUMPER SIDE HOLDER	Bent	66.40 FL	*66.40 FL
18	6		*REAR BUMPER CLIPS	Necessary	25.80 FL	*25.80 FL
19	1		*REAR LAMP	N/S Cracked	600.00 FL	*300.00 FL
20	1		*REAR LAMP APRON PANEL	N/S Bent	110.00 FL	*110.00 FL
21	4		*REAR LAMP APRON PANEL RIVETS	Necessary	17.20 FL	*17.20 FL
22	4		*REAR LAMP CLIP HOLDER	Not Necessary	17.20 FL	*- FL
23	1		*SPARE TYRE CARBOARD	Torn	78.10 FL	*78.10 FL
24	1		*SPARE TYRE CLAMP	Not Necessary	16.00 FL	*- FL
25	2		*REAR LICENSE PLATE LAMP	Not Necessary	143.60 FL	*- FL
26	1		*SET REAR BUMPER PARKING SENSOR	Shorted	450.00 FS	*200.00 FS
27	1		*REAR LICENSE PLATE	Bent	80.00 FS	*14.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,325.10	3,178.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	948.78	741.08
Total Parts (\$\$)	3,376.32	2,437.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,000.00	600.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	950.00	800.00
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
4	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	60.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER,TO ENABLE REPAIR	New	150.00	80.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
7	TO RUST-PROOFING OF THE AFFECTED AREAS	New	180.00	60.00
Gross Labour Cost (S\$)			2,640.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >