



TAN LIM MOTOR PTE LTD

Date of Accident : 11 June 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Miss Sim Poh Eng

Date : 11 June 2018

confirm with
marcus

12.66.2018

Estimate To Repair SGC6935P - Toyota Corolla 1.6
Chassis No : MR053ZEC107109797

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	bootlid <i>W/Buc</i>	\$ 850.00
02	1 pc	bootlid lock <i>W/Buc</i>	\$ 60.00
03	1 pc	bootlid lock stricker <i>11</i>	\$ 26.00
04	1 pc	bootlid weatherstrip <i>Torn</i>	\$ 75.00
05	1 pc	bootlid 1.6 badge <i>ru</i>	\$ 45.00
06	1 pc	bootlid E badge <i>ru</i>	\$ 38.00
07	1 pc	bootlid corolla badge <i>ru</i>	\$ 24.10
08	1 pc	bootlid altis badge <i>ru</i>	\$ 24.10
09	1 pc	bootlid centre logo badge <i>11</i>	\$ 48.00
10	1 pc	bootlid outer chrome panel <i>11</i>	\$ 175.00
11	2 pc	bootlid refelctor @ \$85.00 <i>Missen</i>	\$ 170.00
12	1 pc	rear end panel <i>Body</i>	\$ 625.00
13	1 pc	rear end panel inner trim <i>W/Buc</i>	\$ 75.20
14	1 pc	rear bumper <i>W/Buc</i>	\$ 395.00
15	2 pc	rear bumper bracket @ \$20.00 <i>But 115</i>	\$ 40.00
16	2 pc	rear bumper side retainer @ \$25.20 <i>But</i>	\$ 50.40
17	2 pc	rear bumper side holder @ \$33.20 <i>But</i>	\$ 66.40
18	6 pc	rear bumper clips @ \$4.30 <i>ru</i>	\$ 25.80
19	2 pc	rear lamp @ \$300.00 <i>115 one</i>	\$ 600.00
20	1 pc	rear lamp apron panel <i>W/Buc But</i>	\$ 110.00
21	4 pc	rear lamp apron panel rivets @ \$4.30 <i>ru</i>	\$ 17.20
22	4 pc	rear lamp clip holder @ \$4.30 <i>11</i>	\$ 17.20
23	1 pc	spare tyre carboard <i>Torn</i>	\$ 78.10
24	1 pc	spare tyre clamp <i>11</i>	\$ 16.00
25	2 pc	rear license plate lamp @ \$71.80 <i>11</i>	\$ 143.60
		Less 25 %	\$ 3,795.10
			\$ 948.77
			\$ 2,846.33
		<u>SPECIAL NETT ITEMS</u>	
26	1 pc set	rear bumper parking sensor <i>shotted</i>	\$ 450.00
27	1 pc	rear license plate <i>But</i>	\$ 80.00
			\$ 530.00
		<u>LABOUR & MISC. CHARGES</u>	
01		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,000.00
02		Putty and spray painting of the affected portion.	\$ 950.00
03		To reinstall of rear bumper parking sensor.	\$ 120.00



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

Date of Accident : 11 June 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Miss Sim Poh Eng

Date : 11 June 2018

Estimate To Repair SGC6935P - Toyota Corolla 1.6
Chassis No : MR053ZEC107109797

S/No	Quantity	Description	Amount
		LABOUR & MISC. CHARGES	
04		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 180.00
05		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 150.00
06		To check electrical lighting concerned.	\$ 60.00
07		To rust-proofing of the affected areas.	\$ 180.00
			\$ 2,640.00
		Total	\$ 6,016.33

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

60
80
20
60
4107.22

2964.30
2223.22
4107.22
3285.78.