Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183

Reference : PA/OD/0673/2018/PH

Date : 11-Jun-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Huan Peng

Address : 111 Jalan Jurong Kechit

#02-03

Singapore 1598874

Telephone : HP +65 93893943

Type of Claim : Own Damage Claim

Policy No. : 2100492161-01

Vehicle No : SLJ 1579 X

Model Code : Audi A4 1.4 TFSI

Model / Year : Nov-16
Engine No : CVN0242319

Chassis No : WAUZZZF48HA066150

Mileage : Date In : Liability : Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 5-Jun-18

Place of Accident : Clementi Road, bridge over AYE

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLJ 1579 X.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	
2	To dismantle and renew front bumper, lhs front fender and headlight. Re-organise front crash management components. Reinstall all parts removed.		\$ 2,100.00	(159
3	To respray front bumper, lhs front fender & lhs front door.		\$ 2,000.00	1650
4	To renew lhs front tyre.Carry out wheel alignment.	S/N	\$ 280.00	*
5	To carry out diagnostic check.	S/N	\$ 192.00	/
	SUB-LABOUR CHARGES	:	\$ 4,932.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 1579 X.

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

S/N	Parts Description			Damage Parts & Prices S/NETT REMARKS
	٨			
1	BUMPER COVER Deficed		\$	1,849.00
2	FIXING PARTS FOR FOR BUMPER 7		\$	245.00 <i>X</i>
3	SECURING STRIP	2	\$	60.00 ₹
4	CLOSING ELEMENT - LOWER CENTRE FIL NEW		\$	180.00⊀
5	AIR GUIDE - LH		\$	73.00 ¥
6	AIR GUIDE GRILLE - LH		\$	118.00 🖟
7	FENDER - LH DISTARL		\$	665.00
8	ATTACHMENT PARTS FOR ONE FENDER ?		\$	45.00
9	CLOSING ELEMENT - LH		\$	44.00 1
10	BRACKET FOR FENDER - LH		\$	31.00
11	BRACKET FOR DEFORMATION ELEMENT H		\$	43.00
12	BRACE - LH FRONT 34		\$	103.00 🗸
13	WHEEL HOUSING LINER - LH tow		\$	215.00
14	ATTACHMENT PARTS FOR WHEEL HOUSING LINER		\$	78.00 ?
15	WHEEL SPOILER - LH ?		\$	63.00 ?
16	STONE CHIP GUARD WW		\$	44.00
17	LED HEADLIGHT - LH CM		\$	6,973.00
18	LIFT CYLINDER - LH New		\$	184.00 *
19	COVER-LH ZNICC		\$	20.00 🗸
20	COVER - LH		\$	27.00 🗸
21	TYRE BH M	1	TBC	; *
22	sundries ?		\$	300.00 ?
	TOTAL SPARE PARTS	:	\$	11,360.00
	TOTAL LABOUR CHARGES	:	\$	4,432.00
	GRAND TOTAL	:	\$	15,792.00
	All charges are not inclusive of GST.			

Premium Automobiles

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Not Authorsed, OSDays

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant