

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00
 Springleaf Tower
 Singapore 079909
 Tel : 6389 - 6111
 Fax : 6224 - 7478 / 7175

Thin Thin

Quotation
 DATE : 12.06.2018
 VEH NO : SKU2524B
 MODEL : Lexus IS250
 D O A : 11.06.2018
 YR REF : GBC539Z

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKU2524B (Lexus IS250)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Bumper <i>behind</i>	1	881.90 ✓
2	Front Bumper Clips <i>m</i>	1 set	30.00 ✓
3	Front Bumper Side Holder - RH <i>m</i>	1	85.40 ✓
4	Front Bumper Reinforcement <i>inner</i>	1	389.20 ✗
5	Front Bumper Fog Lamp - RH <i>inner</i>	1	325.40 ✗
6	Front Bumper Lower Spoiler <i>Repair</i>	1	681.00 ✗
7	Headlamp - RH <i>at</i>	1	2,188.00 ✓
8	Front Fender - RH <i>Repair</i>	1	731.40 ✗
9	Front Fender Inner Shield - RH <i>behind</i>	1	250.30 ✓
10	Front Fender Inner Shield Clips - RH <i>m</i>	1 set	30.00 ✓

10%
 Less 10%
 \$ 5,592.60
 (1,118.52)
 \$ 4,474.08

Total parts **\$ 4,474.08**

LABOUR CHARGE

1	To knocking out front portion & renew above parts	\$ 800.00 400
2	To putty & spray up paint works	\$ 600.00 500
3	To check wiring system	\$ 50.00 30

Total Labour \$ 1,450.00

Grand Total **\$ 5,924.08**

total: 4048.77

*h/c 32K
 04 Days*

RE : ESTIMATE FOR ACCIDENT REPAIR SKU2524B (Lexus IS250)

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: