



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20180611/0722	LOCATION OF FIRE:		
FIRE REPORTED ON : 11 June 2018	Along the Tampines Expressway service road		
TIME OF CALL : 19:17:08 hrs	between Seletar West Link & Seletar Aerospace Way		
STATION COVERAGE : Ang Mo Kio Fire Station	Singapore		
2. INCIDENT INFORMATION			
FIRE INVOLVED: A car (make, model and registration plate number burnt beyond recognition) at the above said location.			
METHOD OF EXTINGUISHMENT: By SCDF crew using two 38mm compressed air foam hose lines from fire appliance.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating at the engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, the car was damaged.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:			
DANNIES ANG WEITONG for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.