

LKK: 57543
 IDAC: 13/6/2018
 4 ASM 160 10779, K 332
 Kenneth
 Surveyor: Kenneth
 DOI: 11-06-18 (13/6/18)
 Date / Time: 13/6/2018
 Registered in Merimen:
 Pre-assign / CCU / FTE: GT5336K
 Insured Vehicle No.: GT5336K
 Name of Insured: JIN ANGR ENH. PLC
 Insured Tel No.: HP:
 Excess Sec II : \$\$ 1000.00 D.O.A: 6-6-18
 Is driver the owner? (YES / NO) Nature of Accident:
 If NO, Driver Name / Age: Singham Anandan
 Driver Tel No.: 98301277 (V/L: YES / NO)
 OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
 Insured Liability: % Final ? Yes / No
 SLK 6081 B → GT5336K → SLA 1150 X
 INSRs: WSP: Tel: Liability: RMKS:
 INSRs: WSP: Tel: Liability: RMKS:
 INSRs: WSP: Tel: Liability: RMKS:
 INSRs: WSP: Tel: Liability: RMKS:

Date / Time	STAGE	DATE / PIC
19/6	Non-Reporting ltr (1st):	
19/6	Non-Reporting ltr (2nd):	
19/6	Non-Reporting ltr (Final):	
19/6	Notification ltr (if non-pickup):	
19/6	Call OI:	21/9/18
19/6	After call ltr to OI:	21/9/18
27/6/18	Documentation Check List:	Handler Typist
27/6/18	Notification ltr (if non-pickup)	
27/6/18	After call ltr to OI:	
27/6/18	Authorisation To Act:	
27/6/18	Release Voucher:	
27/6/18	Final Repair Bill:	
27/6/18	Car Rental Invoice:	
27/6/18	Towing Invoice:	
27/6/18	LTA / GIA:	
27/6/18	Medical Bill:	
27/6/18	PIR:	
27/6/18	Mandate/Reject Instruction:	
27/6/18	LOD:	
27/6/18	Payment Breakdown Form:	
27/6/18	Post-Repair Photos:	
27/6/18	Others:	

PRELIMINARY ADVICE Date/Time: 18/6 Sent By:
 FINALIZATION Date/Time: Confirm with: Confirm by:
 Repair Cost: \$\$ (days) Reduction: % Email ☐ Call ☐
 FINAL SETTLEMENT Date/Time: 21/11/19 Confirm with: Kenny Email ☐ Call ☐
 Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 28
 Repair Cost: w/h 6662.46
 Loss of Rental (LOR): \$\$ 1040.00 (8 days) X \$130-w
 Loss of Use (LOU): \$\$ (\$ - x days)
 Loss of Income (LOI): \$\$ (\$ - x days)
 LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]
 GIA/LTA Search: \$\$ 2.00
 Medical: \$\$
 Disbursement: \$\$ (e.g. Tow/ Independent)
 Legal Cost: \$\$
 Total: \$\$ 7704.46 Global Sum SS: 7700-w
 FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐
 Payee 1: \$\$ 7700-w Name 1: Alan's United Auto Pte Ltd
 Payee 2: (Strike if N.A.) \$\$ Name 2:
 Payee 3: (Strike if N.A.) \$\$ Name 3:

ASS. REC. BY:

REF: AA/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop mv's _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8826

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 4/6 days

Res.: Yes or No

Lum Sum: 1-31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLA1150XYr Regn: 01.06Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mazda CX5c.c. 1998Colour: M. Grey

A/C: _____

Insured / Std / NI / NA

Sp. Reading 74738

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: JM6KE 1072G-034P487Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD / Rim orTyre Size: F: 225/65R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. P mmL/Bal. 8 mmD.O.A. 8/8/18D.O.I. 11/6/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/6 File pass to CatherinePIP \$ 624.60 (Reel \$ 2465.08 / 324.1)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + R.S. \$ _____

Factors _____

Others _____

TOTAL

Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

Tech Invs (\$ _____)

☐

Weekend (\$ _____)

Report Format: _____

Lump Sum / I.B.I. (\$) _____




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18010779/Kwa3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 13-06-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GT 5336K	Veh. Inspected	SLA 1150X	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00K0G	Excess (\$)	0.00	
Assign From		Assign Date	13/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/06/2018	Inspection Date	13/06/2018	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Kw

GST Reg. No.: 201113667N

Not withdrawn
1-B.1
Penny B & paint
5 days

=====

150.00 1201

43 120.00 ?

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GT5336K

Page : 2

To apply undersealing	60.00	301
To putty and spray replaced parts	900.00	600
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts	850.00	500
Total :	S\$ 9,191.68	

Singapore Dollars Nine Thousand One Hundred and
Ninety One and Cents Sixty Eight Only

P 4857.60
SN 85
L 1290.00
6226.60 ✓ ok
①
5 days
→ Kenneth pls confirm
TKS

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05791

Vehicle Insured : GT5336K

Accident Date : 06-Jun-2018

Date : 08-Jun-2018

Our Ref : 218095 (AXA) / CHAN

PAGE : 1

LEE HON HUAN

BLK 734 JURONG WEST STREET 73

#08-06

Singapore 640734

Not authorized
1-B.1
Person B & party

ESTIMATED COST OF REPAIR FOR MAZDA CX5 2.0 SLA1150X

QTY	DESCRIPTION	UNIT PRICE	TOTAL PRICE	REMARKS
1 pc	Tail gate		1,479.70	
1 pc	Tail gate glass inner seal		42.10	
1 pc	Tail gate logo		51.70	
1 pc	Tail gate outer garnish		437.10	
1 pc	Tail gate "CX-5" emblem		45.30	
1 pc	Tail gate "SKYACTIV" plate		71.60	
2 pcs	Tail gate license plate lamp	@ S\$ 42.10	84.20	
1 pc	Tail gate wiper motor		412.50	
2 pcs	Tail gate lamp	@ S\$ 466.60	933.20	
2 pcs	Tail lamp	@ \$1201.00	2,402.00	
1 pc	Rear end panel		473.90	
1 pc	Rear bumper fascia		1,218.00	
2 pcs	Rear bumper tow cover	@ S\$ 8.00	16.00	
1 pc	Rear bumper reinforcement		584.80	
			8,252.10	
Less 20% :			1,650.42	

```
1 pc Rear no.plate with box
1 pc Rear bumper reverse sensor(4pc
1 pc Rear w/s glass sealant
```

6,601.68
 45 sn 50.00 sn
 400.00 sn
 40 sn 60.00 sn

To remove & refix rear windscreen glass and conduct water leak test.

150.00 1201

To remove roof lining, front and rear seats, trim board and carpet

40 120.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey ~~before~~ after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date:

Con't Page 2 ...

24468.76
? 2614.32
2750

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GT5336K

Page : 2

To apply undersealing

60.00 *301*

To putty and spray replaced parts

900.00 *6001*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

520 850.00 *2*

Total :

S\$ 9,191.68
=====

Singapore Dollars Nine Thousand One Hundred and
Ninety One and Cents Sixty Eight Only



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 18/6/2018

Survey Details:

Date of loss	6-Jun-18
Date of appointment	13-Jun-18
Date of survey	13-Jun-18
Location of survey	Alan's United Auto Pte Ltd

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SLA 1150X
Make and Model	MAZDA CX-5 - 1998cc
Date of registration	22-Jan-16
Excess	
Market Value	\$ 82,000.00
Part Rebate	\$ 64,892.00
Nett Loss	\$ 17,108.00

Repair details:

Initial Estimate	\$ 9,191.68
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 4,468.76
Check items (estimate)	\$ 2,614.32
Labour	\$ 750.00
Total	\$ 7,833.08
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>4-6 days</u>
---------------------------	-----------------

Vehicle Registration Detail Information

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert No.:	S7978823F
Owner ID Type:	Singapore NRIC
Owner Name:	LEE HON GUAN
Registered Address:	APT BLK 734 JURONG WEST STREET 73 #08-06 SINGAPORE 640734
Mailing Address:	-
Birth Date:	04 Apr 1979

Vehicle Particulars

Vehicle No.:	SLA1150X
Previous Vehicle No.:	-
Effective Date of Ownership:	22 Jan 2016
Original Regn Date:	22 Jan 2016
Registration Date:	22 Jan 2016
Year of Manufacture:	2015
Vehicle Type:	Passenger Station Wagon/Jeep/Land Rover
Vehicle Scheme:	-
Vehicle Attachment 1:	No Attachment
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Make:	MAZDA
Vehicle Model:	CX-5 SKYACTIV-G 2.0 SP.6EAT 2WD LED
Primary Colour:	Grey
Secondary Colour:	-
Passenger Capacity:	4
Chassis No.:	JM6KE1072G0349487
Engine No.:	PE10290149
Engine Capacity / Power Rating:	1998 cc / -
Maximum Power Output:	121.0 kW (162 bhp)
Propellant:	Petrol
Max Unladen Weight:	1528 kg
Maximum Laden Weight:	1978 kg
Open Market Value:	\$24,136.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jan 2026
Minimum PARF Benefit:	\$12,895.00
No. of Transfers:	0
IU Label No.:	1126248730
COE No.:	2016010107000245C
COE Expiry Date:	21 Jan 2026
COE Category:	E - Open Category
COE Registration Category:	B - Car above 1600cc or 97kW (130bhp)
Quota Premium (QP) / Prevailing Quota Premium:	\$60,003.00 / -
Actual QP Paid:	\$60,003.00
QP (Regn Cat):	\$60,001.00
OPC Cash Rebate Eligibility:	No
QP during COE Bidding Exercise:	\$60,003.00
Additional Registration Fee Rate:	First \$20,000.00 (100%), next \$4,136.00 (140%)
Actual ARF Paid:	\$25,791.00
Vehicle Lifespan Expiry Date:	No Lifespan
CO2 Emission:	148.00 (g/km)
CEV/VES Rebate Utilised Amount:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-
Message:	COE rebate, if applicable, will be based on the QP of \$60,001.00. This is the lower of QP from Category E and the corresponding Category B in the same tender exercise. To renew the COE, the Prevailing Quota Premium payable is that of Category B.




Service Request Details

Claim

S8M00K0G

Reference

None 

Loss Date

June 6, 2018

Request Date

June 13, 2018

Due Date

June 21, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

13062018 @ 11.24 am
Kenny veh in
Kenneth sunny on 13062018.

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLA1150X

Make

Model

Service Address

28 JALAN BUROH, ., 619484

Primary Contact/Insured

JIN QUAN ENGINEERING PTE. LTD.
28 JALAN BUROH, 619484, Singapore
65471626

Claim Handler

TAY Ernest
6568804835
ernest.tay@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message



Re:S8M00K0G-mandate approval

Type

🔔 Question

Message

COR \$6,291.60 W/GST LOR \$960 (8DAYS) LTA \$2.00 TOTAL \$7,253.60

Reply



RE: Re:S8M00K0G-mandate approval

Type

🔗 Question

Message

Hi, Third party rejected our offer at \$7,253.60(all-in) and proposed \$7,944.46(all-in). The breakdown of third party propose is as follows: - 1)Cost of Repair (w/GST):\$6,662.46 + 2.)Loss of Rental (8days x \$160.00): \$1,280.00 + 3). LTA/GIA Search Fee: \$2.00 = TOTAL: \$7,944.46. For your further mandate / instruction please.
Hsiao Tong - 20 Aug 2019

Reply

Hsiao Tong (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Tuesday, 20 August 2019 3:06 PM
To: Hsiao Tong (LKKAuto)
Subject: FW: New message for service request 51543, vehicle number SLA1150X

20/8/19 10:07 AM *** Message PLS PROCEED AS FOLLOWS COR \$6,500.00 LOR \$1,027.20 (8DAYS) LTA \$2.00 TOTAL \$7,529.20 *LOR SUBJECTED TO TP RENTED VEH. - CHAN Kian Chuan

-----Original Message-----

From: kianchuan.chan@axa.com.sg <kianchuan.chan@axa.com.sg>
Sent: Tuesday, 20 August, 2019 10:08 AM
To: admin-d@lkkauto.com
Subject: New message for service request 51543, vehicle number SLA1150X

AXA Insurance has sent you a message for claim number S8M00K0G.

Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



RE: Re:RE: Re:S8M00K0G-mandate approval

Type

🔔 Question

Message

Hi, Third party rejected our offer at \$7,529.20(all-in) and proposed \$7,944.46(all-in). The breakdown of third party propose is as follows: - 1)Cost of Repair (w/GST):\$6,662.46 + 2.)Loss of Rental (8days x \$160.00): \$1,280.00 + 3). LTA/GIA Search Fee: \$2.00 = TOTAL: \$7,944.46. For your further mandate / instruction please, Hsiao Tong - 12 Oct 2019

Reply

Hsiao Tong (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Monday, 14 October 2019 2:35 PM
To: Hsiao Tong (LKKAUTO)
Subject: FW: New message for service request 51543, vehicle number SLA1150X

14/10/19 2:28 PM *** MessageREVISED OFFER @ \$7,700.00 ALL IN - CHAN Kian Chuan

-----Original Message-----

From: kianchuan.chan@axa.com.sg <kianchuan.chan@axa.com.sg>
Sent: Monday, 14 October, 2019 2:29 PM
To: admin-d@lkkauto.com
Subject: New message for service request 51543, vehicle number SLA1150X

AXA Insurance has sent you a message for claim number S8M00K0G.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.
This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Hsiao Tong (LKKAuto)

From: alan khong chin wah <alanauto@gmail.com>
Sent: Saturday, 2 November 2019 9:47 AM
To: Hsiao Tong (LKKAuto)
Subject: Re: Your Ref: SLA1150X *Our Ref: CC4/ASM18010779/Kpa3 [ACCIDENT INVOLVING GT 5336K(AXA) / SLA 1150X/ OTHERS ON 06/06/2018]

OK OFFER ACCEPTED AT \$7700 (ALL IN)

Regards
Kenny
Alan's United Auto Pte Ltd
64538686

On Sat, Nov 2, 2019 at 8:53 AM Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:

Without Prejudice

(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to maintain offer at a global sum of \$7,700.00(all-in).

Kindly re-consider our offer.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: alan khong chin wah <alanauto@gmail.com>

Sent: Tuesday, 29 October 2019 12:57 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Re: Your Ref: SLA1150X *Our Ref: CC4/ASM18010779/Kpa3 [ACCIDENT INVOLVING GT 5336K(AXA) / SLA 1150X/ OTHERS ON 06/06/2018]

Hi Hsiao Tong

Offer not accept , we like to counter propose COR \$6662.46 (with GST) , RENTAL \$160 x 8 days = \$1280 and search fee \$2.00

Total is \$7944.46 , kindly look into the matter & revise your offer to us again thank you .

Regards

Kenny

Alan's United Auto Pte Ltd

64538686

On Sat, Oct 26, 2019 at 11:38 AM Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:

Without Prejudice

(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to revise offer at a global sum of \$7,700.00(all-in).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: alan khong chin wah <alanauto@gmail.com>

Sent: Monday, 26 August 2019 11:50 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Re: Your Ref: SLA1150X *Our Ref: CC4/ASM18010779/Kpa3 [ACCIDENT INVOLVING GT 5336K(AXA) / SLA 1150X/ OTHERS ON 06/06/2018]

Dear Hsiao Tong

Your offer NOT Accept , our LOD show is \$6662.46 that is finalize with your surveyor , and wonder how you get the rental amount of \$1027.20 , if base on BOLA benchmark , rental is \$120-\$180 , we counter propose for \$160 per day , thank you .

Regards

Kenny

Alan's United Auto pte Ltd

64538686

On Mon, Aug 26, 2019 at 11:33 AM Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to offer as follows: -

1. Cost of Repair (w/GST)	\$ 6,500.00
2. Loss of Rental (8days x \$120.00)(w/GST)	\$ 1,027.20
3. LTA/GIA Search Fee	\$ 2.00
Total	\$ 7,529.20

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: alan khong chin wah <alanauto@gmail.com>

Sent: Saturday, 17 August 2019 9:21 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Re: Your Ref: SLA1150X *Our Ref: CC4/ASM18010779/Kpa3 [ACCIDENT INVOLVING GT 5336K(AXA) / SLA 1150X/ OTHERS ON 06/06/2018]

Hi Hsiao Tong

Please refer to our counter propose email on 18-01-2019 , your surveyor recommend COR and you offer us the amount is difference , the rental also propose for \$160 per day , kindly check again thank you .

Regards

Kenny

Alan's United Auto pte Ltd

64538686

On Sat, Aug 17, 2019 at 8:57 AM Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:

Your Ref: **SLA1150X** **Without Prejudice**

Our Ref: CC4/ASM18010779/Kpa3

Dear Sirs/Mdm,

ACCIDENT INVOLVING GT 5336K(AXA) / SLA 1150X/ OTHERS ON 06/06/2018

We refer to the above matter.

We have our principal instruction to offer as follows: -

1. Cost of Repair (w/GST)	\$ 6,291.60
2. Loss of Rental (8days x \$120.00)	\$ 960.00
3. LTA/GIA Search Fee	\$ 2.00
Total	\$ 7,253.60

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 15577

Vehicle Insured : GT5336K
Accident Date : 06-Jun-2018

Date : 17-Jul-2018

Our Ref : 218095 (AXA) / CHAN

PAGE : 1

LEE HON HUAN
BLK 734 JURONG WEST STREET 73
#08-06
Singapore 640734

FINAL REPAIR COST FOR MAZDA CX5 2.0 SLA1150X

=====

1 pc	Tail gate		1,479.70
1 pc	Tail gate glass inner seal		42.10
1 pc	Tail gate logo		51.70
1 pc	Tail gate outer garnish		437.10
1 pc	Tail gate "CX-5" emblem		45.30
1 pc	Tail gate "SKYACTIV" plate		71.60
2 pcs	Tail gate lamp	@ S\$466.60	933.20
1 pc	O/s taillamp		1,201.00
1 pc	Rear bumper fascia		1,218.00
1 pc	Rear bumper reinforcement		584.80

			6,064.50
Less 20% :			1,212.90

4,851.60
45.00 sn
40.00 sn

To remove & refix rear windscreen glass and conduct water leak test.	120.00
To remove roof lining, front and rear seats, trim board and carpet	40.00
To apply undersealing	30.00
To putty and spray replaced parts	600.00

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GT5336K

Page : 2

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

500.00

6,226.60

Add 7% GST :

435.86

Total :

S\$ 6,662.46

Singapore Dollars Six Thousand Six Hundred and
Sixty Two and Cents Forty Six Only

LEE HON GUAN

c/o Blk 7 Sin Ming Industrial Estate
#01-76

Singapore 575642

Date: 20-7-2018

AXA INSURANCE SINGAPORE PTE LTD
MOTOR CLAIMS DEPT.

8 SHENTON WAY #27-01

AXA Tower

Singapore 068811

L/K/C

Dear Sir / Madam

ACCIDENT INVOLVING MOTOR VEHICLES SLA1150 X AND GT5336 K
ALONG SUP RD TO YUAN CHANG ANN ERIT FROM AYER ON 06-06-2018

I / We, the owner of Vehicle No. SLA1150 X which was involved in the above accident.

My / Our vehicle sustained damages as a result of the above said accident and I / we are now claiming against you for the followings:-

- | | |
|-----------------------------------|-------------------|
| 1. Costs of repair | - \$ 6662.46 |
| 2. Loss of Use/Rental fees | - \$ 2400.00 |
| 3. Police / GIA report / LTA fees | - \$ 2.00 |
| 4. Surveyor report fees | - |
| 5. Others | - |
| Total: | <u>\$ 9064.46</u> |

Please advise whether you are now prepare to settle my claims as outlined above.

I / We hereby authorise my / our repairers, M/s Alan's United Auto Pte. Ltd. and/or their representatives to negotiate/compromise settlement of my / our above claim on my / our behalf. If there is a settlement I / we further authorise you to pay whatever settlement sum to my / our repairers being the outstanding repair bill and incidentals due to them.

Your kind attention and prompt settlement is much appreciated.

Yours faithfully,






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18010779/Kpa3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KIAN CHUAN		Date : 13-11-2019		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GT 5336K	Veh. Inspected	SLA 1150X	
Policy No.	P1565403	Coverage (\$)	0.00	
Claim No.	S8M00K0G	Excess (\$)	0.00	
Assign From	KIAN CHUAN	Assign Date	13/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA CX-5 (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6KE1072G0349487	Colour	METALLIC GREY	
Odometer	74738	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	MICHELIN	8 mm	
L/H Front Tyre	225/65 R17	MICHELIN	8 mm	
R/H Rear Tyre	225/65 R17	MICHELIN	8 mm	
L/H Rear Tyre	225/65 R17	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/06/2018	Inspection Date	11/06/2018	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 1150X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAIL GATE (CONSISTENT)	BENT	1,479.70	1,479.70
1	TAIL GATE GLASS INNER SEAL (CONSISTENT)	NECESSARY	42.10	42.10
1	TAIL GATE LOGO (CONSISTENT)	NECESSARY	51.70	51.70
1	TAIL GATE OUTER GARNISH (CONSISTENT)	WARPED	437.10	437.10
1	TAIL GATE "CX-5" EMBLEM (CONSISTENT)	NECESSARY	45.30	45.30
1	TAIL GATE "SKYACTIV" PLATE (CONSISTENT)	NECESSARY	71.60	71.60
2	TAIL GATE LICENCE PLATE LAMP @ \$42.10 (CONSISTENT)	SERVICEABLE	84.20	-
1	TAIL GATE WIPER MOTOR (CONSISTENT)	SERVICEABLE	412.50	-
2	TAIL GATE LAMP @ \$466.60 (CONSISTENT)	CRACKED	933.20	933.20
2	TAIL LAMP @ \$1201.00 (CONSISTENT)	O/S CRACKED / N/S SERVICEABLE	2,402.00	1,201.00
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	473.90	-
1	REAR BUMPER FASCIA (CONSISTENT)	BUCKLED	1,218.00	1,218.00
2	REAR BUMPER TOW COVER @ \$8.00 (CONSISTENT)	SERVICEABLE	16.00	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	584.80	584.80
	LESS 20% DISCOUNT		-1,650.42	-1,212.90
			6,601.68	4,851.60
SPECIAL NETT ITEMS				
1	REAR NO. PLATE WITH BOX (SN) (CONSISTENT)	DENTED	50.00	45.00
4	REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	SERVICEABLE	400.00	-
1	REAR W/S GLASS SEALANT (SN) (CONSISTENT)	NECESSARY	60.00	40.00
			510.00	85.00
LABOUR				
	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		150.00	120.00
	TO REMOVE ROOF LINING, FRONT AND REAR SEATS, TRIM BOARD AND CARPET.		120.00	40.00
	TO APPLY UNDERSEALING.		60.00	30.00
	TO PUTTY AND SPRAY REPLACED PARTS.		900.00	600.00

Report Ref No. CC4/ASM18010779/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		850.00	500.00
			2,080.00	1,290.00
GRAND TOTAL			9,191.68	6,226.60
RECOMMENDED COST OF REPAIRS				6,226.60

Report Ref No. CC4/ASM18010779/Kpa3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.