

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05791

Vehicle Insured : GT5336K

Accident Date : 06-Jun-2018

Date : 08-Jun-2018

Our Ref : 218095 (AXA) / CHAN

PAGE : 1

LEE HON HUAN

BLK 734 JURONG WEST STREET 73

#08-06

Singapore 640734

*Not Authorized  
1.B.1  
Pursuing B & paint*

## ESTIMATED COST OF REPAIR FOR MAZDA CX5 2.0 SLA1150X

1 pc	Tail gate			1,479.70	✓
1 pc	Tail gate glass inner seal			42.10	✓
1 pc	Tail gate logo			51.70	✓
1 pc	Tail gate outer garnish			437.10	✓
1 pc	Tail gate "CX-5" emblem			45.30	✓
1 pc	Tail gate "SKYACTIV" plate			71.60	✓
2 pcs	Tail gate license plate lamp	@ S\$ 42.10		84.20	?
1 pc	Tail gate wiper motor			412.50	?
2 pcs	Tail gate lamp	@ S\$466.60		933.20	✓
2 pcs	Taillamp	@ \$1201.00		2,402.00	✓
1 pc	Rear end panel			473.90	?
1 pc	Rear bumper fascia			1,218.00	✓
2 pcs	Rear bumper tow cover	@ S\$ 8.00		16.00	X
1 pc	Rear bumper reinforcement			584.80	?
				8,252.10	
Less 20% :				1,650.42	

- 1 pc Rear no.plate with box
- 1 pc Rear bumper reverse sensor(4pc
- 1 pc Rear w/s glass sealant

*Ad 45sn 6,601.68*  
*50.00 sn*  
*400.00 sn ?*  
*40sn 60.00 sn*

To remove & refix rear windscreen glass and conduct water leak test.

150.00 *1201*

To remove roof lining, front and rear seats, trim board and carpet

120.00 ?

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GT5336K

Page : 2

To apply undersealing	60.00 <i>301</i>
To putty and spray replaced parts	900.00 <i>6001</i>
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts	850.00 <i>7</i>
Total :	<u>S\$ 9,191.68</u> =====

Singapore Dollars Nine Thousand One Hundred and  
Ninety One and Cents Sixty Eight Only