

ASS. BY: _____

REF: _____

CS/CTI18010782/Ntd3br

Special Instruction: _____

Drive

Surveyor

Meimoh

ASSIGNMENT (Office)

From (Person):

Sharon Han

of

CTI

Date/Time:

13/6/18 @ 9:30am

Estimated Cost: _____

Bill to: _____

OD / TP / WS / TR RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 6070B

Insured:

SJU 8452Y

at Workshop m/s

Auto Sum Chuan

Tel:

9744 1203 / 6532 2009

of

2 Kaki Blk + Ave 2 # 02-03

Year/ms Teng

Policy No:

PMPCSN 301411700

Claim No:

SNM18D02897C02

Sum Insured: _____

Excess: _____

Make of Veh:

(Client's Record)

D.O.A.

07/06/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement: _____

Date/Time:

10:24am @ 13/6/18

Person Contacted:

Mr Cheah

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLQ 6070B -x

SJU 8452Y -x

NAZ

REF: CTI

ASSIGNMENT

From: _____ Date: 13/6/18

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLQ 6070B

at Workshop n/s Auto Sum Chuan

of 2 Kaki Bkt Ave 2 #02-03

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Mr Cheeh @ 9744 1203

Veh No: SLQ 6070B Yr Regn: 17 JUL 2017

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: HONDA VEZEL 1.5 X SENSING CC 1496

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 29,189 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU11217801

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16

(F) R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or (R)

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. 7/6/18	D.O.I. 13/6/18

Survey held at AUTO SUM CHUAN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or N/S FRONT

The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)

N/S	O/S
-----	-----

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{lup}

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time | Action / Instruction

2013/19 FINALIZED PART BY PART REPAIR & 1203.04 / 4 DAYS (P/P)

(Red: 7/14.26 : 37%)

RECEIVED 25 MAR 2019

Date/Time File Pass to? : Preli. Report

1) 2/3 Typist : Final Report

Date/Time File Return to?

2)

Report Format: TP

Lump Sum / I.B. : (\$ 1203.04)

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Survey Fee:

Transportation	220
_____ S + RS _____ SI	
Photos	
Others	
TOTAL	220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jun 2018		13 Jun 2018 09:30 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)
CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	TING KING MOK		
Vehicle Reg. No.:	SLQ6070B	Date of Loss:	07/06/2018 00:00 - :59
Claim Type:	TP / SNM18D02897C02	Policy/Cover Note No.:	DMPCSN3014111700
Vehicle Reg. No. (Insured):	SJU8452Y	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Auto Sum Chuan (HQ) 2, KAKI BUKIT AVENUE 2, KAKI BUKIT AUTOHUB,, #02-03, 417921 Kaki Bukit - Tel: 67479189		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/06/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN XING GUO QIANG AS SJE.		

ASSOCIATED MAIL RECEIVED
[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

ACCIDENT STATEMENT

Date Of Report	08/06/2018 10:31
Date Of Accident	07/06/2018 16:35
Exact Location Of Accident	IN BET BLK 221 BUKIT BATOK EAST AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ6070B
Insured/Policyholder	
Name Of Registered Owner	TING KING MOK
NRIC No	S2568299H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91708898
Alternative Phone No	OTHERS-91708898
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL 1.5X SENSING
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5092453387
Cover Note Number	
Driver	
Name of Driver	TING YEE CHEING
NRIC No	S8870253J
Date Of Birth	05/09/1988
Occupation	INDOOR
Date Of Driving Pass	13/01/2009
Driving Experience	9 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91272089
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address BLK 217 #06-363 BUKIT BATOK STREET 21
 Postcode 650217
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLIDED INTO PARKED VEHICLE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

THE INCIDENT TOOK PLACE ON THE ABOVEMENTIONED LOCATION. AFTER PARKING AND SECURING MY VEHICLE I LEFT HOME. WHEN I COME BACK 16:50 AND TO REALISED THERE IS DAMAGED TO MY VEHICLE. I THEN RETREIVE FROM MY IN CAR CAMERA AND SAW VEHICLE B-SJU8452Y HAS COLLIDED ONTO MY VEHICLE LEFT HAND SIDE WHEN HE WAS DOING THE REVERSING INTO THE LOT BEHIND. VEHICLE FRONT PORTION COLLIDED ONTO MY VEHICLE LEFT HAND SIDE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WITH DRIVER
 Was there any audio recorded? NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJU8452Y
 Vehicle Make/Model/Colour NISSAN
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

Sketch Plan #2 Pg. 1

Blk 201 Bukit Batok East Street 3

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Blk 216 Bukit Batok Street 21

Refer e-File

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

08 JUN 2018

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Reporting Centre, Singapore 415933

Phone: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

AUTO SUM CHUAN

BLK 2 KAKI BUKIT AVE 2 [KAKI BUKIT AUTO HUB]
 #02-04 SINGAPORE 417921
 AUTO SUM CHUAN, UOB AC ; 412 300 9376 , OCBC 826700134001
 Tel No. : 67479189 Fax No. : 67412008
 E-Mail : autosumchuan@gmail.com
 Buss. Reg. No. : ASC.33428000A

Estimate : ES000035

Date : 12/06/2018
 Vehicle Num. : SLQ 6070 B
 Make/Model : HONDA VEZEL
 Chassis/Eng# :
 Accident Date : 12/06/2018
 Claim No. :
 Reference :
 Policy No. :

aa

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.		LIST ITEMS :		
2.		BUMPER RETAINER RR LH		28.50 X SVC
3.		FRONT BUMPER ASSY		450.00 DEF
3.	10	CLIP	3.50	35.00 X SVC
4.		FOG LAMP MOULDING		45.00 ALL
5.		FENDAL MOULDING LHS		153.80 scratch
6.		BUMPER MOULDING LHS		195.50 scratch

List Total S\$:

917.30

LABOUR :

TO SPRAY ANTI RUST COATING AFFECTED AREA
 TO SPRAY PAINTING ON AFFECTED AREA
 TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED & REPLACE
 DAMAGED PARTS

NUMBER OF DAY FOR REPAIR ?
 CHECK WIRING

14 days

300 ~~60.00 X NA~~
~~520.00~~
 380.00
 200
~~40.00~~ 20

E. & O.E.

Total S\$:

1,917.30

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

for AUTO SUM CHUAN

NAZ
 LKK
 17/6/18
 1345
 P/P
 4 Days

Signature
 14/9/18

PARTS \$853.80

LESS 20% \$683.04

LABOUR \$520

TOTAL \$1203.04 / 4-DAY

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	11 Jun 2018		13 Jun 2018 09:30 Edit Adj Rpt	S\$1,203.04 Edit Estimates	S\$1,203.04 View Rpt	Pending for Survey Report

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: TING KING MOK									
Vehicle Reg. No.: SLQ6070B		Date of Loss: 07/06/2018 00:00 - :59 [10 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D02897C02		Policy/Cover Note No.: DMPCSN3014111700							
Vehicle Reg. No. (Insured): SJU8452Y		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Auto Sum Chuan (HQ) 2, KAKI BUKIT AVENUE 2, KAKI BUKIT AUTOHUB,, #02-03, 417921 Kaki Bukit - Tel: 67479189									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 25/06/2018]									
Adj Asg. Remarks: NO EST, ASSIGN XING GUO QIANG AS SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPING (07/11/2018): Alert - Adj Mandate Revoked - SLQ6070B - Claim Handler: Sharon Han									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLQ6070B (SNM18D02897C02)**
[SJU8452Y]
TP
TING KING MOK
Jun 7 2018 12:00AM
[-]
Auto Sum Chuan

Upload Documents		Upload Photos	Compose New Letter	View View in Browser
Photos/Images				3 per page <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/09/18 18:29	General View	Load JPG	<input checked="" type="checkbox"/>
2	13/09/18 18:29	General View	Load JPG	<input checked="" type="checkbox"/>
3	13/09/18 18:29	General View	Load JPG	<input checked="" type="checkbox"/>
4	13/09/18 18:29	General View	Load JPG	<input checked="" type="checkbox"/>
5	13/09/18 18:29	General View	Load JPG	<input checked="" type="checkbox"/>
6	13/09/18 18:29	General View	Load JPG	<input checked="" type="checkbox"/>
7	13/09/18 18:29	General View	Load JPG	<input checked="" type="checkbox"/>
8	13/09/18 18:29	General View	Load JPG	<input checked="" type="checkbox"/>
9	13/09/18 18:29	General View	Load JPG	<input checked="" type="checkbox"/>
10	13/09/18 18:29	General View	Load JPG	<input checked="" type="checkbox"/>
11	13/09/18 18:29	General View	Load JPG	<input checked="" type="checkbox"/>
12	13/09/18 18:29	General View	Load JPG	<input checked="" type="checkbox"/>
13	13/09/18 18:29	General View	Load JPG	<input checked="" type="checkbox"/>
14	13/09/18 18:29	General View	Load JPG	<input checked="" type="checkbox"/>
15	13/09/18 18:29	General View	Load JPG	<input checked="" type="checkbox"/>
16	13/09/18 18:29	General View	Load JPG	<input checked="" type="checkbox"/>
17	13/09/18 18:29	General View	Load JPG	<input checked="" type="checkbox"/>
18	13/09/18 18:29	General View	Load JPG	<input checked="" type="checkbox"/>
19	21/03/19 14:16	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
20	21/03/19 14:16	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
21	21/03/19 14:16	Replacement Part Photo	Load JPG	<input checked="" type="checkbox"/>
22	21/03/19 14:16	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
23	21/03/19 14:16	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
24	21/03/19 14:16	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page <input type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/06/18 09:30	PRS	Load PDF	
2	13/06/18 09:30	TP GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18010782/NTD3E2

Date: 25/03/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN3014111700	
Claimant Vehicle No: SLQ6070B	Insured Vehicle No: SJU8452Y	
Date of Loss: 07/06/2018	Nature of Claim: TP	Claim No: SNM18D02897C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ6070B	
Make & Model:	HONDA VEZEL, 1.5 X SENSING (A)	Engine No: L15B4417800
Reg. Date:	17/07/2017 (Man. Year: 2017)	Chassis No: RU11217801
Colour:	White	Odometer: 29189 km
Engine Capacity:	1496 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	917.30	683.04	234.26	25.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	520.00	480.00	48.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,917.30	1,203.04	714.26	37.25

INSPECTION

Date of Assignment:	13/06/2018	
Date Inspected:	13/06/2018 Inspected At:	Auto Sum Chuan (HQ) 2, KAKI BUKIT AVENUE 2, KAKI BUKIT AUTOHUB,, #02-03 Singapore 417921
Estimated Period of Repair:	4.0 days	

Adjuster: Muhammad Nazril Bin Abdullah

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Mar 2019)
Parts: M1-SUV	HONDA VEZEL 1.5 X SENSING (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLQ6070B)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER RETAINER RR LH	Serviceable	28.50 F	*- FL
2	1		*FRONT BUMPER ASSY	Deformed	459.50 F	*459.50 FL
3	10		*CLIP	Serviceable	35.00 F	*- FL
4	1		*FOG LAMP MOULDING	Necessary	45.00 F	*45.00 FL
5	1		*FENDAL MOULDING LHS	Scratched	153.80 F	*153.80 FL
6	1		*BUMPER MOULDING LHS	Scratched	195.50 F	*195.50 FL
Sub Total (S\$)					917.30	853.80
- List Item Discount on L Items 0.00/20.00% (S\$)					0.00	170.76
Total Parts (S\$)					917.30	683.04

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SPRAY ANTI RUST COATING AFFECTED AREA	New	60.00	0.00
2	TO SPRAY PAINTING ON AFFECTED AREA	New	520.00	300.00
3	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED & REPLACE DAMAGED PARTS	New	380.00	200.00
4	CHECK WIRING	New	40.00	20.00
Gross Labour Cost (\$\$)			1,000.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >