

ASS. REC. BY

REF: cs/CTI/8010784/ A+d3

n2

Special Instruction:

Survivor
Mainmen

Adrian

ASSIGNMENT (Office)

From (Person):

Chong Bangsun

of CTI

Date/Time: 12/6/18 @ 2:12pm

Estimated Cost:

Bill to:

OD / TP AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDR 11B

Insured:

SJK 3834P

at Workshop m/s

sk Automobile

Tel:

6789 5155

of

23 Kaki Bkt Ave 4 # 03-01

Policy No:

DMPCSN1770191700

Claim No:

SNM18D02924C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09/06/2017

CA / REV / REP. / REV 24 HRS

up

Date/Time:

9:52am 13/6/18

Person Contacted:

Huey Lee

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time

Action/Instruction

(✓)

Estimate

SDR 11B - X

SJK 3834P - X

30/11/2018

Spote to Huey Lee can finalize.

lump sum 8000- (Red: 27564.19; 74%)

REF:

ASS. REC. BY: Adrian King

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SDR11BYr Regn: 2015 JuneType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Lexus ES300c.c. 2494Colour: Gold

A/C: Insured / Std / NI / NA

Sp. Reading: 53176

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTHBW166202057625Gen. Cond: Good / Fair / Poor / BurntSteering: Orderly / Jammed / Leaked / Burnt orBrake: Orderly / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/55R17R: 215/55R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A.

D.O.I. 18/06/18Survey held at SKDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction

TP Ching

RECEIVED 01 MAR 2019

Date/Time, File Pass to?

☐ : Preli. Report☒ : Final Report1) 1/3 Typist
Date/Time, File Return to?

2) _____

Days Of Repair: 6Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.E. (\$)

TP
3000+220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Jun 2018		12 Jun 2018 14:12 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN SEOW KIM		
Main Claimant:	HO KAI KENG ROGER		
Vehicle Reg. No.:	SDR11B	Date of Loss:	09/06/2018 17:00 - :59
Claim Type:	TP / SNM18D02924C02	Policy/Cover Note No.:	DMPCSN1770191700
Vehicle Reg. No. (Insured):	SJK3834P	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre, 415933 Kaki Bukit - Tel: 67895155		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/06/2018]		
Adj Asg. Remarks:	Please survey third party vehicle & let us have your recommendation on estimated amount required to repair the vehicle if there is NO estimate provided during pre-repair inspection. APPOINTED SURVEYOR : CHUA WEIJIE		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

MALP16075369 / Alpine Motors Pte Ltd - HQ
 ENTRY DATE & TIME: 11/06/2018 12:18
 SUBMITTED BY: Mohd Suhaimi Bin Mohd Suadi Ong

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 11/06/2018 12:16
 Date Of Accident 09/06/2018 17:00
 Exact Location Of Accident PIE TOWARDS TUAS(KALLANG EXIT)
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SDR11B

Insured/Policyholder
 Name Of Registered Owner HO KAI KENG ROGER
 NRIC No S1759253Z
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-96755567
 Alternative Phone No OTHERS-96755567

Vehicle Particulars
 Manufacturer TOYOTA
 Model LEXUS ES300H LUXURY CVT
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR

Insurance Company
 Name of Insurance Company AXA INSURANCE PTE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number VPA/P1936318
 Cover Note Number

Driver
 Name of Driver HO KAI KENG ROGER
 NRIC No S1759253Z
 Date Of Birth 14/09/1966
 Occupation INDOOR
 Date Of Driving Pass 24/12/2002
 Driving Experience 15 YEARS AND 5 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-96755567
 Fax Number
 Contact Number OTHERS-96755567
 Email Address NOEMAIL

Address BLK 351 CLEMENTI AVENUE 2 #09-65
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : RAEKI HO
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJK3834P
 Vehicle Make/Model/Colour HONDA ODYSSEY 2.4 A
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insured companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: J. L. M.
NIC/FIN No.: 88050321A

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 9/6/18 at 14:20 hrs, I was travelling along the road
towards and at the road left hand side of the road.

The vehicle in front slow down and I follow and
suddenly I felt an impact on my rear vehicle.
The 20241P was involved and I was not injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name: S. K. S.
NIC/ID No.: 60503770

**Lexus RX270 Sport****\$134,800**

\$15,690 /yr

12-Feb-2015

2,672 cc

81,000 km

SUV

Available

Full Servicing History By Borneo Motors. Last Serviced On Feb 2018 (75000KM). 1 Owner. Grey Paintwork With Beige Interior. Facelifted Model. Comes With Navigation And Sunroof. Contact Us For More Data...

Auto Zoom Enterprise Pte Ltd

Posted: 05-Jun-2018 Tags: 2015 Lexus RX270, Lexus RX270, Lexus, RX270, Used Lexus

**Lexus GS350 F Sport****\$154,888**

\$16,250 /yr

05-Feb-2015

3,456 cc

110,000 km

Luxury

Available

1 Owner! Cheapest In The Market. Regularly Serviced By Lexus Agent! 5 Years Warranty! Buy With A Peace Of Mind! Beautiful Sporty F Sport Kit (F Sports Emblem Interior And Exterior), Luxury Yet Sporty ...

Hui Hua Credit Pte Ltd

Posted: 04-Jun-2018 Tags: 2015 Lexus GS350, Lexus GS350, Lexus, GS350, Used Lexus

**Lexus ES250****\$135,000**

\$17,380 /yr

13-Jan-2015

2,494 cc

52,000 km

Luxury

Available

1 Careful Owner. Accident Free. Excellent Condition. Beautiful Brown Interior Leather Matched With Black Exterior. High Trade In And Financing Available.

Posted: 02-Jun-2018 Tags: 2015 Lexus ES250, Lexus ES250, Lexus, ES250, Used Lexus

**Let's help you 2888 K?**

Many auspicious and rare car plates for sale at a good price! Get lucky today with our Bidded car plate numbers for sale!

Find out more!

**Lexus ES Hybrid ES300h
Luxury****\$136,800**

\$14,800 /yr

18-Dec-2015

2,494 cc

Luxury

Available

Fuel Type: Petrol-Electric

\$0 Down Payment Available! We Are sgCarMart Premium Dealer 2015 To 2017! Buy With Confidence! No Hidden Cost! Full Agent Service History, 5 Years Agent Warranty And 10 Years Hybrid Battery Warranty! 1...

88 Motor Trading

Posted: 01-Jun-2018 Tags: 2015 Lexus ES, Lexus ES, Lexus, ES, Used Lexus

**Lexus NX Hybrid NX300h
Luxury****\$203,800**

\$23,600 /yr

28-Oct-2015

2,494 cc

69,000 km

SUV

Available

Fuel Type: Petrol-Electric

15k Drive Away! Beautiful Silver Toyota Lexus NX300H With Walnut Leather Upholstery. Full Serviced And Maintained By Borneo Motor With 5 Years Unlimited Mileage Warranty Program And 10 Years Warranty ...

Dynamic Motoring

Posted: 31-May-2018 Tags: 2015 Lexus NX, Lexus NX, Lexus, NX, Used Lexus

**Lexus NX Hybrid NX300h
Luxury****\$142,000**

\$16,950 /yr

23-Mar-2015

2,494 cc

86,000 km

SUV

Available

Fuel Type: Petrol-Electric

Price Negotiable.

Posted: 25-May-2018 Tags: 2015 Lexus NX, Lexus NX, Lexus, NX, Used Lexus

**Lexus ES250 Luxury****\$131,800**

\$15,420 /yr

01-Sep-2015

2,494 cc

44,000 km

Luxury

Available

5 Years Borneo Warranty And Servicing Package. 1 Owner. Sonic Titanium Paintwork With Black Interior. Comes With Panoramic Roof/Navigation/Ventilated Seats. Well Maintained And Regularly Groomed. Call...

Posted: 24-May-2018 Tags: 2015 Lexus ES250, Lexus ES250, Lexus, ES250, Used Lexus

**Lexus NX Hybrid NX300h
Luxury****\$152,800**

\$17,060 /yr

31-Aug-2015

2,494 cc

20,000 km

SUV

Available

Fuel Type: Petrol-Electric

Immaculate Condition With Full Service Records At Borneo And Recently Serviced Only.

Posted: 22-May-2018 Tags: 2015 Lexus NX, Lexus NX, Lexus, NX, Used Lexus

**Lexus NX Hybrid NX300h
Luxury****\$145,000**

\$16,170 /yr

31-Jul-2015

2,494 cc

46,000 km

SUV

Available

Fuel Type: Petrol-Electric

Lowest Depreciation In The Market. Come With Lexus 5 Years Warranty And 10 Years Hybrid Warranty By Agent. Super Low Mileage. Parked Under Shelter And Very Under Utilised. Trade In Are Welcome. Consig...

Posted: 09-May-2018 Tags: 2015 Lexus NX, Lexus NX, Lexus, NX, Used Lexus

**Lexus NX Turbo NX200t F
Sport****\$158,888**

\$18,270 /yr

30-Jul-2015

1,998 cc

20,000 km

SUV

Available

Extremely Low Mileage Due To Frequent Travels. Forever Sheltered Parking. Stock Condition With New Car Smell. Serviced Per Lexus Standard. Special Nova White Color.

Posted: 09-May-2018 Tags: 2015 Lexus NX, Lexus NX, Lexus, NX, Used Lexus

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

9253Z

Vehicle Details

Vehicle No.:

SDR11B

Vehicle to be Exported:

Yes

Intended De-registration Date:

11 Jun 2018

Vehicle Make:

TOYOTA

Vehicle Model:

LEXUS ES300H LUXURY CVT

Primary Colour:

Silver

Manufacturing Year:

2015

Engine No.:

2AR1294954

Chassis No.:

JTHBW1GG202097625

Maximum Power Output:

151.0 kW (202 bhp)

Open Market Value:

\$45,066.00

Original Registration Date:

29 Jun 2015

First Registration Date:

29 Jun 2015

Transfer Count:

0

Actual ARF Paid:

\$45,093.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

28 Jun 2025

PARF Rebate Amount:

\$33,819.00

Intended COE Rebate Details

COE Expiry Date:

28 Jun 2025

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$71,509.00

COE Rebate Amount:

\$50,393.00

Total Rebate Amount:

\$84,212.00

The information contained herein is correct as at 11 Jun 2018

OK

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4 #03-01
Vicom Inspection Centre
Singapore 415933
Tel: 6789 5155 Fax : 6783 5155

TO	: CHINA TAIPING	DATE	: 11-Jun-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	: <i>Dense.</i>	VEHICLE NO	: SDR11B
ADDRESS	:	MODEL	: LEXUS ES300H
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE	:	<i>JTH BWIGG 202097625</i>	
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR PARKING SENSOR UNIT <i>2 pieces dry</i>	4	\$ 412.00	\$ 1,648.00
2	REAR PARKING SENSOR RETAINER <i>3pc</i>	4	\$ 68.80	\$ 275.20
3	REAR PARKING SENSOR WIRE HARNESS	1	\$ 435.40	\$ 435.40
4	REAR BUMPER <i>Distorted</i>	1	\$ 2,028.60	\$ 2,028.60
5	REAR BUMPER LOWER PROTECTOR <i>2pc</i>	1	\$ 548.00	\$ 548.00
6	REAR BUMPER COVER CAP <i>1pc</i>	2	\$ 22.30	\$ 44.60
7	REAR BUMPER REFLECTOR <i>2pc</i>	2	\$ 207.40	\$ 414.80
8	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 553.60	\$ 553.60
9	REAR BUMPER REINFORCEMENT FOAM <i>2pc</i>	1	\$ 308.20	\$ 308.20
10	REAR BUMPER REINFORCEMENT BRACKET <i>2pc</i>	2	\$ 214.00	\$ 428.00
11	REAR BUMPER SIDE RETAINER <i>2pc</i>	2	\$ 198.20	\$ 396.40
12	REAR BUMPER LOWER COVER <i>2pc</i>	1	\$ 321.60	\$ 321.60

400
+
+
+
426
281
+
✓
✓
✓
✓
250.
✓

13	SMART ENTRY ANTENNA <i>could</i>	1	\$ 755.74	\$ 755.74 195
14	SMART ENTRY ANTENNA BRACKET <i>new</i>	1	\$ 97.60	\$ 97.60 +
15	BOOT LID <i>Buckled</i>	1	\$ 3,281.20	\$ 3,281.20 1859,
16	BOOT LID LOGO <i>new</i>	1	\$ 156.00	\$ 156.00 ✓
17	BOOT LID OPENER SWITCH <i>new</i>	1	\$ 319.60	\$ 319.60 +
18	BOOT LID CHROME GARNISH <i>new</i>	1	\$ 1,056.30	\$ 1,056.30 +
19	BOOT LID WEATHERSTRIP <i>at</i>	1	\$ 470.50	\$ 470.50 ✓
20	BOOT LID LOCK ASSY <i>new</i>	1	\$ 754.00	\$ 754.00 ✓
21	BOOT LID LOCK COVER <i>at</i>	1	\$ 116.00	\$ 116.00 ✓
22	BOOT LID STRIKER <i>new</i>	1	\$ 185.90	\$ 185.90 +
23	BOOT LID INNER TRIM	1	\$ 746.30	\$ 746.30 ✓
24	REAR END PANEL <i>Deled</i>	1	\$ 1,689.00	\$ 1,689.00 965
25	REAR FLOOR PANEL <i>Repis</i>	1	\$ 2,145.00	\$ 2,145.00 +
26	REAR END PANEL TOP GARNISH <i>Deled</i>	1	\$ 728.60	\$ 728.60 320
27	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 924.40	\$ 924.40 +
28	REAR FLOOR PANEL SIDE TOOL BOX <i>new</i>	2	\$ 423.80	\$ 847.60 +
29	REAR FLOOR PANEL UNDER COVER <i>new</i>	1	\$ 410.00	\$ 410.00 ✓
30	REAR FENDER SIDE INNER TRIM <i>new</i>	2	\$ 1,356.10	\$ 2,712.20 +
31	BOOT LID LAMP <i>2</i>	2	\$ 1,543.80	\$ 3,087.60 +
32	TAILLAMP <i>new</i>	2	\$ 1,045.00	\$ 2,090.00 +
33	TAILLAMP LOWER BRACKET <i>new</i>	2	\$ 144.00	\$ 288.00 +
34	EXHAUST PIPE SILENCER	1	\$ 2,129.60	\$ 2,129.60 x.

8490.70
7641.63

TOTAL PRICE \$ 32,393.54
LESS 10% \$ 3,239.35
SUB TOTAL PRICE \$ 29,154.19

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE WITH CASING <i>new</i>	1	\$ 300.00	\$ 300.00 +
2	REAR BUMPER CLIPS SET <i>new</i>	1	\$ 70.00	\$ 70.00 30
3	REAR FENDER INNER SHIELD CLIPS SET <i>2</i>	1	\$ 45.00	\$ 45.00 +
4	BOOT LID JOINT SEALANT <i>new</i>	1	\$ 90.00	\$ 90.00 +
5	BOOT LID INNER TRIM CLIPS SET <i>new</i>	1	\$ 70.00	\$ 70.00 +
6	REAR END PANEL TOP GARNISH CLIPS SET	1	\$ 45.00	\$ 45.00 10
7	REAR END PANEL JOINT SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00 60
8	REAR FLOOR PANEL JOINT SEALANT <i>2</i>	1	\$ 80.00	\$ 80.00 +
9	REAR FLOOR PANEL JOINT INSULATOR <i>new</i>	1	\$ 300.00	\$ 300.00 +
10	REAR FENDER INNER TRIM CLIPS SET	2	\$ 65.00	\$ 130.00 +

SUB TOTAL PRICE

\$ 1,210.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	CUT OFF, REPLACE REAR END PANEL AND FLOOR PANEL. STRAIGHTEN, REALIGN REAR CHASSIS FRAME AND RENEW OTHER DAMAGE PARTS.	\$ 1,600.00	9w	
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	\$ 1,400.00	10w.	
3	DISMENTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS.	\$ 150.00	X	
4	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY TESTING.	\$ 200.00	100	
5	RENEW REAR FLOOR INSULATOR.	\$ 100.00	X	
6	REMOVE AND REPLACE SMART KEYLESS ANTENNA AND BUZZER. RESET SMART ENTRY SYSTEM.	\$ 200.00	60	
7	DISMENTLE AND INSTALL REAR SEATS, SPEAKER BOARD AND SEATS TRIMMING.	\$ 150.00	to X.	
8	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUCTION.	\$ 200.00	30	
10	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA.	\$ 100.00	X	
12	TRANSFER BOOT LID ATTACHMENT AND MECHANISM INTO NEW POWER BOOT LID ASSY. RE-ALIGN TO POSITION.	\$ 200.00	80	
13	DISMENTLE AND RE-INSTALL REAR INTERIOR COMPARTMENT TRIMMING.	\$ 300.00	60	
14	APPLY TUFF COATING TREATMENT.	\$ 200.00	60	

SUB TOTAL

\$4,800.00

2290

ESTIMATE REPORT

TOTAL PARTS COST : \$ 30,364.19
TOTAL LABOUR COST : \$ 5,200.00

TOTAL REPAIR COST : \$ 35,564.19

APPROVED DETAILS

35164.19

EXCESS

NO. OF WORKING DAYS

RE-SURVEY

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

Adrian Lj
L/S 18/06/18
OG hys

total 1003163.

L/S: 8k

8/c

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18010784/ATD3N2

Date: 04/03/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1770191700	
Claimant Vehicle No :	SDR11B	Insured Vehicle No :	SJK3834P	
Date of Loss:	09/06/2018	Nature of Claim:	TP	Claim No: SNM18D02924C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDR11B	Engine No:	2AR1294954
Make & Model:	TOYOTA LEXUS, 2.5 ES300H CVT (A)	Chassis No:	JTHBW1GG202097625
Reg. Date:	29/06/2015 (Man. Year: 2015)	Odometer:	53176 km
Colour:	Gold		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	30,364.19	7,741.63	22,622.56	74.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,800.00	2,290.00	2,510.00	52.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,164.19	10,031.63	25,132.56	71.47
Approved Total (Overridden) (S\$)		8,000.00		
(S\$)	35,164.19	8,000.00	27,164.19	77.25
+ GST 7.00/7.00% (S\$)	2,461.49	560.00	1,901.49	77.25
Nett Amount (S\$)	37,625.68	8,560.00	29,065.68	77.25

INSPECTION

Date of Assignment:	12/06/2018	
Date Inspected:	18/06/2018	Inspected At: SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre Singapore 415933
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Mar 2019)
Parts:	143	TOYOTA LEXUS 2.5 ES300H CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDR11B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR PARKING SENSOR UNIT (4Pcs)	Damaged (2 Pcs only)	1,648.00 FL	*400.00 FL
2	4	*REAR PARKING SENSOR RETAINER	Not Necessary	275.20 FL	*- FL
3	1	*REAR PARKING SENSOR WIRE HARNESS	Not Necessary	435.40 FL	*- FL
4	1	*REAR BUMPER	Distorted	2,028.60 FL	*1,426.00 FL
5	1	*REAR BUMPER LOWER PROTECTOR	Deformed	548.00 FL	*281.00 FL
6	2	*REAR BUMPER COVER CAP	Not Necessary	44.60 FL	*- FL
7	2	*REAR BUMPER REFLECTOR	Cracked	414.80 FL	*414.80 FL
8	1	*REAR BUMPER REINFORCEMENT	Bent	553.60 FL	*553.60 FL
9	1	*REAR BUMPER REINFORCEMENT FOAM	Deformed	308.20 FL	*308.20 FL
10	2	*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	428.00 FL	*- FL
11	2	*REAR BUMPER SIDE RETAINER	Necessary	396.40 FL	*250.00 FL
12	1	*REAR BUMPER LOWER COVER	Deformed	321.60 FL	*321.60 FL
13	1	*SMART ENTRY ANTENNA	Cracked	755.74 FL	*195.00 FL
14	1	*SMART ENTRY ANTENNA BRACKET	Not Necessary	97.60 FL	*- FL
15	1	*BOOT LID	Buckled	3,281.20 FL	*1,559.00 FL
16	1	*BOOT LID LOGO	Necessary	156.00 FL	*156.00 FL
17	1	*BOOT LID OPENER SWITCH	Not Necessary	319.60 FL	*- FL
18	1	*BOOT LID CHROME GARNISH	Not Necessary	1,056.30 FL	*- FL
19	1	*BOOT LID WEATHERSTRIP	Cut	470.50 FL	*470.50 FL
20	1	*BOOT LID LOCK ASSY	Damaged	754.00 FL	*754.00 FL
21	1	*BOOT LID LOCK COVER	Cut	116.00 FL	*116.00 FL
22	1	*BOOT LID STRIKER	Not Necessary	185.90 FL	*- FL
23	1	*BOOT LID INNER TRIM	Not Necessary	746.30 FL	*- FL
24	1	*REAR END PANEL	Dented	1,689.00 FL	*965.00 FL
25	1	*REAR FLOOR PANEL	Repair	2,145.00 FL	*- FL
26	1	*REAR END PANEL TOP GARNISH	Deformed	728.60 FL	*320.00 FL
27	1	*REAR FLOOR PANEL TOP BOARD	Not Necessary	924.40 FL	*- FL
28	2	*REAR FLOOR PANEL SIDE TOOL BOX	Not Necessary	847.60 FL	*- FL
29	1	*REAR FLOOR PANEL UNDER COVER	Not Necessary	410.00 FL	*- FL
30	2	*REAR FENDER SIDE INNER TRIM	Not Necessary	2,712.20 FL	*- FL
31	2	*BOOT LID LAMP	Not Necessary	3,087.60 FL	*- FL
32	2	*TAILLAMP	Not Necessary	2,090.00 FL	*- FL
33	2	*TAILLAMP LOWER BRACKET	Not Necessary	288.00 FL	*- FL
34	1	*EXHAUST PIPE SILENCER	Not Necessary	2,129.60 FL	*- FL
35	1	*REAR NUMBER PLATE WITH CASING	Not Necessary	300.00 FS	*- FS
36	1	*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
37	1	*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	45.00 FS	*- FS
38	1	*BOOT LID JOINT SEALANT	Not Necessary	90.00 FS	*- FS
39	1	*SET BOOT LID INNER TRIM CLIPS	Not Necessary	70.00 FS	*- FS
40	1	*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	45.00 FS	*10.00 FS
41	1	*REAR END PANEL JOINT SEALANT	Necessary	80.00 FS	*60.00 FS
42	1	*REAR FLOOR PANEL JOINT SEALANT	Not Necessary	80.00 FS	*- FS
43	1	*REAR FLOOR PANEL JOINT INSULATOR	Not Necessary	300.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
44	2	*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	130.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.					
Sub Total (S\$)				33,603.54	8,590.70
- List Item Discount on L Items 10.00/10.00% (S\$)				3,239.35	849.07
Total Parts (S\$)				30,364.19	7,741.63

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OFF,REPLACE REAR END PANEL AND FLOOR PANEL.STRAIGHTEN,REALIGN REAR CHASSIS FRAME AND RENEW OTHER DAMAGE PARTS	New	1,600.00	900.00
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA	New	1,400.00	1,000.00
3	DISMENTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS	New	150.00	0.00
4	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS PERFORM DISTANCE SENSORY TESTING	New	200.00	100.00
5	RENEW REAR FLOOR INSULATOR	New	100.00	0.00
6	REMOVE AND REPLACE SMART KEYLESS ANTENNA AND BUZZER.RESET SMART ENTRY SYSTEM	New	200.00	60.00
7	DISMENTLE AND INSTALL REAR SEATS,SPEAKER BOARD AND SEATS TRIMMING	New	150.00	0.00
8	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUNCTION	New	200.00	30.00
9	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA	New	100.00	0.00
10	TRANSFER BOOT LID ATTACHMENT AND MECHANISM INTO NEW POWER BOOT LID ASSY.RE-ALIGN TO POSITION	New	200.00	80.00
11	DISMENTLE AND RE-INSTALL REAR INTERIOR COMPARTMENT TRIMMING	New	300.00	60.00
12	APPLY TUFF COATING TREATMENT	New	200.00	60.00
Gross Labour Cost (S\$)			4,800.00	2,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >