



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/AXA18010794/Kea3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 13-06-2018		
		Code : AXA2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 5549R	Veh. Inspected	SJK 7838C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	13/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/06/2018	Inspection Date	13/06/2018	
Survey held at	JIN HUAT & CO BLOCK 176 SIN MING DRIVE #05-01 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

JIN HUAT & CO

176 Sin Ming Drive, #05-01

Sin Ming Autocare

Singapore 575721

Tel : 6453 2151; Fax : 6456 3060

email: jinhuat1951@gmail.com

Co. Reg. No: 020403/00C

Quotation

To: **Quan LiFang**
91 Seletar Green View
Singapore 805099

Contact: 9855 9592

Vehicle No: SJK 7838 C
Model: Toyota Wish
Insurer: Direct Asia Insurance (S) Pte Ltd

Date : 11 June 2018

Pages : 1 of 1

Not witharn
61 Day @ 1650h
Repair After Paint
3 days

We are pleased to quote you as follows:

Items	Description	Qty	Unit	Unit Price	Total Price
Accident Details:					
	Date of Accident : 09 June 2018				
	T/P claim against Vehicle No. SHC 5549 R				
	insured with AXA Insurance Singapore Pte Ltd				
Parts:					
1)	Front bumper	1	pc	\$ 385.00	\$ 385.00
2)	Front LH fender	1	pc	\$ 633.00	\$ 633.00
3)	Front LH H/lamp	1	pc	\$ 685.00	\$ 685.00
4)	LH side retainer	1	pc	\$ 35.00	\$ 35.00
5)	Grille	1	pc	\$ 365.00	\$ 365.00
Labour:					
6)	Repair frontal damage & replace new parts	1	lot	\$ 650.00	\$ 650.00
7)	Spray painting.	1	lot	\$ 650.00	\$ 650.00
TOTAL PRICE					\$ 3,403.00

1111X

4001400

JIN HUAT & CO

Alice Tan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 14/6/2018

Survey Details:

Date of loss	9-Jun-18
Date of appointment	13-Jun-18
Date of survey	13-Jun-18
Location of survey	Jin Huat & Co

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SJK 7838C
Make and Model	TOYOTA WISH 1.8 (A) - 1794cc
Date of registration	3-Nov-08
Excess	
Market Value	\$ 12,500.00
Part Rebate	\$ 9,692.00
Nett Loss	\$ 2,808.00

Repair details:

Initial Estimate	\$ 3,403.00
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 1,303.50
Check items (estimate)	\$ -
Labour	\$ 800.00
Total	\$ 2,103.50
Lump Sum(if applicable)	\$ 1,650.00

Number of days for repair	<u>3 days</u>
---------------------------	---------------

Print Received Message

This mail is associated with :

***SJK7838C (C0473874)**
[SHC5549R]
TP
QUAN LIFANG
Jun 9 2018 3:00AM
[TRANS-CAB SERVICES PTE LTD]
Jin Huat & Co

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 18/07/2018 09:43 AM.
To jas.tan@axa.com.sg; stacey.ng@axa.com.sg; LKK_HQ
CC AXA_SG; ashersng@lkkauto.com
Subject Re: New TP Assignment - C0473874/P1680520



AXA INSURANCE PTE LTD
400 Orchard Road, #24-01 AXA Tower
Singapore 238873
Customer Service 24x7
☎ 1876 8888 8888
✉ info@axa.com.sg
www.axa.com.sg
GST Reg No: 196930322P
In Reg No: 196930322P

Hi,

Please reject TP claim.

Thanks,
Jas

<-- Original Message -->

From: LKK_HQ
To: jas.tan@axa.com.sg; stacey.ng@axa.com.sg
CC: AXA_SG; ashersng@lkkauto.com
Sent On: 13/07/2018 10:09 AM
Subject: Re: New TP Assignment - C0473874/P1680520

Hi Sir,

We refer to the above matter.

TP reported that OI graze on the left front portion while making a right turn.

OI reported that TP make a right turn and hit his side door.

We are of the opinion that BOLA 9 applied, liability is not in third party's favour.

In view of the above, we are intending to reject TP claim.

Kindly let us have your advice / instruction if any.

Thank You,

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

<-- Original Message -->

From: AXA_SG
To: LKK_HQ; sur@lkkauto.com; assignments@lkkauto.com
CC: AXA_SG
Sent On: 12/06/2018 09:45 PM

Subject: New TP Assignment - C0473874/P1680520

Dear LKK Auto Consultants Pte Ltd,

Please survey the vehicle and proceed for direct settlement if damages consistent.

Workshop Name: Jin Huat & Co

Policy Number: P1680520

Vehicle Number: SJK7838C

Date of Accident: 09/06/2018

Estimated Claim Amount:

Excess: 5000.00

Claim Handler Name: Stacey Ng

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Thursday, 19 July 2018 10:36 AM
To: 'jinhuat1951@gmail.com'
Cc: Hsiao Tong (LKKAuto); Joy Irene (LKKAuto)
Subject: Your Ref: SJK 7838C, ACCIDENT INVOLVING SJK 7838C AND SHC 5549R ON 09/06/2018
Attachments: OI SKETCH PLAN.pdf

Your Ref: SJK 7838C
Our Ref: CC4/AXA18010794/Kea3

Without Prejudice

Hi Sir/Mdm,

We refer to the above matter.

ACCIDENT INVOLVING SJK 7838C AND SHC 5549R ON 09/06/2018

We attached here with a copy of our insured's accident statement for your easy reference.

Our principal has reiterated that the accident was caused due to the entire negligence of your client make a right turn into the main road and collided with our insured vehicle.

We are of the opinion that liability is not in your client's favor.

Under such a circumstances, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's claim.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jun 2018		12 Jun 2018 21:45 Edit Adj Rpt	S\$1,650.00 Edit Estimates	S\$1,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by Insurer]							
Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K, Email: CLAIMS@TRANSCAB.COM.SG								
Main Claimant:	QUAN LIFANG, ID: S6883390F								
Vehicle Reg. No.:	SJK7838C	Date of Loss:	09/06/2018 03:00 - :59 [115 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0473874	Policy/Cover Note No.:	P1680520 (Third Party Only)						
Vehicle Reg. No. (Insured):	SHC5549R	Policy No. (Claimant):	MS/00209889/03						
		Excess:	S\$5,000.00						
Repairer:	Jin Huat & Co (HQ) 176 SIN MING DRIVE #05-01, SIN MING AUTOCARE, 575721 Sin Ming - Tel:								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Jas Tan - 6880 4844]								
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 22/06/2018]								
Driver/Custodian (Insured):	WONG CHEE WEI (), NRIC: S7341390G, Tel: +6596380537								
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
- AXA_SG (18/07/2018): Re: New TP Assignment - C0473874/P1680520 - AXA_SG (12/06/2018): New TP Assignment - C0473874/P1680520									
ALL ASSOCIATED TASKS									
			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJK7838C (C0473874)**
[SHC5549R]
TP
QUAN LIFANG
Jun 9 2018 3:00AM
[TRANS-CAB SERVICES PTE LTD]
Jin Huat & Co

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Documentation														1 per page 1		☒	
No	Finalized On	AXA Insurance Pte Ltd (HQ)											Thumbnail		Print		
1	12/06/18 09:07	EMAIL1												Load PDF			
2	12/06/18 09:07	EMAIL2												Load PDF			
3	12/06/18 09:07	SHC5549R INSD GIA												Load PDF			
4	12/06/18 09:07	SJK7838C TP GIA												Load PDF			
5	12/06/18 09:07	Quotation												Load PDF			
6	12/06/18 13:22	EMAIL												Load PDF			
7	12/06/18 13:22	GIA REPORT OF SJK7838C (TP)												Load PDF			
8	12/06/18 13:22	GIA REPORT OF SHC5549R (INSD)												Load PDF			
9	12/06/18 13:24	EMAIL RECIVED FROM WORKSHOP												Load PDF			
10	12/06/18 13:24	ESTIMATE												Load PDF			
11	12/06/18 13:24	SHC5549R INSD GIA REPORT												Load PDF			
12	12/06/18 13:24	SJK7838C TP GIA REPORT												Load PDF			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print		
1	21/06/18 12:08	LKK SURVEY PHOTO												Load PDF			
2	21/06/18 12:18	Immediate Advice												Load PDF			
3	23/06/18 15:46	TP ESTIMATE - MARKED												Load PDF			
4	19/07/18 10:37	APPROVAL TO REJECT TP CLAIM												Load PDF			
5	19/07/18 10:37	EMAIL WSP TO REJECT TP CLAIM												Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18010794/KEA3Q2

Date: 24/07/2018

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant Vehicle No : SJK7838C

Insured Vehicle No :

SHC5549R

Date of Loss: 09/06/2018

Nature of Claim:

TP

Claim No: C0473874

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJK7838C

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 1ZZ3148390

Reg. Date: 03/11/2008 (Man. Year: 2008)

Chassis No: JTDER12W503000870

Colour: Metallic Silver

Odometer: 256000 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size:

195/65R15

Front Left Side: Michelin 8 mm

Rear Left Side:

Michelin 8 mm

Front Right Side: Michelin 8 mm

Rear Right Side:

Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,103.00	1,303.50	799.50	38.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	800.00	500.00	38.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,403.00	2,103.50	1,299.50	38.19
Approved Total (Overridden) (S\$)		1,650.00		
Nett Amount (S\$)	3,403.00	1,650.00	1,753.00	51.51
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 12/06/2018

Date Inspected: 13/06/2018 Inspected At:

Jin Huat & Co (HQ)

176 SIN MING DRIVE #05-01, SIN MING

AUTOCARE

Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Jul 2018)	
Parts: M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SJK7838C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (CONSISTENT)	Buckled	385.00 F	*385.00 FL
2	1		*FRONT LH FENDER (CONSISTENT)	Bent	633.00 F	*633.00 FL
3	1		*FRONT LH H/LAMP (CONSISTENT)	Cracked	685.00 F	*685.00 FL
4	1		*LH SIDE RETAINER (CONSISTENT)	Distorted	35.00 F	*35.00 FL
5	1		*GRILLE (CONSISTENT)	Serviceable	365.00 F	*- FL
					Sub Total (\$\$)	2,103.00 1,738.00
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 434.50
					Total Parts (\$\$)	2,103.00 1,303.50

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPAIR FRONTAL DAMAGE & REPLACE NEW PARTS	New	650.00	400.00
2	SPRAY PAINTING	New	650.00	400.00
Gross Labour Cost (\$\$)			1,300.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >